



## ***ECO Triplet-w***

10/2014, Edition 4

User manual





<b>Section 1 Specifications</b> .....	3
1.1 Mechanical.....	3
1.1.1 6-contact connector.....	3
1.1.2 3-contact connector.....	3
1.2 Electrical.....	3
1.3 Communications.....	4
1.4 Three-parameter fluorometer and scattering.....	4
<b>Section 2 Operation and maintenance</b> .....	5
2.1 Verify sensor operation.....	5
2.2 Set up sensor for deployment.....	6
2.3 Monitor data.....	6
2.3.1 Monitor data collected in engineering units.....	7
2.4 Save data.....	7
2.4.1 Save data to sensor.....	7
2.4.2 Save data to host PC.....	7
2.5 Get data from sensor.....	8
2.6 Additional operations.....	9
2.6.1 Set date and time.....	9
2.6.2 Adjust options for data collection.....	9
2.6.3 Adjust views in plot data tab.....	10
2.7 Sensor maintenance.....	11
2.7.1 Clean and lubricate bulkhead connector.....	11
2.7.2 Wiper replacement.....	11
2.7.3 Wiper motor replacement.....	12
<b>Section 3 Reference topics</b> .....	15
3.1 Delivered items.....	15
3.2 Calibration.....	15
3.3 Characterization.....	15
3.3.1 Field characterization.....	15
3.3.2 Store field characterization values in sensor.....	15
3.4 Device files.....	16
3.5 Terminal program operation.....	17
3.5.1 Common terminal program operations.....	17
3.5.2 Terminal program operation for sensors with internal memory.....	17
3.5.3 ECOView and terminal program differences.....	18
<b>Section 4 Optional equipment</b> .....	19
4.1 Test cable.....	19
4.2 Internal batteries.....	19
4.2.1 Remove batteries.....	20
4.2.2 Replace batteries.....	21
4.3 External thermistor.....	22
4.4 Pressure sensor.....	22
4.4.1 Maintain pressure sensor.....	23
<b>Section 5 General information</b> .....	25
5.1 Warranty.....	25
5.2 Service and Support.....	25
5.3 Waste electrical and electronic equipment.....	25



# Section 1 Specifications


ECO sensors measure different parameters of the Earth's natural waters. The sensors are available in several models and with a variety of optional features.

Standard (Std)	Output is digital. Optical face has wiper. Has low power mode. Stores data.
Battery (B)	Standard, and with internal batteries for autonomous operation.

## 1.1 Mechanical


	Std	B
Diameter	8.08 cm	
Length	22.1 cm	36.0 cm
Depth rating	600 m	
Temperature range	0–30 °C	
Weight in air, water	1.28 kg, 0.29 kg	2.1 kg, 0.43 kg

### 1.1.1 6-contact connector

Contact	Function	MCBH-6-MP
1	Ground	
2	RX	
3	Reserved	
4	Voltage in	
5	TX	
6	Reserved	

**Note:** Contact 3 on two-parameter sensors is a second analog output.

### 1.1.2 3-contact connector

Additional bulkhead connector on sensors with internal batteries. Use the three-contact blue-tipped power connector that is supplied with the sensor to supply power to the sensor.		
Contact	Function	MCBH-3-FS
1	Voltage in	
2	No connect	
3	Battery out	

## 1.2 Electrical

Input	7–15 VDC
Current draw, typical	60 mA
Current draw, standby	140 µA

## Specifications

Current draw, active wiper	200 mA
Linearity	99%

### 1.3 Communications

Sample rate	to 4 Hz
Data storage	67,000 samples
RS232 output rate	19200 baud
Output resolution	12 bit
Digital output maximum	4130 ±30 counts

### 1.4 Three-parameter fluorometer and scattering

Parameter	Wavelength EX/EM	Range, Sensitivity
Chlorophyll (Chl)	470/695 nm	0–30, 0.015 µg/L
		0–50, 0.025 µg/L
Colored Dissolved Organic Matter (CDOM)	370/460 nm	0–375, 0.184 ppb
Uranine (UR)	470/530 nm	0–300, 0.073 ppb
Phycocyanin (PC)	630/680 nm	0–175, 0.086 ppb
Phycoerythrin (PE)	540/570 nm	0–175, 0.086 ppb

Parameter	Wavelength	Range, Sensitivity
Scattering	412 nm, 470 nm, 532 nm, 650 nm, 880 nm	0–5, 0.003 m <sup>-1</sup>
		0–3, 0.002 m <sup>-1</sup>
	700 nm	0–5, 0.003 m <sup>-1</sup>

## Section 2 Operation and maintenance

### 2.1 Verify sensor operation

#### ⚠ WARNING


CDOM sensors use an ultraviolet LED light. Do not look directly at a UV LED when it is on. It can damage the eyes. Keep products that have UV LEDs away from children, pets, and other living organisms. Wear polycarbonate UV-resistant safety glasses to protect the eyes when a UV LED is on.

#### ⚠ CAUTION

Do not supply more than 15 VDC to the sensor. More than 15 VDC will damage the sensor.

Make sure that the sensor operates before further setup and deployment.

1. Connect the 6-contact connector on the optional test cable (refer to the section on the [Test cable](#) on page 19 for details) to the sensor.
2. Remove the cap that protects the optical face of the sensor.
3. Connect a serial-to-USB adapter to the test cable to connect the test cable to the host PC.
4. Connect the sensor to a power supply.
  - a. Connect sensors with internal batteries to the manufacturer-supplied, three-contact, blue-tipped power connector.  
The sensor comes on.
  - b. Connect sensors without internal batteries to the optional test cable and a regulated power supply set at 12 VDC.
5. Start the host software from the manufacturer-supplied CD.
  - a. Select the COM port on the host PC.
  - b. Select the device file for the sensor from the CD.
  - c. Select the baud rate if necessary. The default is 19200.



6. Turn on the power supply.  
The sensor comes on.
7. Push **Start Data** on the host software.
8. Go to the *Raw Data* tab of the host software.  
The data collected by the sensor shows in the "Signal" column.

Figure 1 Format of data collected by most ECO sensors

Meter Setup	Raw Data	Plot Data	Transfer Data					
06/14/12 06:06:05	532	267	660	3070	695	78	535	
06/14/12 06:06:06	532	315	660	3406	695	89	535	
06/14/12 06:06:07	532	437	660	3861	695	127	535	
06/14/12 06:06:08	532	509	660	4122	695	175	535	
06/14/12 06:06:09	532	2577	660	4122	695	629	535	
06/14/12 06:06:10	532	4122	660	4122	695	957	535	
06/14/12 06:06:11	532	4122	660	4122	695	970	535	
06/14/12 06:06:12	532	4122	660	4122	695	868	535	
06/14/12 06:06:14	532	4122	660	4122	695	946	535	
Date	Time	Wave-length	Signal	Wave-length	Signal	Wave-length	Signal	Thermistor

Note that RT and puck sensors show 9's instead of the Date and the Time.

- Look at the maximum data value for the sensor. Hold a finger, the protective cap, or fluorescent stick if the sensor is a fluorometer, 1–4 cm away from the optical face of the sensor.

The data value in the "Signal" column in the *Raw Data* tab will increase toward the maximum data value specified for the sensor.

- Scattering and turbidity sensors: use a finger or the protective cap.
- CDOM sensors: use the blue fluorescent stick.
- Chlorophyll or phycoerythrin sensors: use the orange fluorescent stick.
- Uranine or phycocyanin sensors: use the yellow fluorescent stick.
- PAR sensors: point the sensor into the light.

- Push **Stop Data**.

The Bio-wiper closes on sensors so-equipped. If the power is turned off in mid-cycle, the Bio-wiper starts at the beginning of the cycle when power is supplied again.

## 2.2 Set up sensor for deployment

- Refer to the previous section to make sure that the sensor operates correctly.
- Replace the test cable with a sea cable for deployment.
- Remove the protective cap from the sensor if necessary.
- Use either the blue-tipped power connector (sensors with internal batteries only) or an external power supply to supply power to the sensor for deployment. If the power connector and a cable are both attached, the power is supplied by the equipment that supplies the highest voltage.
  - Attach the blue-tipped power connector to the three-contact connector. The sensor will begin operation as set up by the user. The manufacturer recommends this mode for moored applications.
  - Attach a sea cable to the six-contact connector and turn on the power supply (sensors without internal batteries).
- Refer to the section on [Additional operations](#) on page 9 for details on how to set up the sensor for a specific application.

## 2.3 Monitor data

Monitor the data from the sensor in counts. The number of "Signal" columns will vary depending on whether the user has a one-, two-, or three-parameter sensor.

- Make sure the sensor has power supplied and is on.
- Push **Start Data**.
- Go to the *Raw Data* tab.




Refer to the [Verify sensor operation](#) on page 5 illustration to see the format of the collected data.


**Note:** RT and puck sensors usually show 9's as placeholders in the date and time columns.

### 2.3.1 Monitor data collected in engineering units

1. Go to the *Plot Data* tab.
2. Select "Engr Units" from the drop-down menu near the top of the tab.



3. Select the type of units to see.



The host software calculates the engineering units for the *Plot Data* tab.

**Note:** Data is saved in counts, not engineering units.

## 2.4 Save data

Save the data collected by the sensor in the sensor's memory (if so equipped), on the host PC, or both.

**Note:** RT and puck sensors do not store data. Save the data from these sensors in real-time to the host PC or to a data logger.

### 2.4.1 Save data to sensor

1. Stop the sensor if it is on.  
This puts the sensor in standby mode.
2. Push **Turn Logging ON/OFF**.




This turns on the logging, or data storage, in the sensor.


3. Push **Store to Flash**.  
The yellow **Setup not Stored** warning will no longer show. The sensor will save data internally the next time the user turns it on.

### 2.4.2 Save data to host PC

To save data to the host PC in counts, push **Record Raw**. To save data in engineering units, push **Record Engr**. Data collected by the sensor is saved in real-time to the host PC.



1. Push **Record Raw**.  
The *Record Raw Data* window shows in the host software.
2. Select a location on the host PC to store the data.
3. Type a file name.
4. Push **Save**.
5. Push **Record Engr**.  
The *Record Engineering Data* window shows in the host software.
6. Select a location on the host PC to store the data.
7. Type a file name.
8. Push **Save**.
9. Make sure the PC is configured to save data.
  - The file names from step 3 and step 7 will show in the host software.



10. Push **Start Data**.  
The host software will show the host PC file sizes.


## 2.5 Get data from sensor

### ⚠ CAUTION


Do data transfers away from harsh environments such as strong electric fields or electrostatic discharge sources. Electrostatic Discharge (ESD) sources may temporarily disrupt data transfer. If this occurs, move the sensor away from the ESD source. Turn the power off and then on and continue operation.

Get the data from the sensor and save it to the host PC.

1. Make sure that the sensor is not on but has power supplied to it.
2. Select the *Transfer Data* tab in the host software.
3. Push **Receive Data**.



4. Select a location on the host PC to store the data.
5. Type a file name in the *Retrieve Meter's Internal Data* window.
6. Push **Save**.  
The host software saves the sensor's internal data to the host PC.
7. Make sure that the data move is complete.



8. Open the data file to make sure that the data is on the host PC. Contact the manufacturer to get a spreadsheet template for an *ECO* sensor.
9. To erase the data from the sensor's memory, Push **Erase Memory**.

## 2.6 Additional operations


### 2.6.1 Set date and time

Make sure that the sensor is connected to a power supply that is turned on. Make sure that the host software program is open.

1. If the sensor is in operation, push **Stop Data** to stop the sensor.
2. Push **Set Date and Time** in the host software. The host software adjusts the sensor's time to agree with the host PC.



3. Push **Get Date/Time/Setup** to make sure that the sensor and the host PC show the same current time.



### 2.6.2 Adjust options for data collection

The manufacturer sets *ECO* sensors to operate at approximately 1 Hz, with the optional internal data storage turned on.

**Table 1 Options to collect data**

ECOView option	How it works
Set Avg/Data Rate	Adjust from 1 to 65535. Examples:
	1-parameter sensors—approximately 1 Hz = 65; approximately 2 Hz = 30
	2-parameter sensors—approximately 1 Hz = 30; approximately 2 Hz = 15
	3-parameter sensors—approximately 1 Hz = 18; approximately 2 Hz = 6
	PAR sensors—approximately 1 Hz = 310; approximately 2 Hz = 170
Set Number of Samples	Adjust from 0 to 65535. Use 0 to operate continuously.
<b>The three options below apply only to sensors equipped with internal memory</b>	
Set Number of Cycles	Adjust from 0 to 65535. Select the number of sample groups that the sensor will collect between low-power states.
Set Cycle Interval	Adjust the time interval between sample cycles. Do not type the colons. The minimum is 5 seconds.
Turn Logging ON	Push to turn data storage off or on (sensors with internal data storage only).

Adjust any of the options to collect data in the *Meter Setup* tab.

<p><b>1</b> Enter the new value into the variable box.</p>	<p><b>2</b> Push the related button that is to the left of the variable box.</p>	<p><b>3</b> Push <b>Store to Flash</b>. The new value shows in the column <u>Current Ram Settings</u>.</p>
--	--	--

In the example above, the 3-parameter sensor will operate at an "Average" of 18 and a "Data Rate" of 1.12 Hz. The sensor will collect data 10 rows of data for 3 cycles, with a low-power interval of 15 seconds after each cycle. The sensor stops after the 10th row of the third cycle of data is collected.

**Table 2 Data collection examples**

<p><b>Collect moored data</b>  Set Avg/Data Rate = <math>\pm 1</math> Hz  Set Number of Samples = 50  Set Number of Cycles = 24  Set Cycle Interval = 006000  Turn Logging ON/OFF = ON  The sensor will collect data once per second, 50 times every 60 minutes for 24 hours, and store the collected data.</p>	<p><b>Collect profiling data</b>  Set Avg/Data Rate = <math>\pm 1</math> Hz  Set Number of Samples = 0  Set Number of Cycles = N/A  Set Cycle Interval = N/A  Turn Logging ON/OFF = ON  The sensor will collect data once per second and store collected data until the power is turned off.</p>
---	--

If the sensor is set up to collect data intermittently, as for a moored deployment, it may be in a low-power condition. It is not possible to communicate with the sensor in this condition.

1. To start communication again, disconnect the sensor's power supply for one minute.
2. Connect the power again and push **Stop Data** several times.
3. Select the *Meter Setup* tab. Refer to [Adjust options for data collection](#) on page 9.
4. Type **0** into the **Number of Samples** variable box.
5. Push **Set Number of Samples**.
6. Push **Store to Flash**.  
The sensor operates continuously.

Make sure that the sensor operates continuously.

1. Select the *Raw Data* tab.
2. Push **Start Data**.
3. Let the sensor operate for 10 samples or more.
4. Push **Stop Data**.

### 2.6.3 Adjust views in plot data tab

The *Plot Data* tab in the host software lets the user see the data that the sensor has collected.



Button	Function	Description
1	Resume	Push to start or stop the data that shows.
2	Pause	The x-axis will stop.
3	Axes scroll	Move either axis up or down, or right or left.
4	Axes zoom	Move either axis up or down, or right or left.
5	Zoom out	Decrease the detail by 2x.
6	Zoom in	Increase the detail by 2x.
7	Zoom box	Draw a box around the data area to zoom all axes.
8	Cursor	Move the cursor bar to a certain data point.
9	Copy	Copy the current data plot to the host PC clipboard.
10	Save	Save an image of the current data plot to the host PC.
11	Print	Send a snapshot of the current data plot to a printer.

Enter the type of data to view from the drop-down menu above the black view area ( $\mu\text{g/L}$ , ppb, scattering, etc.)

## 2.7 Sensor maintenance

### ⚠ CAUTION

Do not use acetone or other solvents to clean any part of the sensor.

1. After each cast or exposure to natural water, flush the sensor with clean fresh water.
2. Use soapy water to clean any grease or oil on the optical face of the sensor. It is made of ABS plastic and optical epoxy and can be damaged if an abrasive cleaner is used.
3. Dry the sensor with a clean soft cloth.

### 2.7.1 Clean and lubricate bulkhead connector

Lubricate the contacts of bulkhead connectors at regular intervals with pure silicone spray only. Allow the contacts to dry before they are connected.

Make sure that the pins have no corrosion, which looks green and dull. Make sure that the rubber seals on the pins are not delaminated. Connectors should connect smoothly and not feel "gritty" or too resistant.

The manufacturer recommends 3M™ Silicone Lubricant spray (UPC 021200-85822). Other silicone sprays may contain hydrocarbon solvents that damage rubber.

**DO NOT** use silicone grease. **DO NOT** use WD-40®. The wrong lubricant will cause failure of the bulkhead connector and the sensor.

### 2.7.2 Wiper replacement

Replace the sensor's wiper with a new one from the wiper replacement kit (sold separately).

1. Use a 1/16" hex wrench to loosen the wiper's set screw.

**Figure 2 Wiper set screw loosened**



2. Lift the wiper off of the wiper motor shaft.
3. Put the new wiper on the motor shaft.
4. Put the wiper height gauge on the faceplate under the wiper and around the motor shaft.

**Figure 3 Wiper height gauge inserted**



5. Turn the wiper so that the set screw faces the flat on the motor shaft.
6. Push down on the wiper to pinch the wiper height gauge between the wiper and the faceplate and tighten the wiper set screw.

**Figure 4 Wiper attached with set screw**



7. Remove the wiper height gauge.

### 2.7.3 Wiper motor replacement

Replace the wiper motor with a new one from the motor replacement kit (sold separately).

1. Remove the wiper from the sensor.
2. Use a #2 Phillips screwdriver to remove the three faceplate screws. Keep these screws to use again.
3. Lift the copper faceplate off the sensor.
4. Hold the motor shaft and pull straight up. It may be necessary to use pliers to carefully hold the shaft.

**Figure 5 Wiper motor pulled from the sensor**



5. Flush the wiper motor cartridge bore with fresh water two or three times.
6. Dry the wiper motor cartridge bore with canned compressed gas.
7. Flush the wiper motor cartridge bore with isopropyl alcohol to remove any remaining water.
8. Dry the wiper motor cartridge bore with canned compressed gas again.
9. Put the new wiper motor cartridge into the bore until it is flush with the optics face. Note that the wiper motor cartridge may not stay flush until the copper faceplate is attached again.
10. Align the dowel holes on the wiper motor cartridge and bore, and insert the plastic alignment dowel again.
11. Attach the faceplate to the optical face again with the faceplate screws.
12. Put the wiper on the motor shaft. Refer to [Wiper replacement](#) on page 11.

---

**Figure 6 Copper faceplate attached to optical face**



The faceplate fits on the optical face only one way.





### 3.1 Delivered items

- the *ECO* sensor
- a dummy connector and lock collar
- blue-tipped power connector and lock collar for sensors with internal batteries
- a plastic protective cover for the optical face
- a model-specific spare parts kit
- **On the CD:**
- this user manual
- the ECOView host software
- the device file or files for the sensor
- the characterization or calibration page for the sensor.

### 3.2 Calibration

The manufacturer calibrates all scattering sensors to make sure that the data that is collected meets the sensor's specifications. This information is on the sensor-specific calibration page that comes with the sensor.

### 3.3 Characterization

The manufacturer uses a fluorescent material to characterize all fluorescence sensors to make sure that the data that is collected meets the sensor's specifications. This information is on the sensor-specific characterization page that comes with the sensor.

#### 3.3.1 Field characterization

The manufacturer recommends that the user perform a field characterization on fluorimeters to make sure that the data is as accurate as possible for the user's application. The scale factor and the dark counts values can vary depending on the natural water, temperature, length of the cable, the power supply, and other factors.

Do the steps below to field-characterize the sensor.

- **x** = a solution of a known concentration in volts or counts.
  - **output** = the measured sample of interest in volts or counts.
  - **dark counts** = the measured signal output in volts or counts of the sensor in clean water with black tape over the detector.
  - **scale factor** = the multiplier in  $\mu\text{g/L/volt}$ ,  $\text{ppb/L/volt}$ , OR  $\mu\text{g/L/count}$ ,  $\text{ppb/L/count}$ .
1. Get a solution of a known concentration, **x**.
  2. Measure and record this solution using the sensor.  
This value is the **output** in volts or in counts.
  3. Measure and record the sensor's **dark counts**.
  4. Use this equation to determine the sensor's **scale factor**:  
$$\text{Scale factor} = x \div (\text{output} - \text{dark counts}).$$
  5. Use the scale factor to determine the concentration of the sample of interest:  
$$(\text{output counts} - \text{dark counts}) \times \text{scale factor} = \text{concentration of solution}.$$
  6. Store the scale factor and dark counts (offset) in the device file for the sensor, the internal memory of the sensor, or both.

#### 3.3.2 Store field characterization values in sensor

The host software uses a device file to process data. An example is shown below.

```

PCO BBFL2W-933
Created on: 01/22/12

Columns=9
N/U=1
N/U=2
N/U=3
Lambda=4    3.274e-06    50    700    700
N/U=5
ch1=6       0.0121    51
N/U=7
cdom=8      0.091     49
N/U=9
    
```

1. Edit columns 6 and 8 of this device file to include the field characterization values.
2. Save this device file with a new name.
3. Open this device file in the host software under the *File* menu.

### 3.4 Device files

The host software uses a sensor-specific device file to show the data in the *Plot Data* tab and to calculate the data output in engineering units. Each device file has three necessary elements. The device file is not necessary to use the host software to set up and move data from a sensor.

1. The heading for the *Plot Data* tab.
2. The number of columns in the device file.
3. A description of the contents in each column.

#### **Plot Data tab heading**

The first line of the device file shows the model number and the serial number of the sensor. This information appears on the top of the *Plot Data* tab in the host software.

#### **Number of columns**

The column count shows how many columns of data the host software will process. The format is COLUMNS=x.

#### **Description of columns**

Each column of the sensor's data output comes from a description in the device file.

Number of columns=x

Date=x MM/DD/YY

Time=x HH:MM:SS

N/U=x not used

sc=scale factor

off=offset

IENGR=x

mw=measurement wavelength of the sensor

dw=display wavelength of the sensor

#### **Example of a three-parameter device file**

lambda (scattering wavelength) = x sc off mw dw

**Column 4** = scale factor (sc), offset (off), measurement wavelength (mw),

display wavelength (dw).

**Column 6** = scale factor (sc) offset (off).

**Column 8** = scale factor (sc) offset (off).

```

PCO BBFL2W-933
Created on: 01/22/12

Columns=9
N/U=1
N/U=2
N/U=3
Lambda=4    3.274e-06    50    700    700
N/U=5
ch1=6       0.0121    51
N/U=7
cdom=8      0.091     49
N/U=9
    
```

## 3.5 Terminal program operation

Use Windows HyperTerminal® or other terminal program to operate sensors as an alternative to the host software.

Interface settings				
baud rate: 19200	stop bits: 1	data bits: 8	flow control: none	parity: none

### 3.5.1 Common terminal program operations

Command	Parameters	Description
!!!!	none	Stops data collected by the sensor. Lets the user to enter setup values. If the sensor is in a low-power mode, turn the power supply off for one minute, then turn the power on and push the "!" key 5 or more times.
\$save	1–65535	The number of measurements that make up each row of collected data.
\$mnu	—	Prints the menu of setup values to the host PC screen.
\$pkt	0–65535	Sets the number of rows of data that are collected between the specified time intervals.
\$run	—	Uses the current setup values to operate.
\$sto	—	Saves the desired setup values to the sensor's flash memory.

### 3.5.2 Terminal program operation for sensors with internal memory

Command	Parameters	Description
\$clk	24-hour time	Sets the time in the internal memory in the format hhmmss.
\$date	date	Sets the date in the internal memory in the format mmddyy.
\$emc	—	Clears the internal memory.
\$get	—	Reads data from the internal memory. Prints <b>etx</b> when it is complete.
\$int	24-hour time	Sets the time interval between sets of measurements the format hhmmss.
\$mvs	1 = ON; 0 = OFF	1 = the Bio-wiper is open. 0 = the Bio-wiper is closed.
\$rec	1 = ON 0 = OFF	1 = Turns on the sensor's internal memory. 0 = Turns off the sensor's internal memory.
\$rls	—	Loads the settings from the flash memory.
\$set	0–65535	Sets the number of rows of data that are output between low-power states.


\$m1d	0 to 65535	Parameter 1, dark count value to calculate the data collected in engineering units.
\$m1s	float	Parameter 1, slope value to calculate the data collected in engineering units.
\$m2d	0 to 65535	Parameter 2, dark count value to calculate the data collected in engineering units.
\$m2s	float	Parameter 2, slope value to calculate the data collected in engineering units.
\$m3d	0 to 65535	Parameter 3, dark count value to calculate the data collected in engineering units.
\$m3s	float	Parameter 3, slope value to calculate the data collected in engineering units.
\$man	1 = enable 0 = disable	Enables or disables manual start time. The sensor starts at a programmed wake time when enabled. This is automatically enabled if the user enters a manual start time.
\$mst	24-hour time	If enabled, the sensor will start at a pre-programmed time. This allows all sensors on a system to be synchronized to collect data.
\$met	—	Prints metadata that describes the data that is collected. Field 1 is the data. Field 2 is the field tag. Field 3 is the field name. Field 4 is used for units where appropriate.

## Reference topics

\$rat	2400 to 230400	Baud rate for communication. An invalid baud rate will default to 19200. It will show as 19201 so the user knows the software defaulted to this value.
\$rfd	—	Loads the original manufacturer's setup.
\$seq	0 to 3	Selects one of the pre-defined sequences to use to collect data.

### 3.5.3 ECOView and terminal program differences

ECOView uses different but equivalent words for data collection options.




## Section 4 Optional equipment

### 4.1 Test cable

Use a test cable to set up and test the sensor before deployment.



One analog output connector



Two analog output connectors



No analog output

1 six-contact connector	3 db-9 serial port connector
2 9-volt battery connector	4 RCA connector(s)

1. Connect the six-contact connector to the sensor.
2. Connect the 9-volt connector to a 9-volt battery. As an alternative, it can be connected to a regulated power supply.
3. Connect the db-9 connector to the host PC. Use a USB-to-RS232 adapter cable if necessary.
4. Use a digital multimeter (DMM) to see analog output (if applicable) from the sensor. The inside of the RCA is signal (red DMM probe) and the outside is ground (black DMM probe).

### 4.2 Internal batteries

#### ⚠ WARNING

The pressure housing of the *ECO* sensor must be opened to replace the batteries. If done improperly, it could result in personal injury or death due to abnormal internal pressure as a result of flooding. It may not be possible to repair flooded sensors.

The manufacturer disclaims all product liability from the use or service of these sensors. The manufacturer cannot control the use of these sensors or choose qualified personnel to operate them, and therefore cannot take steps to comply with laws pertaining to product liability, including laws that impose a duty to warn the user of any dangers involved with the operation and maintenance of the sensors. Acceptance of these sensors by the customer shall be conclusively deemed to include a covenant by the customer to defend and hold the manufacturer harmless from all product liability claims arising from the use and servicing of these sensors. Flooded sensors are serviced at the discretion of the manufacturer.

#### ⚠ WARNING

The sensor may be under pressure. Do not point it toward any part of the body to remove the vent plug or end flange.

#### ⚠ WARNING

Replace the batteries in a clean and dry environment. Gases in the sensor can expand and push the pressure relief plug open. This will flood the sensor. Do not replace batteries in a cold environment and then deploy the sensor in a hot environment.

Flooded sensors are usually not serviceable. There is a small chance that the manufacturer can get the data that is stored in the sensor. Contact [service@wetlabs.com](mailto:service@wetlabs.com) for more information about flooded sensors.

## Optional equipment

---

Six 9-volt lithium batteries supply power to sensors that have batteries. The sensors can also use alkaline or lithium manganese dioxide (LiMnO<sub>2</sub>) batteries. Alkaline batteries supply about 1000 mA-hours of power. LiMnO<sub>2</sub> batteries supply more than 2000 mA-hours of power.

**Note:** *The nominal water temperature, sequence timing, sample periods, and other variables will change the use time of the sensor's internal batteries.*

### 4.2.1 Remove batteries

1. Clean any debris from the end flange.
2. Dry the sensor thoroughly.
3. Remove the dummy plugs if necessary.
4. Point the connector end flange down, away from the face.
  - a. Pull the vent plug loose.
  - b. If the sensor has an external thermistor, pull it loose.
5. Dry the vent plug (and the thermistor, if applicable).
6. Use needle-nose pliers to remove the monofilament from the end flange.

**Figure 7 Pull monofilament from end flange**



7. Remove the end flange from the pressure housing.  
The jacking screws supplied as spare parts can be used to push the end flange off of the pressure housing, and then be removed.
8. Carefully disconnect each Molex<sup>®</sup> connector.
9. Remove the screw that holds the vent plug in the end flange.
10. Dry the end flange and the pressure housing seal areas.
11. Examine the O-rings on the vent plug and thermistor (if applicable).  
Remove any O-ring that is damaged.
12. Apply a light coat of vacuum grease on a new O10 O-ring and put it on the vent plug or thermistor.
13. Put the vent plug into the top of the end flange.
14. If applicable, insert the thermistor into the end flange again.
15. Put the screw for the vent plug in the inside of the end flange.  
The screw holds the vent plug in the end flange.
16. Carefully pull the white plastic loop to remove the battery pack from the pressure housing.
17. Remove the black plastic protectors from the ends of the long screws that secure the batteries.
18. Loosen, but do **not** remove, the retaining screws using a 1/4" slotted driver.  
Do not remove both screws. If both of the retaining screws are removed, the result will be a pile of parts and the replacement process will not be easy.

Figure 8 Both retaining screws removed




19. Disconnect each of the six batteries.

#### 4.2.2 Replace batteries

Install new batteries in the sensor.


1. Tilt the battery board enough to connect the first battery in the contacts that are perpendicular to the other two.

Figure 9 Connect the first battery



2. Pivot the boards in the opposite direction to connect the other two batteries.
3. Connect the second set of the batteries.
4. Hold the assembly plates on top and bottom and tighten the screws.  
The bottoms of the batteries may splay out. Make sure that the batteries do not extend beyond the circuit boards. If they do, the battery pack will scratch the sealing surface when it is put into the pressure housing again.
5. Install the bottom neoprene pad and the black plastic protective covers on the ends of the screws.
6. Remove and examine the 224 O-ring on the pressure housing for damage.
7. Use a new O-ring if necessary.
8. Apply a light layer of grease such as Dow Corning® High Vacuum Grease on the O-ring.
9. Put the battery pack into the pressure housing.
10. Attach the Molex® connectors.  
Note that the dowel pin may be in the end flange or in the pressure housing.

Figure 10 Inside of end flange



1 dowel hole

2 through-holes for jacking screws


3 vent plug screw

11. Put the end flange onto the housing so that the wires are out of the way.
12. Align the dowel pin with the dowel hole in the end flange, not the jack screw holes, which go through the end flange.
13. Make sure that the wires are not pinched between the end flange and the pressure housing.
14. Make sure that the end flange is attached to the pressure housing.
15. Install the monofilament in the end flange.
- 16.
- 17.
- 18.
- 19.

### 4.3 External thermistor

The calibration coefficient value for the thermistor is on the sensor's characterization page that ships with the sensor. The thermistor gives temperature output in counts. Do one of the methods below to change counts to engineering units.

1. Use the drop-down menu in the host software to see the thermistor output in °C.




2. Use MATLAB, MS Excel or other software to solve for:  
Temperature, °C = (Output × Slope) + Intercept

### 4.4 Pressure sensor

The calibration coefficient value for the pressure sensor is on the calibration page that ships with the sensor. The pressure sensor gives pressure output in counts. Do one of the methods below to change counts to engineering units.

1. Use the drop-down menu in the host software to see the pressure sensor output in dbar.





2. Use MATLAB, MS Excel or other software to solve for:  
relative pressure, dbar = (output × slope) + intercept
3. Calculate the absolute pressure:  
absolute pressure, dbar = relative pressure, dbar - relative pressure at atmospheric-water interface, dbar


Pressure sensors need to be set at zero for each deployment. Do not deploy the pressure sensor deeper than the depth rating on the calibration page.

#### 4.4.1 Maintain pressure sensor

The plastic fitting filled with silicone oil is a buffer between the pressure transducer diaphragm and seawater. Add silicone oil to the reservoir on top of the transducer at regular intervals.

1. Make sure the top of the sensor is clean.
2. Use a 9/16" wrench to hold the white nylon Swagelok® fitting.
3. Use a 7/16" wrench to loosen the cap on top of the fitting.
4. Remove the cap.
5. Use a wire or toothpick to clean the hole in the cap.  
Do not blow compressed air into the fitting. It will make a mess.
6. Add Dow Corning® 200 Silicone Oil to the reservoir until the oil is visible.

**Figure 11 Pressure sensor cap**



7. Replace the cap. Make sure not to tighten the cap too much.
8. Clean any excess oil from the end flange of the sensor.



## Section 5 General information

---

Revised editions of this user manual are on the manufacturer's website.

### 5.1 Warranty

This sensor is warranted against defects in materials and workmanship for one year from the date of purchase. The warranty is void if the manufacturer finds the sensor was abused or neglected beyond the normal wear and tear of deployment.

### 5.2 Service and Support

The manufacturer recommends that sensors be sent back to the factory annually to be cleaned, calibrated, and for standard maintenance.

Refer to the website for FAQs and technical notes, or contact the manufacturer for support at:

support@sea-birdcoastal.com

Do the steps below to send a sensor back to the manufacturer.

1. Contact the manufacturer for a Return Merchandise Authorization (RMA).  
**Note:** *The manufacturer is not responsible for damage to the sensor during return shipment.*
2. Remove all anti-fouling treatment from the sensor before sending it back to the manufacturer.  
**Note:** *The manufacturer will not accept sensors that have been treated with anti-fouling compounds for service or repair. This includes tri-butyl tin, marine anti-fouling paint, ablative coatings, etc.*
3. Use the sensor's original ruggedized shipping case to send the sensor back to the manufacturer.
4. Write the RMA number on the outside of the shipping case and on the packing list.
5. Use 3rd-day air to ship the sensor back to the manufacturer. Do not use ground shipping.
6. The manufacturer will supply all replacement parts and labor and pay to send the sensor back to the user via 3rd-day air shipping.

### 5.3 Waste electrical and electronic equipment



Electrical equipment that is marked with this symbol may not be disposed of in European public disposal systems. In conformity with EU Directive 2002/96/EC, European electrical equipment users must return old or end-of-life equipment to the manufacturer for disposal at no charge to the user. To recycle, please contact the manufacturer for instructions on how to return end-of-life equipment, manufacturer-supplied electrical accessories, and auxiliary items for proper disposal.





**Sea-Bird Coastal**  
13431 NE 20th Street  
Bellevue WA 98005 U.S.A.  
sales (425) 401-7653  
support (425) 401-7654  
support@sea-birdcoastal.com  
www.sea-birdcoastal.com

