EUROPEAN SOUTHERN OBSERVATORY



Organisation Européenne pour des Recherches Astronomiques dans l'Hémisphère Austral Europäishe Organisation für astronomische Forshung in der südlichen Hemisphäre

LA SILLA OBSERVATORY



Г

Pointing Model for the NTT

NTT-MAN-ESO-90100-0002 Date: 2001-Oct-10

L

E.S.O. INTERNAL USE ONLY

Prepared: Reviewed: Approved:

Mónica Castillo Jorge Miranda **Olivier Hainaut**

2001 Oct 10 2002 Feb 14 2002 Feb 16

Release	Date	Changes
1.0	1997 Oct 05	Original Manual Doc.No. VLT-MAN-XXXX
2.0	2002 Feb 16	Complete Revision

Та	Table of Content		
1.	Introduction	3	
2.	Starting the Pointing Modeling Package (Operations).	3	
3.	Making a New Pointing Model.	3	
	3.1. Check rotator center in database and in the telescope.	3	
	3.2. Preparation on TCS.	4	
	3.3. Measure the pointing errors.	6	
	3.3.1. Automatic Procedure.	10	
	3.3.2. Manual Procedure.	10	
	3.4. Return TCS to Initial State.	10	
4.	Adjusting a Model to the Measured.	11	
5.	Installing the Model on the TCS Control System.	12	
6.	Fitting a Model to Outdated Pointing Data.	12	
7.	How to Test a Previous Model with Newly Taken Data	12	

Introduction

This manual provides a description and operation of the Pointing Model (POM) software for the NTT.

1.1. Relevant Document TPOINT user manual

Starting the Pointing Modeling Package (Operations)

At the moment there are two ways to make it: Automatic and Manual mode. Using automatic mode is preferable because it is more easy and fast. Basically automatic mode chooses stars from a chosen catalog and template file. Template file define regions of the sky where a measurement must be obtained. The template makes a preset, and then takes a short exposure, calculates the error vectors, moves the star to center of rotator by offsetting the telescope, store the errors and then move to next star.

Manual mode procedure is practically same than old pointing model.

Making a New Pointing Model

The making of a new pointing model requires several steps, which should be carefully hand led if a good preset accuracy is required.

- To make a pointing model the following steps are to be taken:
- 1.2. Check rotator center in database and in the telescope.
- 1.3. Preparation on TCS.
- 1.4. Measure the pointing errors 1.4.1. Automatic Procedure 1.4.2. Manual Procedure
- 1.5. Return TCS to Initial State

Rotator Center in Database and Telescope

First, focusing telescope and correct in the best way the mirror aberrations (image analysis, focus). Mark down on RTD the point was the telescope pointing is required. This must be the center of rotation of the rotator.

For checking the center of rotation of the rotator presetting to any star, not too bright and setting guide probe to center field.

Offset it from the center by 20 arcs, and rotate the rotator +/- 180 degrees to move the object around. Using the drawing tool of RTD to draw a circle following the rotating object makes this task easier.

Estimate the center of rotator and put down a good mark on it.

Write down x and y values from RTD. Make sure that the values of rotator center are the correct ones, for it, read the values in the database with the command dbRead in wt5tcs xterm (Figure 2.1).

If in A side type: dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNA,refX)" dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNA,refY)" If in B side type: dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNB,refX)" dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNB,refY)"

If values founded are different than the values to database change it by writing in wt5tcs xterm If in A side type:

dbWrite "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNA,refX)" <value> dbWrite "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNA,refY)" <value> If in B side type:

dbWrite "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNB,refX)" <value> dbWrite "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNB,refY)" <value>

```
      tcs@wt5tcs

      (c)Copyright 1989–1991 The University of Maryland

      (c)Copyright 1988 Carnegie Mellon University

      RESTRICTED RIGHTS LEGEND

      Use, duplication, or disclosure by the U.S. Government is subject to restrictions as set forth in sub-paragraph (c)(1)(ii) of the Rights in Technical Data and Computer Software clause in DFARS 252.227-7013.

      Hewlett-Packard Company 3000 Hanover Street Palo Alto, CA 94304 U.S.A.

      Rights for non-DOD U.S. Covernment Departments and Agencies are as set forth in FAR 52.227-19(c)(1,2).

      wt5tcs tcs:~ 384 > dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNA,refX)"

      DOUBLE value = 205.00000

      wt5tcs tcs:~ 386 > dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNA,refX)"

      DOUBLE value = 191.000000

      wt5tcs tcs:~ 386 > dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNB,refX)"

      DOUBLE value = 191.000000

      wt5tcs tcs:~ 387 > dbRead "@wt5tcs:Appl_data:TCS:msw:insData.data(tccdNB,refY)"

      DOUBLE value = 142.500000

      wt5tcs tcs:~ 388 >
```

Preparation on TCS

Before starting the POM measurement process you must do some preparation on TCS:

- 1. Send guide probe to the center field position. Use the corresponding button on TCS main panel.
- 2. Disable the autoguider in order to avoid guide probe movement. To do this, call ccseiMsg program, then select: (Figure 2.2):
 - Environment: wt5tcs Process: prsControl: Type: SETUP ,,TEL.AG.GUIDESTAR NONE To check it, make a preset, the guide probe mustn't move from center field.
- 3. Shutdown the active optics. The POM software will by default try to make a ONECAL for each preset. At the NTT, this will cause a warning Pop Up. To avoid this, [Shutdown] the Active Optics (Figure 2.3). See possible errors below (Apendix A).
- 4. Set the delta UT value for the day. In wt5tcs send the command SETDUT to program trkwsControl, using ccseiMsg.

The value of DUT can be checked by giving the command GETDUT to program xxxtrkControl on the corresponding tracking LCUs.

xxxtrkControl: alttrkControl for lt5alt aztrkControl for lt5az rottrkControl for lt5rb (or lt5ra)

The current value of DUT can be found at: http://hpiers.obspm.fr/iers/bul/bulb/bulletinb.dat





Measuring the Pointing Errors

The making of a pointing model is done using the facilities of the pointing model package POM. This package consists on three programs, which are interfaced through the use of a single GUI (Graphic User Interface).

Using program pomMeasure does the measuring the pointing errors. Basically the idea is to preset the telescope to a given object of well know coordinates, and measure the difference between the position were the object is expected to be and the position were the object actually is after the preset.

1. To start the programs, and the GUI (Figures 2.5 and 2.6), run on a TCS xterm on wt5tcs the script: pomguiStart (Figure 2.4).

This will start the three programs; pomMeasure, pomFits, pomInstall. The pom GUI will also be started, and pomFits program will be initialized.

- 2. Click [Load Catalog] and choose catalog from /vltdata/pointing (Figure 2.7). Select Hip-fk5.tcs.
- 3. Create the name of the file that will hold the error measurements. This is done by choose 'Auto Name' and then pressing button labeled [Create File] on the pom GUI. The name should follow the naming convention for error files (The file containing the pointing errors are created on the following directory: /vltdata/pointing).
- 4. In wt5tcs xterm write: tail -f /vltdata/pointing/<error_file>"
- to check points written to error file; a new line will after each measurement.
- 5. Click [Load...] is side of Template file (*.tpl) and choose template from /vlt/INTROOT/NTTTCS/config (Figure 2.8). For a full model, chose pom Template64.tpl. To check the system, use pom Template5.tpl. In case of emergency (if you have to do a POM measurement during observations), use pom Template24.tpl. (template name: TemplateN°.tpl, where N°=number of stars on template)
- 6. Check integration time and window size from [Manual Control] panel. To change integration time or box side for automatic procedure you have to open 'Manual Control' window (Figure 2.9). There you will have input boxes for window size and integration time. For NTT a good range of integration time is from 0.1 to 0.3 seconds. The other parameters don't need to be changed. Then in [file] menu select [quit], the time will be stored automatically

cs@wt5tcs (c)Copyright 1990 Motorola, Inc. (c)Copyright 1990, 1991, 1992 Cornell University (c)Copyright 1989-1991 The University of Maryland (c)Copyright 1988 Carnegie Mellon University	
RESTRICTED RIGHTS LEGEND Use, duplication, or disclosure by the U.S. Government is subject to restrictions as set forth in sub-paragraph (c)(1)(ii) of the Rights in Technical Data and Computer Software clause in DFARS 252.227-7013.	
Hewlett-Packard Company 3000 Hanover Street Palo Alto, CA 94304 U.S.A.	
Rights for non-DOD U.S. Government Departments and Agencies are as set forth in FAR 52.227-19(c)(1,2). wt5tcs tcs:~ 501 > pomguiStart Starting /vlt/introot/bin/pomFits Starting /vlt/introot/bin/pomMeasure Starting /vlt/introot/bin/pomMeasure Starting /vlt/introot/bin/pomAuto Starting /vlt/introot/bin/pomgui wt5tcs tcs:~ 502 >	
gure 2.4: POM Graphic User Interface.	

POM Graphic U	lser Interface – @wt5tcs				
ile Options	Help				
pomMeasure					
Found Objects (RA, DEC, Mag)	If in CASSEGRAIN PARK LADC!!				
	Observing Catalogue : Load Catalog				
	Err File :				
	Auto Name Create File				
	Template File				
	Load				
	Visited of targets				
	# Measures 0				
7	Start Stop Manual Control				
	Draw Points				
pom	Fits				
Use current error file	SAVEMOD				
	Data Filtering Sottings				
JSE Terms Set: <pre><pre></pre> <pre><pre>Set:</pre> <pre><pre></pre><pre></pre></pre></pre></pre>	Pinky Mode dX 1.0 1 Treshold 1.0 1 Set				
	Brain Mode dD 1.0 1				
	dS 1.0 1				
	Scores dZ 1.0 1				
CLIST FIT	Reset Filters dR 1.0 1				
BESIDIIAL EIX	Set Points				
	LOSE CALL				
MASK					
model to install :	II USEr Show Model				
19990818Amodel.dat					
SET DUT					
Update List 20000126Bmodel.dat					
Command Feedback Window Options					
00:21:59 TPTRUN > INVOKED					
00:22:00 TPTRUN > REPLY/ L OK					
4					

– POM Graphic User Interface – @wt5tcs: TPOINT Ou	tput 🔽 🗌
2001-08-11 00:21:58.906765 pomFits - Application started (proc name 2001-08-11 00:21:59.003504 Init 2001-08-11 00:21:59.004458 pomFITS_MAIN_TASK.C:FindIniFile 2001-08-11 00:21:59.004653 Looking up file tpoint.ini	e: pomFits, D 🔺
2001-08-11 00:21:59.006370 CWD: /vlt/MAR2001/CCS/etc/tpoint 2001-08-11 00:21:59.007196 Pointdir: /vltdata/pointing/	
+ +	
TPOINT Telescope Pointing Analysis System Version 7,6 * *	
Clear	Close

Figure 2.6: POM Graphic User Interface: Tpoint output windows

H File Browser			· 🗆 🗙	
Search Path	🔷 Module	INTROOT	♦ VLTROOT	
	💠 VLTDATA	♦ TCLTK_ROOT	💠 Other	
Root Directory :				
Sub Directory :				
Returned Path	🔶 Absolute 🐟 Relativ	/e		
Filter :				
*.tcs				
Din	rectories	F	ïles	
/VLTDATA/poin /VLTDATA/poin /VLTDATA/poin	ting/catalogs/ ting/ntt_autoPom/ ting/oldModels/	hip-fk5.tcs	V V	
Selection				
	Filter	Cancel	Help	
igure 2.7: Stars Catalog Selection.				

Search Path	🔷 Module	INTROOT	💠 VLTROOT
	💠 VLTDATA	♦ TCLTK_ROOT	💠 Other
Root Directory :			
Sub Directory :			
Returned Path	🕨 Absolute 🐟 Rela	tive	
Filter :			
*.tpl			
Dir	ectories	F	iles
VITAINIRUUI/N	NTTTCS/config/	pomTemplate1	.tpl 4.tpl
7 VIT/INIRUUI/A	ITTTCS/config/	<pre>pomTemplate1 pomTemplate2 pomTemplate4 pomTemplate4 pomTemplate5 pomTemplate5.</pre>	.tpl 4.tpl 0.tpl 4.tpl ig.tpl tpl
Selection	ITTCS/config/	pomTemplate1 pomTemplate2 pomTemplate2 pomTemplate8 pomTemplate8 pomTemplate8	.tpl 4.tpl 0.tpl 4.tpl ig.tpl tpl
Selection	ITTTCS/config/	A pomTemplate1 pomTemplate2 pomTemplate2 pomTemplate8 pomTemplate8 pomTeplate5.	.tpl 4.tpl 0.tpl 4.tpl ig.tpl tpl
Selection	ITTTCS/config/ TCS/config/pomTempl:	ate64.tpl	.tpl 4.tpl 0.tpl 4.tpl tpl tpl Help

→ -# POM Graphic User Interface - @wt5tcs <2>
File Std. Options Help
Quit Snail Controls
Found Objects (RA, DEC, Mag)
HA : 00000 DEC : -6000 Lookup Template File Next Visiting out of targets. Apply AO Center Object Store # Measures 0 Lookup Options Radius : 300 Set Window Size : 150 (plx) Int Time : 0.2 (sec)
Command Feedback Window Options
Figure 2.9: Manual Control Interface.

Automatic Procedure

After of the preparation on TCS and POM, we are ready to start the new measurement automatically.

- 1. Click [Start] on GUI panel.
- 2. Check the tail, if no data stored, it means system failure. Normally, data are stored, with name, coordinates, etc; means system work properly.
- 3. Don't worry about the error boxes which pop up (see below the description of possible errors in appendix A)
- 4. If everything goes O.K., make a coffee and relax, check telescope behavior and wait till template finished.

Manual Procedure

If automatic procedure failed, after of the preparation on TCS, we can start the new measurement manually.

- 1. In POM panel click 'Manual Control'; a panel will pop up
- 2. Click 'Lookup' and list of star will be shown in list
- 3. Click 'Preset' if you are happy for characteristic of first star, if not choose other one.
- 4. Center the star in autoguider RTD pressing 'Center Object' (normally the center of rotation of the rotator). If the object happens to be a double star, reject the object. Select a new, pressing 'Next'.
- 5. When the object is properly centered save the measurement using the button 'Store'. The values of the reference position of the object and the value of the actual corrected position of the object will be saved to the file that was create.
- 6. Check that the measurement in pom panel or manual control panel increase after each 'Store'.
- 7. Then press 'Next'
- Repeat steps 4 => 5 => 6 => 7 ... until the last star have been visited. For a good pointing model, the recommended number is 64 objects. Then close the manual control panel window.

Return TCS to Initial State

After having concluded the measuring of the pointing errors, you should return to the initial state of the TCS, with the following steps.

1. Enable guide probe using ccseiMsg (Figure 2.10), select: Environment: wt5tcs

Process: prsControl:

Type: SETUP,,TEL.AG.GUIDESTAR CATALOG

If you make a preset, the guide probe must be move from center field to the first guide star.

- 2. Start the active optics. Active Optics panel clicking:
 - 'Engineering Interface...' (Figure 2.3), and click INITAO in Active Optics Engineering panel.

Environment: wt5tcs +				. н
Parameter:	Process: prsControl	+	Command:	+
	p		,	
Simulation Mod	e: NORMAL Error C	heckina: CHECK	ALL Receive Tir	neout (ms): 0
CCS 1	Ingineering User	Interface		
The local environment is with lencel lence bence end/liAnager is apparent end/liAnager is apparent — and the line of the line — Translation of Sym — The Symonym-M — Error-Checking — The Timeout for See the short help below for th I wistes prsControl (Com)> — Replies: _ Display mul	the second	riter fact of the final in y it is a second	version 2.16 our network: Saga ItSagb ItSalt It er testServer1 testS Options' menul): nyms	5az USbu UShb USiaa . ierrer2 testSerrer3 te
ব				
Fror Stack :				
4				
	ds:			
ist of Pending Comman	mmands			
List of Pending Comman No pending replies on co				

ADJUSTING A MODEL TO THE MEASURED ERRORS

This task is handled by pomFits, which is an interface to TPOINT. Then following steps are necessary to execute:

- 1. Input the error file name in the corresponding field on POM GUI. Type in the complete data path: /vltdata/pointing/yy-mm-dd_UT5_NS.dat and then press the LOAD button on pom GUI. If you have just finished the measurements, you can press "Use current error file" then [Load]. (Check on the TPOINT output that the error file has been loaded. A list of the measurements will be displayed. If the file is not found a error will be displayed instead of the measurement list).
- 2. Select the terms used at NTT, fit the measurements and display the residuals. This is done if one click with the "PommeFrittes" button. This can be done manually using 2.a and 2.b.
 - a. Select the term to be used on the fitting, using the select buttons on the GUI. Presently at the NTT we use: IA IE CA AN AW NPAE TF TX. There are two ways of selecting the term:
 Select term set, or
 - -Select the term with [Use] on.
 - b. Press button FIT. This will actually perform the fitting, and will display the calculated values on the xterm. Check for a low Sky rms & population. They should be 3 arcs or less. Display the result of the fit. Press the button PLOT a9.
- 3. If rms is high (>1."), look for abnormal measurements. Check the residual values, pressing button RESIDUAL on pom GUI, and look the listing on the xterm. Look for object with very high residuals. This could be a star that had been wrongly identified. Then the idea is to mask this object out. Fill in the number of the object on the field, and press the MASK button. Then repeat the fitting like in point 2. NOTE: if more than one object needs to be masked out, do it one by one. If you enter more than one number on the entry field, you will mask out all measurements between first and second entry.
- 4. If sky rms and population is OK, save the model on a file. The file name should be like the following: yymm-dd_UT5_NSmodel.dat, similar to the input file, with "_model". Then press button SAVEMOD on the GUI.

INSTALLING THE MODEL ON THE TCS CONTROL SYSTEM.

The final step is to install the new calculated model on the telescope control system. This is done by program pomInstall.

- 1. Fill in entry field labeled Model to install the name of the file containing the model. This is the same name that was used in step 4 on the model fitting section. Be sure to include the .dat extension. Then press the button SHOW MODEL in the pom GUI. Please check that the values shown on the GUI are the same displayed in the xterm after the command FIT.
- 2. After 'Load Model' and make some presets to check if model is good. Load model will send new pointing model to LCUs.
- 3. Verify that the model was correctly propagated to tracking LCUs. To do use CCSEI, send command GETTERM to program xxxtrkServer on each of the tracking LCUs (xxx is alt, az, ra or rb). They should return the same values that are shown on pom GUI. Please note that all the terms will have their signs inverted with respect to what came out from the fitting. This is because TPOINT uses a different convention on the coordinates than our control system.
- 4. If the correct values are loaded, check the new model by presetting some bright objects.
- 5. If pointing is OK, then save the new model as the default model. Pressing [Install Model] on pom GUI does this. After this the model will be saved on special files on directory /vltdata/config. And they will be used to load the model when the LCUs are booted, or the side changed, etc.

FITTING A MODEL TO OUTDATED POINTINDG DATA

It is possible, if desired, to remake a model from previously measured pointing data. This maybe useful, if new terms are to be tried out, or just to recover the error curves for analysis.

All data measures is kept in directory /vltdata/pointing. From the name it should be easy to identify the date when the data was taken. This is the reason of enforcing the use of the naming convention previously mentioned. This is also the reason why users must be careful, not to overwrite old data, by using the same filenames again.

To remake a model proceed exactly as it is done for fitting a model to newly taken data, but use the name of the file containing the old data as input for the LOAD button.

HOW TO TEST A PREVIOUS MODEL WITH NEWLY TAKEN DATA

It is possible to check how good a previous model fits on newly taken pointing data. This might be useful in several situations, among them:

- 1. To check how stable the pointing models are
- 2. to see which if there are pointing terms which are changing in time
- 3. to be able to make trend analysis of different terms

The procedure to check an old model with new data is the following, using the pomFits part of pom GUI:

- 4. Input the file name holding the measured pointing data the press the LOAD button
- 5. Select the terms to fit with the select buttons. Usually: ie ia ca an aw tx tf npae or [pommesFrittes]
- 6. Press button FIT, until change is 0. Usually 3 times is enough.
- 7. Enter FIX in field next to EXEC button. Press EXEC button. This will execute the command FIX.
- 8. Press button CLIST to check that the select term are fixed.
- 9. Assign to each of the terms the value they had in the old model. For this enter in the field besides EXEC the name of the term with the corresponding value. Press the button EXE. For instance: IE 123.32 <press EXEC button>
- 10. Press button CLIST to check that all the terms are fixed and having the value that had been assigned.
- 11. Press button FIT until change is 0. The RMS 7 Sky Population numbers will reflect the quality of the fitting of the old model with the new data.
- 12. Press button PLOT a9. The error curves will reflect the residual errors.

If the effect of a single term is to be seen, the following steps can be done using the pom GUI:

- 13. Deselect the desired term with the corresponding select button.
- 14. Select the desired term to unfix it
- 15. Press CLIST to check that the term is not fixed
- 16. Press FIT. And check the new value for the single term that was unfixed and the new RMS.
- 17. Pressing the PLOT A9 button will display the error curves. The residuals can be check in the Tpoint output.

Term Name	Term description	Value Range
IE	Index error in elevation	100 - 140
IA	Index error in azimuth	280 - 310
CA	Left-Right collimation error	120 - 150
AN	Azimuth axis misaligment North South	-1013
AW	Azimuth axis misaligment East-West	20 - 25
NPAE	Az/El non-perpendicularity	-1620
TF	Tube Flexure (sine)	10 – 13
TX	Tube Flexure (tangent)	9 – 13

POINTING MODEL TERMS USED AT NTT

Apendix A

Possible errors which you can (and probably will), get are following.

"Image analysis command not permitted." Don't worry about this. You are just not using the active optics. Procedure will try to apply ONECOR every time for star where it is. Anyway the error vector measurement will be taken and telescope will continue to next star.

"Cannot start TCCDs." Don't worry. Procedure starts and stops TCCDs by itself. If it cannot take a exposure it will continue to next one. You don't even have to start camera for procedure. Of course camera status have to be ONLINE.

"Failed to execute POINOBJ" No worries again. The coordinates of entry are out of the limit and that entry will be skipped and next one is chosen.

NOTE1:Allways keep the tail open to see which points are really saved. Sometimes GUI gives wrong values to '#Measures' output window.

NOTE2: if you stop automatic procedure through 'Stop' button agwsControl can stay to state 'AG busy'. Just init the agws from TCS Status panel and everything will became normal.

NOTE3: if "SETUP,,TEL.AG.GUIDESTAR NONE(CATALOG)" doesn't work from ccseiMsg use the msgSend to send message. Syntax: msgSend wt5tcs prsControl SETUP ",,TEL.AG.GUIDESTAR NONE(CATALOG)"

Apendix B

NTT POINTING MODELS EVOLUTION

Figures a and b display the evolution of the models used at the NTT. No significant trend is observed.





000