

SERVICE MANUAL FM-00-01.3 (Replaces FM-00-01.2) July - 2007

## **RF-1 FLOWMETER**



## (76251-01)

IMPORTANT: Before using this equipment, carefully read SAFETY PRECAUTIONS, starting on page 1, and all instructions in this manual. Keep this Service Manual for future reference.

> Service Manual Price: €15.00 (Euro) \$20.00 (U.S.)



NOTE: This service manual has been superceded from service manual number **FM-00-01.2** to service manual number **FM-00-01.3**. Reasons for this change are noted under "Manual Change Summary" inside the back cover of this manual.

## CONTENTS

	PAGE
SAFETY:	1-6
SAFETY PRECAUTIONS HAZARDS / SAFEGUARDS	
INTRODUCTION:	7-8
DESCRIPTIONS FLOW RATE ACCURACY REVERSE FLOW DETECTION FLUID PASSAGES SPECIFICATIONS	7 7 7 7
INSTALLATION:	9-10
INSTALLATION	9
MAINTENANCE:	11-12
FLOWMETER SERVICING SERVICE CALIBRATION AUTOMATIC CLEANING OF THE FLOWMETER	11 12
PARTS IDENTIFICATION:	13-14
RF-1 FLOWMETER / PARTS LIST	13-14
WARRANTY POLICIES:	15
LIMITED WARRANTIES	15

## SAFETY

### SAFETY PRECAUTIONS

Before operating, maintaining or servicing any ITW Ransburg electrostatic coating system, read and understand all of the technical and safety literature for your ITW Ransburg products. This manual contains information that is important for you to know and understand. This information relates to USER SAFETY and PREVENTING EQUIPMENT PROBLEMS. To help you recognize this information, we use the following symbols. Please pay particular attention to these sections.

A WARNING! states information to alert you to a situation that might cause serious injury if instructions are not followed.

A CAUTION! states information that tells how to prevent damage to equipment or how to avoid a situation that might cause minor injury.

## A NOTE is information relevant to the procedure in progress.

While this manual lists standard specifications and service procedures, some minor deviations may be found between this literature and your equipment. Differences in local codes and plant requirements, material delivery requirements, etc., make such variations inevitable. Compare this manual with your system installation drawings and appropriate ITW Ransburg equipment manuals to reconcile such differences.

Careful study and continued use of this manual will provide a better understanding of the equipment and process, resulting in more efficient operation, longer trouble-free service and faster, easier troubleshooting. If you do not have the manuals and safety literature for your Ransburg system, contact your local ITW Ransburg representative or ITW Ransburg.

#### **WARNING**

► The user **MUST** read and be familiar with the Safety Section in this manual and the ITW Ransburg safety literature therein identified.

► This manual **MUST** be read and thoroughly understood by **ALL** personnel who operate, clean, or maintain this equipment! Special care should be taken to ensure the the **WARNINGS** and safety requirements for oprating and servicing the equipment are followed. The user should be aware of and adhere to ALL local building and fire codees and ordinances as well as **NFPA-33**, prior to installing, operating, and/or servicing this equipment.

#### WARNING

Ţ

► The hazards shown on the following page may occur during the normal use of this equipment. Please read the hazard chart beginning on page 2.

# *IT W* Ransburg

AREA	HAZARD	SAFEGUARDS
Tells where hazards may occur.	Tells what the hazard is.	Tells how to avoid the hazard.
	Tells what the hazard is. Fire Hazard Improper or inadequate operation and maintenance procedures will cause a fire hazard. Protection against inadvertent arcing that is capable of causing fire or explosion is lost if any safety interlocks are disabled during operation. Frequent power supply shutdown indicates a problem in the system requiring correction.	Fire extinguishing equipment must be present in the spray area and tested periodically. Spray areas must be kept clean to prevent the accumulation of combustible residues.
		<ul> <li>cleaning operations using flammable or combustible solvents.</li> <li>Electrostatic arcing must be prevented.</li> <li>Test only in areas free of combustible material.</li> <li>Testing may require high voltage to be on, but only as instructed.</li> <li>Non-factory replacement parts or unauthorized equipment modifications may cause fire or injury.</li> <li>If used, the key switch bypass is intended for use only during setup operations. Production should never be done with safety interlocks disabled.</li> <li>Never use equipment intended for use in waterborne installations to spray solvent based materials.</li> <li>Paint process and equipment should be set up and operated in accordance with NFPA-33, NEC, and OSHA requirements.</li> </ul>

# *IT W* Ransburg

AREA Tells where hazards may occur.	<b>HAZARD</b> Tells what the hazard is.	<b>SAFEGUARDS</b> Tells how to avoid the hazard.
General Use and Maintenance	Improper operation or maintenance may create a hazard.	Personnel must be given training in accordance with the requirements of NFPA-33.
	Personnel must be properly trained in the use of this equipment.	Instructions and safety precautions must be read and understood prior to using this equipment.
<u> </u>		Comply with appropriate local, state, and national codes governing ventilation, fire protection, operation maintenance, and housekeeping. Reference OSHA, NFPA-33, and your insurance company requirements.
Electrical Equipment	High voltage equipment is utilized. Arcing in areas of flammable or combustible materials may occur. Personnel are exposed to high voltage during operation and	The power supply, optional remote control cabinet, and all other electrical equipment must be located outside Class I or II, Division 1 and 2 hazardous areas (refer to NFPA-33).
14	voltage during operation and maintenance.	Turn the power supply OFF before working on the equipment.
	Protection against inadvertent arcing that may cause a fire or explosion is lost if safety circuits are disabled during operation.	Test only in areas free of flammable or combustible material.
	Frequent power supply shutdown indicates a problem in the system	Testing may require high voltage to be on, but only as instructed.
	which requires correction.	Production should never be done with the safety circuits disabled.
	materials and cause a fire or explosion.	Before turning the high voltage on, make sure no objects are within the sparking distance.
Explosion Hazard / Incompatible Materials	Halogenated hydrocarbon solvents for example: methylene chloride and 1,1,1,-Trichloro- ethane are not chemically compatible with the aluminum that might be used in many system components. The chemical reaction caused by these solvents reacting with aluminum can become violent and lead to an equipment explosion.	Aluminum is widely used in other spray application equipment - such as material pumps, regulators, triggering valves, etc. Halogenated hydrocarbon solvents must never be used with aluminum equipment during spraying, flushing, or cleaning. Read the label or data sheet for the material you intend to spray. If in doubt as to whether or not a coating or cleaning material is compatible, contact your material supplier. Any other type of solvent may be used with aluminum equipment.

# *"T*WRansburg

AREA Tells where hazards may occur.	<b>HAZARD</b> Tells what the hazard is.	<b>SAFEGUARDS</b> Tells how to avoid the hazard.
General Use and Maintenance	Use of hand tools may cause cumulative trauma disorders (CTD's). CTD's ormusculoskeletal disorders, involve damage to the hands, wrists, elbows, shoulders, neck and back. Carpal tunnel syndrome and tendinitis (such as tennis elbow or rotator cuff syndrome) are examples of CTD's. CTD's when using hand tools, tend to affect the upper extremities. Factors which may increase the risk of developing a CTD include: 1. High frequency of the activity. 2. Excessive force, such as gripping, pinching or pressing with the hands and fingers. 3. Extreme or awkward finger, wrist or arm positions. 4. Excessive duration of the activity. 5. Tool vibration. 6. Repeated pressure on a body part. 7. Working in cold temperatures.	Risk is reduced by avoiding or lessening the listed hazards. CTD's can also be caused by such activities as sewing, golf, tennis and bowling, to name a few. Pain, tingling, or numbness in the shoulder, forearm, wrists, hands, or fingers, especially during the night, may be early symptoms of a CTD. Do not ignore them. Should you experience any such symptoms, see a physician immediately. Other early symptoms may include vague discomfort in the hand, loss of manual dexterity, and nonspecific pain in the arm. Ignoring early symptoms and continued repetitive use of the arm, wrist and hand can lead to serious disability.
Toxic Substances	Certain material may be harmful if inhaled, or if there is contact with the skin.	Follow the requirements of the Material Safety Data Sheet supplied by coating material manufacturer. Adequate exhaust must be provided to keep the air free of accumulations of toxic materials. Use a mask or respirator whenever there is a chance of inhaling sprayed materials. The mask must be compatible with the material being sprayed and its concentration. Equipment must be as prescribed by an industrial hygienist or safety expert, and be NIOSH approved.

# *IT* WRansburg

AREA Tells where hazards may occur.	<b>HAZARD</b> Tells what the hazard is.	<b>SAFEGUARDS</b> Tells how to avoid the hazard.
Tells where hazards		



## INTRODUCTION

### DESCRIPTIONS

The *RF-1 Flowmeter* has been developed for precise metering and monitoring of fluid flows. The flowmeter in many cases, surpasses the performance of meters currently used.

### FLOW RATE ACCURACY

Flow rate accuracies of 0.5% are not uncommon with many fluids if the flowmeters are calibrated at or near the expected flow rates. Even with wide flow rate swings (such as when used with robots under analog control) accuracies of +/- 2% are achievable.

### REVERSE FLOW DETECTION

Sensors are of the quadrature type, which allows reverse flow detection, if necessary. Under conditions where reverse flow detection is not necessary, only one sensor output is used, leaving the second sensor output as a spare output that can be used if the first sensor should ever fail.

### FLUID PASSAGES

The RF-1 requires 3/8" AN male fittings. This style fitting eliminates flow "dead space" and also eliminates the need for specially designed fittings or Teflon inserts. By creating a streamline fluid passage, color change time of the meter is improved.

#### SPECIFICATIONS

#### Material Viscosity Range

Flow Rate:	.0150 GPM (.04-1.9 LPM)
Accuracy:	+/- 0.5% (system dependent)
Working Pressure:	500 psi (345 bar) MWP @ 100°F
Temperature:	180°F (85°C)
Signal Output:	2 Channel Quadrature 30,000 PPG (8100 PPL)
Power:	8-24 VDC
Materials	
Body:	303 Stainless Steel
Gears:	Stainless Steel (Hardened)
Bushings:	Carbide
Shafts:	Carbide
Seal:	Teflon
Filtration:	100 Mesh (maximum)
Connections:	Threaded 3/8" AN (F)
Weight:	4.5 lbs. (2.0 Kg)



RF-1 Flowmeter - Introduction

## INSTALLATION

The unit may be mounted using the bolt pattern shown in Figure 1. [2] 1/4 - 20 bolts should be used. Always mount the flowmeter with the gear faces perpendicular to the horizon of the earth (i.e. Vertical). This minimizes the effect of gravity on the gears. The direction of flow must be plumbed as marked on the side label of the meter. The fluid inlet is opposite the sensor connection.

The meter should be plumbed such that flow enters at the bottom of the meter and exits at the top. This eliminates any possibility of air entrepment in the meter.

#### WARNING

► This meter may be installed in Class I, Division I, Group D locations when used in conjunction with the proper Zenner Barrier.



RF-1 Flowmeter - Installation

## MAINTENANCE

### FLOWMETER SERVICING

Flowmeter problems can be caused by improperly filtered fluid. Particulates in the fluid can cause gear binding, resulting in improper signals for the actual flow rate. Maintain the fluid filters according to the instructions from the filter manufacturer. If repeated disassembly and cleaning for removal of solids and particulates occurs, inspect the entire fluid supply system and evaluate the system cleaning cycle.

Fluid back-up, that is reverse flow, can cause reacted/catalyzed material to enter the flow-meter. Reverse flow will be detected by the 2k controls and the system will shut down. The flowmeter should be cleaned immediately, before the fluid sets-up.

Under normal operation the magnetic sensors or electrical connections will not require replacement.

## SERVICE

Disconnect sensor cable [1] from the flowmeter sensor [2]. Remove meter for service to a suitable clean area to perform maintenance. Using a 3/16" Allen wrench, remove all 10 [3] bolts. Pull the sensor section STRAIGHT apart from the gear pocket section. If the body halves do not slide apart easily, DO NOT pry them apart with screwdrivers, etc. Rather, replace a few of the bolts and only thread them in a few turns, then tap the top of the bolts with a soft mallet, while holding the top half of the body. Pull the gears and pins from the gear pocket section. Clean and replace worn parts as necessary. Install new teflon o-ring [7]. Install all parts the order they were removed. Install flated portion of shafts [5] toward gears (see Figure 1). Push the two covers together, aligning the pins and holes by hand.



Figure 1: Views of Flow Meter Body

NOTE

There is only one way to install the sensor section and the gear pocket section.

Snug all screws down. Tighten the screws in the sequence pattern shown in Figure 1 to 13 lbs•ft torque. This is a cross pattern to insure proper gasket sealing.



Figure 2: View of Flated Portion of Shafts

## *Tw* Ransburg

### CALIBRATION

Refer to appropriate associated equipment for calibration procedure.

### AUTOMATIC CLEANING OF THE FLOWMETER

#### Fluid Line Air Purges

Air purges are often used in automatic coating operations for rapid color changes and to minimize the amount of solvent required to flush-out the old color. Special considerations must be made when using air purges through the flowmeter.

1. Air purges do not provide the lubrication the flowmeter gears require. Lubrication is normally provided by the metered fluid or solvent.

2. Air purges can cause some coating materials to "dry" on the flowmeter shafts and gears thus affecting the performance characteristics of the flowmeter, especially when water-based materials are used.

3. Excessively long air purges will cause premature gear and shaft failure.

4. All clean cycles should begin with a solvent push to prevent drying of coating material on flowmeter parts.

5. Solvent and air "chop" cycles are recommended as the most efficient way of flushing flowmeters.

6. Air purge cycles are not recommended in water-based applications.

## PARTS IDENTIFICATION





RF-1 FLOWMETER - PARTS LIST (Figure 3)			
ltem #	Part #	Description	Notes
1	TR-SSEH-585	Electrical Connector	Same connection as TR-SSEH series flowmeters
2	76252-00	Sensor Assembly	See Service Bulletin #98-11 (revised) for interchangeability with TR-SSEH-793-2 sensors
3	1/4" -20 x 1-1/4" L.	Socket Hd. Cap Screw	Must be grade 8 or better
4	N/A	Upper Housing	Cannot be purchased seperately
5	76271-00	Shaft	Interchangeable with TR-SSEH-604
6	76270-00	Gear	Stamped with an 'F' or 'G' to distinguish from TR-SSEH-603 gears
7	76272-00	Teflon O-Ring	
8	N/A	Lower Housing	Cannot be purchased seperately
9	N/A	Alignment Pin	Pins press fitted in and cannot be removed or replaced.
10	LSF10033-00	3/8" AN x 3/8" ODT Fit.	Optional fitting
	77104-00	3/8" AN x 3/8" NPSM (m)	Optional fitting
	77105-00	3/8" AN x 1/4" NPSM (m)	Optional fitting
11	76804-00 (-01)	3/8" OD SS Tubing	Used when replacing TR-SSEH series flowmeters on 2k Controls (or 2k880) fluid panels.
12	76850-00	Fitting Kit	Used when 1/4" OD tubing is required or preferred

## WARRANTY POLICIES

### LIMITED WARRANTY

**ITW Ransburg** will replace or repair without charge any part and/or equipment that fails within the specified time (see below) because of faulty workmanship or material, provided that the equipment has been used and maintained in accordance with ITW Ransburg's written safety and operating instructions, and has been used under normal operating conditions. Normal wear items are excluded.

THE USE OF OTHER THAN ITW RANSBURG APPROVED PARTS VOIDS ALL WARRANTIES.SPARE PARTS: One hundred and eighty (180) days from date of purchase, except for rebuilt parts (any part number ending in "R") for which the warranty period is ninety (90) days.

SPARE PARTS: One hundred and eighty (180) days from date of purchase, except for rebuilt parts (any part number ending in "R") for which the warranty period is ninety (90) days.

EQUIPMENT: When purchased as a complete unit, (i.e., guns, power supplies, control units, etc.), is one (1) year from date of purchase. WRAPPING THE APPLICATOR IN PLASTIC, SHRINK-WRAP, ETC., WILL VOID THIS WARRANTY.

ITW RANSBURG'S ONLY OBLIGATION UNDER THIS WARRANTY IS TO REPLACE PARTS THAT HAVE FAILED BECAUSE WORKMANSHIP OF FAULTY OR MATERIALS. THERE ARE NO IMPLIED WARRANTIES NOR WARRANTIES OF EITHER MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ITW RANSBURG ASSUMES NO LIABILITY FOR INJURY, DAMAGE TO PROPERTY OR FOR CONSEQUENTIAL DAMAGES FOR LOSS OF GOODWILL OR PRODUCTION OR INCOME. WHICH RESULT FROM USE OR MISUSE OF THE EQUIPMENT BY PURCHASER OR OTHERS.EXCLUSIONS:

#### EXCLUSIONS:

If, in ITW Ransburg's opinion the warranty item in question, or other items damaged by this part was improperly installed, operated or maintained, ITW Ransburg will assume no responsibility for repair or replacement of the item or items. The purchaser, therefore will assume all responsibility for any cost of repair or replacement and service related costs if applicable.

## MANUAL CHANGE SUMMARY

This manual was published to supercede Service Manual **FM-00-01.1** to make the following changes:

1. Added "Service Manual Price" to the "Front Cover".

- 2. Added "Safety Section".
- 3. Added "Warranty Section".
- 4. Added "Manual Change Summary" page.

5. Added "Service Manual Price" to the "Back Cover".

6. Revised "Contact Information" on the "Back Cover".

Service Manual Price: €15.00 (Euro) \$20.00 (U.S.)

#### Manufacturing

1910 North Wayne Street Angola, Indiana 46703-9100 Telephone: 260/665-8800 Fax: 260/665-8516

#### **Technical/Service Assistance**

Automotive Assembly and Tier I
Industrial Systems
Ransburg Guns
www.itwransburg.com

Telephone: 800/ 626-3565	Fax: 419/ 470-2040
Telephone: 800/ 233-3366	Fax: 419/ 470-2071
Telephone: 800/ 233-3366	Fax: 419/ 470-2071

Technical Support Representative will direct you to the appropriate telephone number for ordering Spare Parts.





Form No. FM-00-01.3 Litho in U.S.A. 07/07