

# Service Information

## FUEL INJECTION PUMP TIGHTENING TORQUE SERVICE MANUAL REVISION

One of the tightening torques in the 'Fuel Injection Pump Tightening Torques' service manual (Publication No. EE10E-11012) has been revised.

### 1. APPLICABLE PAGE

Page 46 ('12 COMPENSATORS' section)

### 2. REASON FOR REVISION

It was found that there was a difference between the torque specified by the Design Department and that implemented by the Manufacturing Department.

As a result of verification by the Design Department, the torque value was revised to that implemented by the Manufacturing Department.

### 3. LOCATION OF REVISED TORQUE VALUE AND NEW TORQUE VALUE

- Location of revised torque value: Refer to 'Revision' in the figure below.
- New torque value: 15 ~ 21 {1.5 ~ 2.1} (Previous: 29 ~ 39 {3 ~ 4})

