

OPERATING MANUAL SHREDDER



HSM FA 400.2



english

Keep in a safe place for future use!

Contents

1.	Proper use, warranty	3
2.	Safety instructions	3
3.	Overview	4
4.	Dimensions	5
5.	Transportation, installation	6
6.	Operating and display elements on the keypad	7
7.	Start-up, inspecting the safety devices	7
8.	Malfunctions	9
9.	Maintenance and care	.10
10.	Scope of supply, accessories	.12
11.	Technical data	.12
12.	Electric wiring diagrams for Solo- and Combination-version	.13

HSM (UK) Ltd.

14 Attwood Road / Zone 1 Burntwood Business Park Burntwood Staffordshire WS7 3GJ

Tel. +44(0) 1543.272.480 Fax +44(0) 1543.272.080 info@hsmuk.co.uk www.hsmuk.co.uk



HSM GmbH + Co. KG Bahnhofstrasse 115 88682 Salem / Germany

Tel. +49 (0) 75 53 / 822-0 Fax. +49 (0) 75 53 / 822-160 info@hsm-online.de www.hsm-online.de HSM of America LLC

1075 Andrew Drive, Suite C West Chester PA 19380

Tel. (610) 918-4894 (800) 613-2110 Fax (610) 918-4899 customerservice@hsmofamerica.com info@hsmofamerica.com www.hsmofamerica.com

Do not reach into the paper feed

Before destroying credit cards and store cards, CD-ROMs or floppy disks,

you must fit a splinter guard (strip

curtain, order no. 1.513.050.445).

Danger of injury during intake

Do not go near the paper feed open-

ing with long hair, loose clothing, ties, scarves, necklaces, bracelets etc.

Do not destroy any material which might become tangled, such as tapes,

Splinters can cause injury

Danger of injury

openina.

1. Proper use, warranty

The shredder is exclusively designed for destroying paper and cardboard, as well as store cards, credit cards, CD-ROMs and floppy disks. Its sturdy drive mechanism is not damaged by paper clips and staples.

Our general business conditions are applicable. We provide a one year warranty for the document shredder. The warranty period is 6 months when used in multiple shifts. This warranty excludes wear, damage due to improper handling, natural depreciation, and actions taken by third parties.

Safety instructions 2.




Caution:

It is prohibited to operate one only machine of a combination-version machine. Only the combination of document shredder and HSM baling press fulfils the requirements of EN 294 (Safety clearances).

- Read the operating manual before starting up the shredder.
- Do not remove or modify safety devices which guarantee the safe operation of the machine.
- Observe all safety instructions attached to the machine.
- The shredder may not be operated by anyone under 16 years of age.
- Only open the front door once the machine has come to a standstill.
- Carry out inspection and maintenance regularly.
- Switch off the shredder, disconnect the power plug and call customer service in the following circumstances:
 - Power cables or plugs are damaged -
 - Liquid has entered the shredder
 - The shredder has been exposed to rain
 - The machine does not work properly despite the operating manual having been observed
 - The shredder has been damaged







binder ties or foil.

before moving or cleaning the shredder, or any other task outside its normal scope of use.



Maintenance and service tasks may only be performed by HSM customer service and service engineers of our dealers.

Operating controls for your safety

Emergency stop button



In the event of danger, press the emergency stop button immediately. This switches off the shredder, and stops the cutting block and feed belt.

Main switch (only Solo-version)



In the event of danger, turn the main switch to "0". You can secure the main switch in


this position with a padlock to prevent restarting.


Overview 3.




- Main switch (only solo-version) 1
- 2 Keypad
 - Emergency stop button
- 3 4 Loading tray
- 5 Option: extra-wide work table
- Left cover panel 6
- 7 Right cover panel
- 8 Intake conveyor,
 - paper feed opening Front door
- 9
- 10 Braking swivel castors 11 Oiler on particle cut machines
- Nameplate 12


4. Dimensions








HSM FA 400.2 Combi version




Transportation dimensions (without tray)




Space requirements for operation and maintenance

5. Transportation, installation

- Place the shredder in its packaging on a smooth, level surface.
- Remove the packaging.
- If you need to move the shredder through narrow doors, you can wait until it is at its final location before fitting the loading tray. Without the tray, the machine is only 805 mm wide.
- When moving the shredder, note that it may topple over.
- The shredder can be moved on its rollers. If using a forklift to transport a Solo machine, you must first remove the waste trolley. Then you can push the forks under the machine from the left or right side and lift it up.



- Fitting the loading tray: Fasten the tray on both sides at the top with the Phillips screws (1) and at the bottom with the 2 nuts (2).



- The shredder may only be placed in dry rooms on a hard, level floor not on carpets. The floor load on each roller is approximately 107 kg.
- Place the machine in such a way that the power plug is easily accessible and the ventilation slots are free.

Solo machine:

- Lock the front castors by pressing down the brake lever.

- Connect the power plug of the shredder to the 32A CEE mains socket.

Combination version:

- Push the shredder up to the baling press until the press and the outlet chute of the shredder touch.

- Bolt the shredder and the baling press together.

- Lock the front castors by pressing down the brake lever.

- Connect the power plug of the shredder to the combination socket of the baling press.

- The machine must be connected to a power source which meets the specifications on the nameplate.
- Make sure the power cable is unobstructed and that nobody can tread on it.
- No platforms or other raised surfaces may be placed near the shredder if they encroach on the specified safety clearances.


6. Operating and display elements on the keypad

Paper jam or overload Ready for operation Red LED Green LED Door open Waste bag full Red LED Red LED Start button The shredder switches on. The feed belt moves in the intake direction. Stop button The cutting block and feed belt stop. The shredder is in standby mode. **Reverse button** The cutting block and feed belt run in reverse.

7. Start-up, inspecting the safety devices

Attaching the waste bag (Solo version)

- Open the front door and pull out the waste trolley.
- You can modify the trolley from a double-chamber to a single-chamber system by removing the brackets (1).



- Put in a new waste bag and fold it approximately 20 cm over the top frame tube. When using a two-chamber system, make sure that there is also around 20 cm of plastic foil below the brackets (1).
- Push in the waste trolley and close the front door.

Switching on the shredder



• Pull out the emergency stop button.



Solo-version: Turn the main switch to the I position.
 Combination-version: Turn the main switch on the baling press to the I position.

► The green "Ready for operation" LED lights up.

Note:

There is a safety switch on the front door of the shredder. The machine can only be switched on when the door is shut.



Press the green start button.
The cutting block and feed belt start up.



Caution!

The feed belt can run in reverse if the phase wires in the power plug are incorrectly connected. Turn off the main switch immediately and pull out the power plug! Have an electrician change two of the three phase wires

Inspecting the safety devices



- Check that the safety devices are working properly:
- At the start of each shift
- After any maintenance or repair work

Do not start the machine until you have checked the emergency stop button and the door switch and found them to be in perfect working order. If any defect arises during operation stop the machine immediately and make sure it is corrected.

Checking the emergency stop button



Press the emergency stop button while the machine is running. The shredder must switch off immediately. The cutting block and the feed belt must stop.

The machine will only start again once you have pulled out the emergency stop button again.

Inspecting the door switch



- Open the front door.
 - The red "door open" LED must light up.
 The cutting block and feed belt must stop.

After you close the door, the LED should go out and you can start the machine again by pressing the start button.



Shredding material



Place the material to be shredded on the loading tray and then place batches on the feed belt.

If material that is not supposed to be shredded is mistakenly placed onto the belt, never attempt to pull it out.



- Press the stop button.The drive stops.
- Press the reverse button.
 The cutting block and feed belt run in reverse.



• You can now remove the material from the belt and start the shredder again by pressing the start button.

Waste bag full



The red LED on the keypad lights up. The shredder switches off automatically.



Press the reverse button for approx. 3 seconds.
 Part of the material is pulled back into

Part of the material is pulled back into the apparatus.

• Open the front door and shake the waste trolley.

▶ The cut material spreads in the cut material sack and does not fall into the interior of the shredder.

- Pull the waste trolley out and change the cut material sack.
- Push the trolley back in and start the shredder again by pressing the green start button.

Stopping the shredder



- Press the stop button.
 The cutting block and feed belt stop.
 - The shredder switches to standby mode.

Switching off the shredder



• Turn the main switch on the paper shredder or the baling press to **0**. You can secure the main switch in this position using a padlock.

8. Malfunctions

Check the following before calling customer service:

- Is the power plug connected?
- Is the shredder switched on?
- Is the front door closed?
- Is the waste bag full?
- Is there a paper jam in the shredder?
- Has the motor been overloaded?

Paper jam (excessive paper feed)



- The red LED on the keypad blinks
- The cutting block automatically runs in reverse for several seconds.

ΉSM®

Caution!

The blade rollers can still cause injuries even while they are not running. Do not reach into the cutting apparatus! Wear safety gloves!

Do not alternately press the "Forwards" and "Reverse" buttons to remove the blockage. This will damage the shredder.

• Take out the pile of paper.



• Press the green start button and put less paper on the feed belt.


Electric motor overheated

- The red LED on the keypad lights up.
- ▶ The shredder switches off automatically.
- Let the motor cool down for 20 30 minutes.



• Press the green start button.

Door open



- ▶ The shredder switches off automatically.
- Close the front door.



Press the green start button.

9. Maintenance and care

Cleaning the cutting block Strip cut machines: (1 x daily)



- Switch off the shredder.
- Squirt special cutting apparatus oil through the paper feed opening onto the blade rollers.

Order no. 1.235.997.401 for a 250 ml bottle Order no. 1.235.997.500 for 5 litre container

- Let the cutting apparatus run forwards and backwards several times without feeding in any paper.
 - ▶ This loosens paper dust and particles.

Cross cut machines:



If the cutting quality deteriorates or the machine becomes noisy:


- Let the shredder run without feeding in any paper.
- Push the lever of the oiler down several times.
- Make sure the oil level in the container is between the MIN and MAX markings. Order no. 1.235.997.500 for 5 litre container


Checking the chain tension (twice yearly)



- Switch off the shredder.
- Pull out the power plug.
- Remove the tray and the left cover panel.

The sag of the chain should be 4 - 10 mm.





If you need to tighten the chain:

- Remove the right cover panel.
- Loosen the nuts and push the motor and the tensioning screws until the chain sags by 4 – 10 mm.
- Tighten the nuts again.
- Put the cover panels and the tray back on.

Note:

Do not tighten the chain too much, as this will cause premature wear on the chain and bearings.



Greasing the drive chains and cogs (twice yearly)



- Switch off the shredder.
- Pull out the power plug.
- Remove the tray and the cover panels.
- Grease the cogs and the drive chains from the motor to the cutting apparatus, the cutting block to the feed belt and the cutting block to the regulating roller.
 Recommended lubricating grease: K2K in accordance with DIN 51502/DIN 51825
- Put the side cover panels and the tray back on.



You must check that the feed belt runs straight:

Switch on the shredder and let it run for 10 minutes. During this time, the feed belt must run in the middle of the snub roller. If it slips to the left or right edge, you must alter the setting of the snub roller.

Checking the feed belt for wear

The surface of the feed belt can become worn after long periods of use. If you can see the fabric inlay in the belt, it must be replaced. Please notify our customer service.

Cleaning the shredder:

- Switch off the shredder and disconnect the power plug.
- Only use a soft cloth and mild soapy water for cleaning. Never use scouring agent, cleaning fluid, petroleum or thinners.

Tightening the feed belt

The feed belt should not slip when loaded with material.



• Switch off the shredder.



- Loosen the hex nuts (1) on the left and right sides of the snub roller.
- Loosen the lock nuts (2) of the tensioning bolts (3).
- Tighten the feed belt evenly using the tensioning bolts.



Note:

Only tighten the feed belt until it stops slipping. The feed belt bearing may be damaged if it is tightened too much.

• Tighten the hex nuts on the snub roller and the lock nuts on the tensioning bolts again.


10. Scope of supply, accessories

- Machine on pallet with a wooden frame, strapped with packing tape and packed in foil
- 4 waste bags, order no. 1.513.995.000 for 2-chamber system (Solo version)
- 1 waste bag, order no. 1.513.995.100 for 1-chamber system (Solo version)
- Special cutting block oil For strip cut machines: 250 ml bottle, order no. 1.235.997.401 For cross cut machines: 5 l container with spout, order no. 1.235.997.500
- Operating manual
- Accessories: strip curtain, order no. 1.513.050.445

11. Technical data

Cutting type		Strip	cut	Cross cut									
Cut size (mm)		11,8	5,8	5,8 x 50									
Safety level DIN 32757 - 1		1	2	3									
Cutting capacity (sheets), DIN A4,	70g/m ² 80g/m ²	180 144	130 104	120 96									
Cutting speed		210 n	nm/s	220 mm/s									
Effective width		428 mm											
Weight		approx. 425 kg											
Waste container volume (Solo machines) 1-chamber system 2-chamber system		460 l 2 x 230 l											
Power supply			3 x 400 V	V, 50 Hz									
Rated power			4	<w< th=""></w<>									
Max. current			21	A									
Fuse rate		25 A											
Plug		CEE 32A											
Sound level (idling / under load)		61 dB(A) / 75 dB(A)											

0702




12. Electric wiring diagrams

13


H5

FA 400.2


ß



F				+	+																					1 Bl.
		\mid	+	+	+		+	+										$\left \right $	+	$\left \right $	+	+			Blatt	_
		$\left \right $	+	+	+	+	+	+										$\left \right $	+	$\left \right $	+	+			05 6	
			_		+		+	+											+					- AV	598 C	
					+		-	+																-	500	· ·
				-	+	-	+	+																-	-	
			-	+	+		+	+											-					-		
				-	+		+			۱۹-	58.27				77	22	7S-∀W+	×						-		2
				+	+	-	+			rA- rA	58.57				12			×	_	\square			 jnj beq		Plan Nr.:	liagram N
				-	+	-	+	_		۲A- ۲A							+BF-51	×	_				Sack voll	-		1
			_	+	+		+				50'7/					22		×	+					-		
			+	+	+	+	+	_		ы- Г	\$0.27				61		+8F-51		-	$\left \right $	_		suA-toN			
			+	+	+	+	+	×		1A-	£)'7/				81	17	52-AN+	×	+	$\left \right $	+	+	 qoot			
-			+	+	+	+	+	-		14-	15:03					77		×	+		_	\square	Tür	-		
F			+	+	+	+	+	×		r.A	19.27					Zd			-		_			hection		
			-	+	+	+	+	×		۲A-	78.57		-			١d	IM-AM+	×	+		-			- terminal connections	Set	
				-	+		+				90'l⁄			\mathbb{D}		ЪЕ	ſΜ-ΑΜ+	X	_					termin	400 V / Soo	
				+	+	_	+	×		-KJ	90'l/				٤١	M	ſM-AM+	X	_					Б		
-					+		_	×		-K۱	90'l/				٢L	٨	ſM-AM+	X	_				motor	Klemmenplan	FA400	- AV-S-X1
				_	+	_	+	X		-кл	50°17				u		ſΜ-ΑΜ+	X					Motor	Kle		`<
				_	+	_	+	-		-к5	71.62				01											
				_	+		+	+		-к5	23.17	21			6	7		X	_					-		
					_		_	×		-кл	23.17	ίŢ				Z							nətlərisiqueH Anityina niem	-		hinch
								×		S+	29'L/			Ð	L		₩+	X	_					_		Frests durch
					_			×		S+	28'L/			Ð	9		۶+	X						_	Ī	-
								_			28.1/	ЪЕ	4		S		\$+	×						_		
					_			×	L	۱ ۸ -	28'I/	N			7	N	OLX-	X								
																٤٦	OLX-	×					nie switch Netzstecker Pulg zniem			7 für
											28'I/	٤٦			٤	S	10-78+	X					etler etler	н		Frests für
																۲٦	01×-	×					nis witch Vetzstecker Plug plug			
											28°17	۲٦			ζ	٤	r0-98+	×					atlatschalter nitch	Ή		
																ı٦	01×-	×					anismicu 1942stecker 1940sniem			
Ļ											28.r\				ι	l	+BF-Q1	×					retlerschalter Antiver nie		+	Ur spring
													X- : 912i9J Meznen9mm	אוי ד										.12.2002		
	netnemmoyetëned tnemmon eniveb								бu							бu							Gerätekommentar device comment	.60		
									Anschlußbezeichnung connection Betriehsmittel	,	sort	Klemmenkommentar comment	Drahtverbindung wire connection Laschenverbindung	La M	her	Anschlußbezeichnung connection	la.							Datum	Geprüft	Norm
									Anschlußbezei connection Betriehsmittel		Darstellungsort location	ienkom int	Drahtverbindung wire connection Laschenverbindu		terminal number	ilußbez ction	Betriebsmittel device									Name
									Anschlußbe connection Betriehsmi	device	Darstellu location	Klemment comment	Drahtverbin wire connec Laschenver	Typ typ Klemmennimmer	termin	Anschlußbe connection	Betriet device									Dation
									leniatni.ieda te				rod lenim					0					_	\parallel	+	
					səp a əzəqli			frei	111a101 11a101az	I9iZ		9†	zialflulda	enA		nnetxe	nəriszləiS Terisei təpist	frei	u Đ	nundois oitenpi	sab alo sab alo	le X Yeo	-			
										it			iproppe x					90								R Anderinn
											I n9	tdage	DIN 3ל ר	א חארא	ιәш	JAVS†	לנאיי						0.1.7 (9) DADU3 tim tiletan	H		a



HSM[®]



7																												
																		T					Π				i	E.
																											Blatt 1	7
																											1	-
		t																									05 8	
		┢				+	+	+										+		-		+	$\left \right $			-AV	598 05	
		\vdash				-	+	-										-				+	$\left \right $				200	
																						_					10	
	"							×	2Z I	+BF-5	£3'Z/				9	8 5	7X-2+98											
	suA-toN qots yonagnama							×	12 1	+BF-5	×۲.E3				S	Z L	7X-2+98	= ~										- 10
											/5'E5			,	7	z 9	LX-S+d8										Plan Nr.:	-> ifeld
		┢						×		19-	72.52				ε	z s	7X-2+98	+				+						
		┢				+	+	-								+		+		_		+	$\left \right $					
					_	_	_	×		۱A-	58.27					Ζ6	7X-2+98	+		_		+	\square					
								×		۱A-	58.27				l	Z OL	7X-2+98	- 9				_					<u> </u>	1
								×	S	۱A-	SO'Z∕				0	Z ZL	r2-38	•		<				u				
											50'Z/			`	6	เแ	r2-98	·		<				qots y	suA-toN (onepreme	ions		
					T	T		×		۱A-	/۲.СЗ				8	1 12	E2-AM	·		<			Π			- terminal connections		
		t					1	×		۱A-	⁄.2.03				L	1 22	E2-AM		>	<		+	Π		Joop	inal co		
		┢					+	×		۱A-	79'7/				ç	+		+		<		+			٦ÜT	term		
		┝			-	+	+	+								+		+		+	$\left \right $	+	$\left \right $			an		_
		╞			_	+	+	×		۱A-	78.2/					l ld	ſM-AM	*		<		+	$\left \right $			Klemmenplan	LA400	=AV+5-X1
											90'1/					۶E ا	ſM-AM	•	*						"	a K	₹ : 	EA.
								×	9	-K2	90'l/	۱M			8	ιM	ſΜ-ΑΜ	•	m									
								×	†	-K2	90'l/	١٨			Z	۱۸	rm-AM	·	2									
								×	z	-K2	sa∵ı∕	IU			I	ιn	rm-Am	·	-						notoM notom			
		F						×		S+	78'I/				⊕	L	AM.		>	<						U		z durci
		┢						×		S+	28.1/				~	9						+						trsa
		┢				+	+	<u> </u>		5					-	+	111 61 10	-		/		+	$\left \right $					
		\vdash				_	+				28.1\					S 3d		+		<		+	$\left \right $					
							_	×	L	۱A-	28.1\	N				7 7	7X-2+98	-		<		_						
																٤	7X-2+98			<								z tur
											28'L/	٤٦				εs	KI	-		<								Ersatz für
-																Z	7X-2+98	-	>	<								
		1		\square	1	1					28.1\	۲S				zε	КI	-		<	$ \uparrow $	1	Π			1		
		\vdash		\square	+	+	+	-								ι	7X-2+98	+		<	+	+						
		┢				-	+				28.1\	17						┢		<		+	$\left \right $					sprung.
											1917		jųezue	inemme.			14									10		-in
										ŕ		l	χ-:a	tsisJ												6.02.20		
	netnəmmoyətënəd tnəmmon sivəb								бur			L		cī,		- Eur								tekommentar ce comment		iter 0	+	1
									teichnu	el	sort	menta	dund noit	indun	. mer	ceichnu	e.									Datum Bearbeiter	Geprüf	Norm
									ußbez	bsmitt	ellung:	enkom n†	rerbin	envert joint	unua.	ußbez	tion bsmitt											Name
									Anschlußbezeichnung connection	Betriebsmittel device	Darstellungsorf location	Klemmenkommentar comment	Drahtverbindung wire connection	Laschenverbindung strep joint	Typ typ Klemmennummer	rerminal number Anschlußbezeichnung	connection Betriebsmittel device											Ę
		L														Ĺ		3-								\parallel		Datum
		\vdash			jisəb i			rei 0	nnətni nəd: Jennətni.ned					uldos enima			zetxe nedsiesleiZ netxe.neds tegre	4	4 0	noiten	6isəb	oldeo	\neg					
		<u> </u>	Б	ichnur	iəzədl	ledeX	1	1 ₁		i۲	E NI(1						serve pri	Ļ		ճսոսպ	niəzədl	Kabr						lerung
			_	_	_	_	_							NIO 4	erk nach		vztudo2						Ec	15 0.5.7 (A) 0.5.9 ii	m tiletana	\vdash		R. Anderung
																												-

/																											
																											BI.
																										7	
		-		-	-		-	+	+									\vdash	-	_		-	+		+	Blatt	
																										0	
		_		_	_	_		_	+													_	_		-9P	500 598 05	, ,
																									Π.	-	i
								+	1																	00	š
																									1	-	
		┝		-	+	-		+	+									\vdash					-		1		
									Т																		<u>i</u>
				_	_	_	_	_	+										_	_		_	_		-	Plan Nr.:	Juan 1
																										Pla	ein
																									1		
		_		_	_	_		_	+													_	_		-		
				+	\uparrow	+	+	1	1									\square	+	\uparrow	$\uparrow \uparrow$	+	\top				
			\square	_	-				\downarrow									\square	_	_	\parallel		_		-		
				+	+	+			┥									\vdash	+	+	+		+		۰.		
				\square														\square					_		- terminal connections		
																									nned		
									┥														+		- 0 		
																									,ë		
																									te		
					-			+	┥													+	+		E I		
																									duar	00	×-S
A.																									Klemmenplan	FA400	=BP+S-X7
					-			+	+											-		+	+		+		٦
					-	_		-	+													-	-				
												ſA.ſ∖VA=			bΕ	S	rX-2+VA=		×							٦	÷
												58.2\VA=		1	01	١Z	lX-2+VA=	9									z dur
		-		-	-	_		+	+							-			_	-		+	+			C	Ersat
												58.S\VA=			6	22	¢X-2+VA=	ŝ									
												E7.S\VA=			8	9Z	rx-2+VA=	4									
		-		_	-	_		+	+										_			+	+		-		
												EA.S\VA=			L	57	rX-2+VA=	m									
									Τ			27.2/VA=			g	7 Ζ	ΓX-2+VA=	2		Τ			T		1		_
		-	\vdash	+	+	+	+	+	+									\vdash	+	+	$\left \right $	+	+		-		Ersatz für
												27.2/VA=			S	53	¢X-2+VA=	-									Ersa
							1	1	1			rA.r∖∨A=			+	7	ΓX-2+VA=		\times		\square				1		
		-	\vdash	-	+	+	+	+	+							Ľ				+	+		+		-		
												ſA.ſ∖VA=			٤	٤	¢X-2+VA=		×								
									1			14.1 \ \ \ A =			7	z	ΓX-2+VA=	\square	\times		\square				1		
				-	+	+	+	_	+			ra.r∖va=			۔ ۔	L.	N 2.VA-	\vdash	\sim	+		_	+		-		6un
												ra.r∖va=			L	L	¢X-2+VA=		×								Ursprung
														ldeznenammal	к										007		7
									ļ				L	X- : stsisJ	_										5.02.2		
	tnemmore of vector									-						L.								tnemmor sovet	.90		-
	Gerätekommentar									iunu			tar	f fur		วันทนเ								lerätekommentar	Datum	inf f	E
										Anschlußbezeichnung connection	tel	Darstellungsort location	Klemmenkommentar comment	Drahtverbindung wire connection Laschenverbindung strep joint	Typ typ Klemmennummer terminal number	Anschlußbezeichnung	tel								Dati	Gep d	Nor
										-ion	smit	fung (it nkor	erbir nnec nver oint	unu _	JBbe .	smit										Name
										schlt inect	Betriebsmittel device	Darstellu location	imme Imen	Drahtverbin wire connec Laschenver strep joint	Typ typ Klemmennummer terminal number	schlt	connection Betriebsmittel device								\square	\square	1
										An. con	Bei dev	Dar Loc;	Kle cor	Dr. vir str	Tyi typ Kle ter	An:	cor Bel dev										Datum
																		3						ļ	\mathbb{H}	+	Ä
		\vdash	uq	oitenp	isəp	alde:)	-		nnətni nər Jennətni.ner				od Jenima		lenn	atxa.nanjaziaiz etxa.nanj tagnet	。 1	0	noite	uɓisəp	aldeo		4			
			би	inudoi	iəzəq	l9d6)	ł		frei					siəlfluldos			txe nertierleiz	frei		бипи	toiezed	Kabeli			4		Бu
											i٦			ibnocce Mr				90									R. Änderung
												j uə.	цзеәс	1 75 NIO 4	nerk nact	٦٩٧	Schutz							92 0.5.7 (9) DADI tim tiletar			R. A
\ '		-						-	-																		- /





Declaration of Conformity

Machinery directive 98 / 37 / EG EMC directive 89 / 336 / EWG Low voltage directive 73 / 23 / EWG

The manufacturer **HSM GmbH + Co. KG**, Bahnhofstrasse 115, D-88682 Salem declares herewith, that the paper shredder **(Solo machine) HSM FA 400.2** corresponds with the above mentioned EC Machine Directive including all relevant modifications. Applied standards and technical specifications:

- EN 60204-1:1997-12
- EN ISO 12100-2:2003-11
- EN 55014-1:200-10 + A1:2001-10 + A2:2002-10
- EN 61000-3-2:2000-12



- EN ISO 12100-1:2003-11
- EN 294:1992-06
- EN 55014-2:1997-02 + A1:2001-12
- EN 61000-3-3:1995-01 + A1:2001-06



Salem, 01.12.2004

It is prohibited to operate only one machine of a combination-version machine. Only the combination of document shredder and HSM baling press fulfils the requirements of EN 294.

Gutier

Rolf Gasteier - Technical Director

Machine type inspection for compliance with the requirements of the EC Machine Directive was carried out by the "Administration"/ Inspection Authority Committee of Experts, Subject Area "Office Machines and Devices", on the premises of the Verwaltungs-Berufsgenossenschaft, Deelbögenkamp 4, D-22297 Hamburg. This inspection authority is the authority responsible in accordance with Annex V of the EC Machine Directive.