

DVD-302 SCSI Slot-Load DVD-ROM Drive Unit Addendum to the Product Specifications Installation Under Microsoft Windows NT[®] 4.0

The information provided below concerns issues with the installation of the Pioneer[®] DVD-302 DVD-ROM Drive under the Microsoft Windows NT Operating System.

- ♣ Verify that Windows NT Service Pack 3.0 is present before installing the drive
Available from the Microsoft website

- ♣ Assign each DVD-302 drive a unique SCSI ID

- ♣ Reapply the Service Pack 3.0 upon initializing Windows NT 4.0

- ♣ Confirm that the drive(s) appear within *My Computer*