Step 3   Software Installation

1. Insert the SpeedStream® USB 10/100 Ethernet adapter Installation CD into your CD-ROM drive.
2. The *New Hardware Wizard* will appear.
3. When prompted for the device driver location, select CD-ROM drive.
4. Click Next.
5. Follow the on-screen instructions.
6. When prompted, click Yes to reboot.

When the reboot is complete, verify that the USB 10/100 Ethernet adapter
has a valid connection by observing the LED light.

LED Indicator Light

Color	Status	Description
——	OFF	No network connectivity or No driver loaded
RED	ON	10 Mbps connection
	Blinking	10 Mbps traffic
GREEN	ON	100 Mbps connection
	Blinking	100 Mbps traffic

Technical Support for North America is available 24 hours a day, 7 days a week, by phone, email or online:

Phone: 1-877-823-6722
Email: support@speedstream.com
Online: *http://www.support.speedstream.com*

SIEMENS

For more information regarding *SpeedStream®* products visit: www.speedstream.com.
Efficient Networks, Inc.
A Siemens Company
**4849 Alpha Road**
Dallas, TX 75244

SIEMENS

SpeedStream® USB 10/100 Ethernet Adapter

Quick-Start Guide

Before you begin:

Verify that the following items came with your kit:


| USB 10/100 Ethernet Adapter | Software CD-ROM | Quick-Start Guide | Safety and Certification information |

Before installing the SpeedStream® USB 10/100 Ethernet Adapter, ensure that your PC is equipped with the following. Note that the adapter is not installable on Macintosh computers.

• Microsoft® Windows® 98 Retail, Windows® 98 SE (Second Edition), Windows® 2000, or Windows® Me (Millennium Edition)
• 32 MB RAM
• Available USB Port

Step 1   Connect the USB Cable to the computer

Connect the USB cable to the USB port on your computer

Step 2   Connect the Ethernet Cable

Using an RJ-45 cable (not included), connect the Ethernet port of the adapter to an Ethernet modem, bridge, router, switch or hub.