# Derob-LTH   v1.2
**Installation guide**

1. Click on *full* installation for the version 1 and revision 1 in the table.
2. Copy the file *Derob1.2Setup20060118.exe* to a directory on your hard disk.
3. If earlier version of the Derob program is installed, uninstall it.
    Use the function *Add / Remove programs* in the control panel to uninstall.
4. Double-click the downloaded file  – the installation will start.
5. Follow the instructions given by the installation program. Use the default  filename.
    If you get a question about <u>version conflicts</u>  , keep existing file (answer Yes! ).
6. If you want to use an existing  Derob-LTH model then  start the Derob-LTH program and select the Derob
    entry  *File / Edit System File*
        a) Set  the <u>Project directory</u> to the directory of the existing model.
        b) Click on *Save* to save the settings.
7. If you want to change user interface, go to the entry *File / Edit System File*  and select from the list of user
    interfaces.
*8.* Exit the Derob-LTH program  - select the entry   *File / Exit Derob-LTH*

After the installation is completed, some documents are stored in the directory   c:\derob\document  :
1. CD_Derob4w4.doc – Derob-LTH user's manual
2. CD_Exercise.doc – a small exercise to show how to work with the program.
3. CD_Hints.DOC – some hints.
4. CD_Kgkcomf.doc – a theoretical background to the comfort program.
5. CD_Kgkshade.doc – a theoretical background to shading of diffuse radiation.
6. CD_Kgkwdw.doc –  a theoretical background to thermal modelof windows.

**In case you face any problem, don't hesitate to send an e-mail to
Hasse.Kvist@Ebd.Lth.Se**