USER MANUAL

TWOWHEELCOOL ≫ Pilot
### HELMET LIGHT

1 • Control button
2 • Rear light (red)
3 • USB charge port
4 • Strap holes
5 • Front lights (white)
6 • Battery indication

RECHARGING: To recharge the PILOT connect USB cable provided to the USB charge port and plug into USB socket of computer or power adapter.

Ensure the USB connection into the light is very firm, you should hear a "click" when the cable is fully engaged.

We suggest overnight charging before the first use.

TECHNICAL SPECIFICATIONS
Helmet Light

LED	40 Lumen White LED (Front light) and Safety Red LED (Rear light)
BATTERY	Rechargable Lithium Polymer LiPo
FEATURES	Water resistant silicone, USB rechargable battery, adjustable velcro straps, low battery indicator light, memory function.

MODES

STEADY	3 hours burn time
REAR FLASH	4 hours burn time
FRONT FLASH	5 hours burn time
FULL FLASH	10 hours burn time (Rear and Front Flash)
CHARGE TIME	5 hours
DIMENSIONS	150 x 42 x 20 mm
WEIGHT	23 grams
MATERIALS	Silicone outer, ABS case.
OPERATION	Hold control button (1) for two seconds to power PILOT on/off. Press control button (1) to scroll through light modes once power on.
LOW BATTERY	The low battery light (6) will turn red when the PILOT is powered off and requires charging. When connected to the computer or safe power adaptor, the Battery Indication Light (6) will shine red. When fully charged, the light will turn off indicating the unit is fully charged.

Note - the indicator may be difficult to see on Black coloured models.