

## WARNING!

To prevent damage to the camera or lens of an ICS200 or ICS300 Series Camclosure® integrated camera system, the camera must be installed in the proper hole of the mounting bracket. If the camera is not installed in the correct hole, the window of the enclosure may be forced against the lens.

Refer to the illustrations for which mounting hole to use to install the camera.








Pelco World Headquarters: 3500 Pelco Way, Clovis, CA 93612-5699 USA • **www.pelco.com** USA & Canada: Tel: 800/289-9100 • Fax: 800/289-9150 International: Tel: 1-559/292-1981 • Fax: 1-559/348-1120

C2463M (1/03)


## WARNING!

To prevent damage to the camera or lens of an ICS200 or ICS300 Series Camclosure® integrated camera system, the camera must be installed in the proper hole of the mounting bracket. If the camera is not installed in the correct hole, the window of the enclosure may be forced against the lens.

Refer to the illustrations for which mounting hole to use to install the camera.







Pelco World Headquarters: 3500 Pelco Way, Clovis, CA 93612-5699 USA • **www.pelco.com** USA & Canada: Tel: 800/289-9100 • Fax: 800/289-9150 International: Tel: 1-559/292-1981 • Fax: 1-559/348-1120

'ELC