



TurboChef Technologies Inc.

Field Service Bulletin

File: *FSB10036*

Date: *SEPT 02*

REFERENCE:

TurboChef C-Series ovens operational issue

DISTRIBUTION:

All field support personal

APPLICATION:

C3/C, C3/AB, C3-Multi

PROBLEM:

Incorrect (backward) installation of cooking platter causing door open and operational issues.

ACTION REQUIRED:

During a service call, start-up or scheduled maintenance to an oven:

1. Prepare oven top trim surface next to top left sticker "Exposure to Microwaves" by cleaning and removing grease residue using Oven Cleaner.
2. Once you have cleaned the surface, peel back of new sticker and place next to existing sticker with a minimum of 1/4" clearance. See Figure 1 for overview and figure 2 for details.



NGC
To make

C3



HHB



TurboChef Technologies Inc.

Field Service Bulletin

File: *FSB10036*

Date: *SEPT 02*



END OF PROCEDURE

NGC
Tornado

C3



HHB