



CORDLESS LED WORK LIGHT MODEL H7517 INSTRUCTION SHEET

Introduction

The Model H7517 Cordless Rechargeable LED Work Light (**Figure 1**) features a retractable hook, 30 LEDs that stay lit 5 to 6 hours on each charge, and a water-resistant body.

Inventory

- A. Work Light 1
- B. Charger 1
- C. Cord..... 1

Assembly and Operation

1. Attach the cord to the charger.
2. Place the work light into the charger and charge for 6-8 hours before the first use. An indicator light on the charger glows red during charging.

Note—If the indicator light does not illuminate, make sure the work light and charger contact. Be sure the work light is OFF before charging.

3. Remove the work light from the charger when the indicator light turns green, showing it is fully charged. Recharge the work light when the bottom warning LED turns red.

Note—After the warning LED illuminates, the work light will stay lit for several seconds before shutting off.

4. Charge the work light in the charger for three hours after the warning LED illuminates. Fully charge the light before storing.

If you need additional help with this assembly, call our service department at: (570) 546-9663.



Figure 1. Model H7517.


CAUTION

Keep away from fire! Work light could explode!

NOTICE

Work light is water resistant, but not waterproof. Unit may be damaged if submerged in water.

H7517 Parts Breakdown and List



REF	PART #	DESCRIPTION
1	PH7517001	HOOK
2	PH7517002	HOOK BRACKET
3	PH7517003	END CAP
4	PH7517004	BATTERY 4.8V 3300MA/H-NI-H
5	PH7517005	TAP SCREW M3 X 25
6	PH7517006	TAP SCREW M2 X 6
7	PHTEK9M	TAP SCREW M3 X 15
8	PH7517008	WORK LIGHT
9	PH7517009	CHARGER
10	PH7517010	CORD

COPYRIGHT © FEBRUARY, 2005 BY GRIZZLY INDUSTRIAL, INC.
**WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE
OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.**
#BL6956 PRINTED IN CHINA