



## Installation & Setup

1. Copy **VeriTape.exe** and **win2k\_winxp** to your PC.
2. Connect the VeriTape scanner to your PC with the USB cable provided.
3. You will see on your PC the **Found New Hardware Wizard**.
4. Question: **Can Windows connect to Windows Update to search for software?** Select **Yes, this time only**.
5. Question: **What do you want the wizard to do?** Select **Install from a list of specific locations**. Select **Include this location in the search**: Enter the location of the file **win2k\_winxp** on your PC.
6. After the file is found you will see the message: **The software you are installing for this hardware has not passed Windows Logo testing to verify its compatibility with Windows**. Select **Continue Anyway**.
7. After the installation is complete create a VeriTape icon on your desktop.
8. Start VeriTape. If you see a message in the box at the bottom of the VeriTape screen **LTO Reader not Found – still looking**, select **File**, then select the **Com port** to which the scanner is connected.
9. Exit VeriTape. Restart VeriTape and you are now ready to scan cartridges.

To download the VeriTape user manual go to [www.mptapes.com/veritape](http://www.mptapes.com/veritape)

To download the newest version of VeriTape go to [www.mptapes.com/veritape](http://www.mptapes.com/veritape)