User manual Skin cleaner T3





1. Declaration of Conformity

EU Declaration of Conformity

Manufacturer: Jasopels A / S Address: Fabriksvej 19, Tel. +45 76 94 35 00 DK-7441 Bording

Machine: Skin cleaner T3 Type: 52-0000

Jasopels A / S declares that this product is in accordance with the following EU directives:

2006/42/EC

2006/95/EC

2006/108/EC

Furthermore, we declare that the following harmonized standards have been applied:

EN 60204-1

DS/EN 12100 : 2005

DS/EN 14121-1

DS/EN 14121-2

Place and date: Bording, 31st. January 2011

Name: CEO Poul Bach

AmBack



2. Table of contents

1.	Declaration of Conformity2
2.	Table of contents3
3.	Preface4
4.	Symbol explanation5
5.	Introduction to the machine6
6.	Start-up7
7.	Operation8
8.	Replacement of belt10
9.	Maintenance11
10.	Technical data12
11.	Spare part list13
12.	User's note14



3. Preface

• This User Manual is an important part of your new machine. Read the manual carefully and use it as a reference book.

• This manual contains important information about safety and the proper use of the machine.

• The manual should be stored with the machine. It is important that the user manual is supplied with the machine upon resale and loan out.

• The owner of the machine must make sure that the operator, service personnel and others who have access to the machine are instructed on the proper use and handling of the machine. Read this user's manual for more information.

• Unauthorized modifications, additions or changes on the machine are not permitted for reasons of overall safety. Neither the manufacturer nor the vendor can be held responsible for damage that occurs because of the above mentioned. Any risk arising of unauthorized use is solely the end user's responsibility.



4. Symbol explanation

Please read this manual and follow the instructions. In order to emphasize certain information, the following expressions are used:





A triangle containing an exclamation mark is a warning symbol that warns you of important instructions or information concerning this machine.

• Danger!!



A triangle containing a lightning bolt is a warning symbol that warns of "High Voltage"

• Warningl!!



A triangle containing a warning about an entanglement and crush hazard.



5. Introduction to the machine

- BS Skin Cleaner Type 3 is designed for the softening of mink skins.
- After having beed terated in this machine they are soft and fluffy, ready for auction.
- The machine is easy and simple to use.





6. Start-up

- Before start-up the machine has to be mounted onto a table. The machine is pushed up to the edge of the table, then the two bolts are fastened tightly under the table top. Make sure that the machine is fastened to the table before it is started.
- In the factory the machinehas been assembled with a 5-poled 16 A CEE plug at the end of the power supply cable and can be connected to an outlet with 3P+N+PE. At the side of the skin cleaner a valve has been installed with a quick coupling where the compressor's tube is connected.



- Connect a vacuum cleaner under the machine, the tube on the machine fits into the hose of a vacuum cleaner. This removes loose hair and sawdust from the skins' outside and does not hurl them into the room.
- The skin cleaner is now ready for use.





7. Operation

After having been connected the skin cleaner is ready for use. Turn on the air and suction before starting the machine.



Fig. 1 Start/stop

On the front of the machine there is a switch. Start the machine by pressing the green button and stop it by pressing the red.

Never operate the machine without suction, because this will whirl dust and sawdust into the room.

Standing in front of the skin cleaner the skin is run through the machine from the right to the left with its back turned towards the operator.

Take the mink's head in your left hand and its tail in your right. The mink's head is run in between the brushes and followed by the skin with a firm pull, at an angle down towards the left (in the drwaing: down towards the right). This is done in order to soften the skin over the last brushes.



Fig. 2 Brushes



Keep the skin taut by holding back on the tail. Run the skin trough the machine at an even speed to avoid stripes.

After the skin has been run through the skin cleaner there will be a certain amount of sawdust in the skin. At one side of the machine there is an air branch over which the skin is pulled.

The air branch is activated by pressing it slightly upwards, now the skin is blown clean from the inside.



Fig. 3 Nozzle

After this the skin is ready for delivery!



8. Replacement of Belt





The belt has to be mounted in the following way:

- To begin with remove the screen at the back of the skin cleaner.
- Now the belt can be removed. The belt can be loosened with the help of the tension pulley
- Put the new belt into its place according to the following drawing.



- Remember to tighten the belt again using the tension pulley.
- Finally put the screen back into its place.



9. Maintenance



Loosen the 3 screws with a 4 mm unbraco key

Fig. 5 Changing brushes

Skin cleaner is mainly maintenance-free, but there will always be a certain wear on the brushes. When the brushes have to be exchanged, it is done in the following way:

- Disconnect the air and power supply.
- Screw off the screens.
- Each of the 12 brushes has been attached by 3mm unbrako bolts. Unscrew the 3 bolts, remove the old brushes, put a new on and tighten the 3 bolts again.
- Screw the screens back.
- Reconnect air and power supply and continue with your work.
- At the end of the season the machine has to be cleaned, this is done with compressed air and water. After having been cleaned all the lubricating nipples on the bearing have to receive a single press with a grease press.

Fig nr	Item number	Name
1	5190-00529000	Brush for Skin cleaner 150 mm

••••	DANGER!	•
•	If you need to do maintenence work inside the drum, the power cable and compressed air hose MUST be removed.	



10. Technical data

•	Electrical connection:	3 x 400 V +	PE 5 poled CEE plug
•	Power:	1,2 A	
•	Air connection:	Quick coup	ling
٠	Air consumption:	Max 8 bar. 1 l/min.	
•	Measurements:	Height	55 cm
		Length	28 cm
		Width	63 cm



11. Spare part list



Fig. 6 Skin cleaner

Fig nr	Item number	Name
6.1	5931-30037405	Engine
6.2	5911-5228320001	Valve
6.3	5925-51289000	Engine starter Skin cleaner T3



12. User's note



