

User Manual

Pressure • Temperature • Humidity • Air Velocity • Airflow • Sound level

Thermometers TN 100, 101, 102 & TN 150, 151

TN 102







See table

"Functions available from main screen"

-"Function" key -

1x: "Hold": measure holding

1x long: "Auto-Hold" see p.2

2x: "Min/Max": display of minimum and maximum values from channel 1 since last request.

3x: "Min/Max": display of minimum and maximum values from channel 2 since last request.

4x: Back to held measure.

- "On / off" key -

ON : Switch-on OFF : Switch-off

Escape: Return to previous screen

"Backlight" key -

1x - ♥ Level 1

3x - ♥ No backlight

"OK" key -

1x "To validate"

or "Delta temperature" voir P2.

Functions available from main screen		
Selec prob	TY (Select) — (OK) — Press (Select) to scroll down units	⇒ Validate with OK
Automation Shut-of	2x (Select) — (OK) — Press (Select) TO SCROIL GOWN MINUTES	⇒ Validate with OK
Bee	p 3x (Select) - OK) - Press (Select) to activate or to deactivate.	⇒ Validate with OK
(Class 150) Lowe	4X (0000) — (OK) — O	⇒ Validate with OK
(Class 150) Uppe alarr	3x (Select) - (1)k)	⇒ Validate with OK
(Class 150) Auto	Av land made (11 11)	⇒ Exit with Esc
(2 channels) Delt	1x (OV) > Dolto tomporoturo voluo : T	⇒ Exit with Esc

Simplified mode

The simplified mode is the disablement of all keys, excepted "On / off" key.

- > To enable this mode :
 - Switch-off the device.
 - Press simultaneously "Hold" and "On / off" keys.

 When the simplified mode is **enabled**, the automatic shut-off is settled on 15 mn.

 This mode stays **enabled** even if device is switched on and off.
- > To disable this mode:
 - Switch-off the device.
 - \bullet Press simultaneously "Hold" and "On / off" keys.

Device is in normal mode.

How to change battery

- 1. Remove the front part at the back of the instrument
- 2. Remove old battery
- 3. Insert the new battery in accordance with proper polarity drew inside the housing.
- 4. Replace the front.





nce returned to KIMO, required waste collection will be assured in the respect of the environment in accordance to 2002/96/CE guidelines relating to WEEE

www.kimo.fr

Tel: + 33.1.60.06.69.25 - Fax: + 33.1.60.06.69.29

