VIA USB 2.0

User Manual



Contents

1.0	USB Port FeaturesP	.3
2.0	System RequirementP	.3
3.0	Driver LimitationsP	.3
4.0	Driver Installation (Windows XP)P	.4
5.0	Driver Installation (Windows 2000)P	.5
6.0	Driver Installation (Windows ME)P	.7
7.0	Driver Installation (Windows 98/98SE)P	2.8

Introduction Add a USB device to your PC

Instantly add USB peripherals to your PC. Never open your computer case again after you have your USB Port (PCI) card installed and say good-bye to confusing cables.

The USB Port (Universal Serial Bus) allows you to instantly connect USB devices to your computer. The USB Port will allow you to attach 2/3/4 USB devices instantly.

You never have to worry about running out of slots in your computer or those confusing IRQ's again. You can also "Hot Swap" your USB devices. What does this mean" You never have to power down your PC to install hardware again. Gamers can switch joysticks on the fly. Welcome to the USB Revolution.

1.0 USB Port Features

This is a true 32-bit PCI-Bus USB card. It supports the following I/O features:

- 2/3/4 USB ports (root hub and two/three/four down stream function ports)
- Auto detect speeds and connections of devices
- Integrated physical layer transceivers
- Normal and low power operating modes
- Fully Plug and Play compatible
- OHCI (Open Host Controller Interface) specification V2.0 register compatible
- USB specification V.1.0 compatible

2.0 System Requirements

This setup program will install the driver for VIA USB 2.0 Host Controller. Before you start to run the setup program, please make sure your computer is an IBM PC-compatible system.

This driver can be used either the following operating systems: Windows98 Second Edition. Windows Millennium. Windows 2000. Windows XP.

3.0 Driver Limitations

Current limitations of the driver are: Composite devtces and Hi-Speed Isochronous Transfers are currently not supported.

Please visit VIA web site (http://www.via.com.tw) to get the latest driver.

4. Driver Installation (Windows XP)



*NOTE: The drivers for lhis card are compressed on the included CD using "Winzip".

 Please make sure this PCI card has been installed on your system correctly.
 Open the "Device Manager" and check if there is a "Universal Serial Bus (USB) Controller" in "Other devices".

- Insert the Driver CD into the CD-ROM drive and execute the setup program by double clicking on the "setup.exe" file, (the path is \USB\USB2.0-VIA)
- 3. Select "Install USB 2.0 Driver" and press "Next".



4. Press "Continue Anyway",



5. Press "Next".



6. Press "Continue Anyway".



7. Then Press "Finish".



 Open "Device Manager" and check if your device works.

Notel If there is a yellow exclamation mark on "VIA USB 2.0 Enhanced Host Controller" or "USB 2.0 Root Hub Device", please remove this item from the "Device Manager" by clicking the "Uninstall" button and click 'Refresh' to re-install this driver again.

No. of Concession, Name	(a)G(A)
the detail time this	
Borney Constraints Co	

5.0 Driver Installation (Windows 2000)



'NOTE: The drivers for this card are compressed on the included CD using "Winzip".

 Please make sure this PCI card has been installed on your system correctly.

Open the Device Manager and check if there is a "Universal Serial Bus (USB) Controller" in "Other devices".

- Insert the Driver CD into the CD-ROM drive and execute the setup program by double clicking on the "setup.exe" file, (the path is \USB\USB2.0-VIA).
- 3. Select "Install USB 2.0 Driver" and press "Next".



12 Indered

Triat, when and pa

Cathorne and

COLUMN THE CASE

A statute and the function of the statute of the st

9

4 Press "Finish".

Note! This will restart your system. Please remember to close other programs before you click "Finish"



5 After restarting your system, please check if you. device works.

Note! If there is a yellow exclamation mark on "VIA USB 2.0 Enhanced Host Controller" or "USB 2.0 Root Hub Device", please remove this item from the "Device Manager" by clicking the "Uninstall" button and click "Refresh" to re-install thts driver again.

6. Driver Installation (Windows ME)

rdush Pegparitit	41
Same (Prove State (States of States) Parton and	
When the states of the strengthe strengthe	
The second state of the second states of the second	22
An and the second secon	
And Francisco May USB New Plate And USB New Plate And Vis Local DISP PD NEW Descend Plate Complex And Vis Local DISP PD NEW Descend Plate Complex	
 Violation 2001/CONDUCTOR Devices of Net Consider Violation 2001/CONDUCTOR	
and the set of the property for the set	3

3. Select "Install USB 2.0 Driver" and prei





 Please make sure this PCI card has been installed on your system correctly.

Open the Device Manager and check if there is a yellow exclamation mark on one of the "VIA Tech 3038 PCI to USB Universal Host Controller" item.

- Insert the Driver CD into the CD-ROM drive and execute the setup program by double clicking on the "setup.exe" file, (the path is \USB\USB2.0-VIA).
 - 4. Press "Finish".

Note! This will restart your system. Please remember to close other programs before you click "Finish" button.

-	a management of the	1000
	Trees of the local division of the local div	100
		183
100	a manufacture	15000
		10254

5. After restarting your system, please check if your device works.

Note:

If there is a yellow exclamation mark on "VIA USB 2.0 Enhanced Host Controller" or "USB 2.0 Root Hub Device", please remove this item from the "Device Manager" by clicking the "Uninstall" button and click "Refresh" to re-install this driver again.

The "green question mark" on "VIA USB 2-0 Enhanced Host Controller" item is not an error message. Please ignore it.

7.0 Driver Installation (Windows 98/98SE)



 Please make sure this PCI card has been installed on your system correctly.

Open the "Device Manager" and check if there is a "Universal Serial Bus (USB) Controller" in "Other devices".

2. Insert the Driver CD into the CD-ROM drive and execute the setup program by double clicking on the "setup.exe" file, (the path is \USB\USB2.0-V1A).

3. Select "Install USB 2.0 Driver" and PIPSS "Next".



4. Press "Finish".

Note! This will restart your system. Please remember to close other programs before you click "Finish" button.

-	and the second second	
(m)	And the Apple Street of Street	
5		

128.000			
2	and the second second		
1.0	And the outputter		
2.5	Section and the section of the secti		
2.0	Control in Control of		
1 200	an Japan and a	-	-
41	en Mittel and	5-5- A	2
4.5	A DECEMBER	1000	·
Course]	- 2000 [-	man fr	-
			S. Sour

5. After restarting your system, please check if your device works.

Notel If there is a yellow exclamation mark on "VIA USB 2.0 Enhanced Host Controller" or "USB 2.0 Root Hub Device", please remove this item from the "Device Manager" by clicking the "Uninstall" button and click "Refresh" to re-install this driver again.