

Digital Photogrammetric System

PHOTOMOD

Version 6.0.2

USER MANUAL

Hotkeys








Table of Contents

1. General 3
2. The Explorer window and windows for resources load/save 4
3. Progress bar 4
4. Windows with a list of files/folders of Windows file system 5
5. The main system window 5
6. Geomosaic program 9

The system provides using of customized and non-customized hotkeys, that duplicate menu items and toolbars buttons. This document contains information only about the hotkeys, which customizing is not provided by the system. The rest of hotkeys used in the system you can setup in the **Customize hotkeys** window (**Service** › **Customize hotkeys**).

1. General

Press and hold the **Alt** key to substitute the **Cancel** button by the **Reset** button in the following windows:

- the main window of the **Control Panel** utility (the **Control Panel** item of context menu in the *System Monitor* module, opened by right click the  icon in *Windows* system tray);
- the **Triangulation points** window (**Orientation** › **Tie points list**  or **Orientation** › **GCP list** );
- the **GPS/GLONASS communication setup** window (**Service** › **GPS/GLONASS** › **Activate** );
- the **Set correlator parameters** window in *StereoLink/StereoACAD*;
- the **Symbols** window to setup symbols for triangulation points displaying (the  button in the **Points measurement**);
- the **Set ground sample distance** window (**Block** › **Set GSD**);
- the **Exterior orientation parameters** window (**Orientation** › **Exterior orientation data list** );
- additional windows of the main **Compute points** window (**Vectors** › **Compute points automatically**) used to setup parameters of correlator, pass parameters, parameters of first approximation;
- the **Brightness-Contrast-Gamma**, **Color balance** and **Rotate-flip** additional windows of the main **Radiometric correction** window (**Block** › **Image radiometric correction** ).

Shortcuts like **Ctrl+Alt+<letter>** are used to open the following windows and modules:

- **Ctrl+Alt+A** allows to open the **Automatic tie point measurement** window;
- **Ctrl+Alt+B** allows to open the **Block editor** window;
- **Ctrl+Alt+C** allows to open the **Marker** window;
- **Ctrl+Alt+D** allows to open the **Measurements** window;

- **Ctrl+Alt+E** allows to open the **Explorer** window;
- **Ctrl+Alt+I** allows to open the **Manage project cameras** window;
- **Ctrl+Alt+K** allows to open the **Points measurement** module with images containing marker position;
- **Ctrl+Alt+L** allows to open the **Block layout** window;
- **Ctrl+Alt+M** allows to open the **Mosaic** module;
- **Ctrl+Alt+O** allows to open the **Project management** window;
- **Ctrl+Alt+P** allows to open the **Settings** window;
- **Ctrl+Alt+R** allows to open the **Relative orientation report settings** window;
- **Ctrl+Alt+S** allows to open the **Block adjustment** toolbar;
- **Ctrl+Alt+T** allows to open the **Triangulation points** window on the **All triangulation points** tab;
- **Ctrl+Alt+W** allows to open the **2D-window (stereopair)** window.

2. The Explorer window and windows for resources load/save

- **Ctrl+Alt+E** allows to open the *Explorer* window;
- Click selected resource while holding the **Alt** key to display full ID of the resource and local/network path to the resource (for folders ID only) and to copy the ID to clipboard.
- **Left arrow/Backspace** allows to move at one subfolders level *up*.
- **Right arrow/Enter** allows to show content of selected folder, i.e. to open the folder.
- **Shift+F6** in the **Image** window (the **View as image** context menu item, opened by right click the resource) allows to enable *roam-mode* to view raster image, which allows to move the image using left mouse button, while the marker is fixed and located in the center of the window.

3. Progress bar

- **Ctrl+C / Ctrl+Ins**, as well as the **Copy** context menu item, allow to copy event log to clipboard.
- **Ctrl+Shift+C / Ctrl+Shift+Ins** allow to copy event log to clipboard in inner format.



Click an event log area to use hotkeys.

4. Windows with a list of files/folders of Windows file system









For example, lists in the **Raster Converter**, **Add images**, **Add pushbroom images** windows.


- **Backspace** allows to move at one subfolders level *up*.
- **F5** allows to refresh a list of files/folders in case you made changes in *Windows* file system during working in the window.
- [only for files list] **Ctrl+Alt+Up** allows to move to a folder that includes selected file, i.e. to rise one level up.
- [only for files list] **Ctrl+Alt+Down** allows to display content of selected folder, i.e. to open the folder.

5. The main system window

The following hotkeys are available in the main system window:


- Press and hold the **Alt** key during closing of the **Camera** window (the  button in the **Project management** window) that allows to not re-calculate interior orientation.
- **F3** in the **Project management** window (**Project** > **Open/manage** ) allows to pass from the projects list to input field used for input of key word for project search, i.e. this allows to shift the focus. Moreover, you can click the **F3** button after keyword input for projects search to perform sequential search for projects in the list.
- **Ctrl+F** on the **Codes** tab in the **Classifier** window (**Window** > **Classifier**) allows to search for specified keyword in the Code table, **F3** – to move to the next code, containing the keyword specified.
- Press and hold the **Ctrl** key while opening the **Measurement** window (the  button of the main toolbar), that allows to not change current active layer in Manager, otherwise the *Marker* layer becomes active. In the same way, press and hold the **Ctrl** key while closing the **Measurement** window, that allows to not change the *Marker* active layer (if the window was opened without using the **Ctrl** key), otherwise the layer which was active before opening the window becomes active.
- Press and hold the **Alt** while clicking the  button in the **Marker** window (the  button of the main toolbar) allows to copy all three coordinates to clipboard, otherwise – just X,Y coordinates.
- Double click in the **Map** window (opened using the  button in the **Points measurement** window) to search for marker position only on opened images of the **Points**

measurement window; **Shift** + double click – allows to search and open only the images that contain marker position.

- **Ctrl+Ins/Ctrl+Del** in tables of the **Camera** window ( in the **Manage project cameras** window) allow to add/delete the table row. Press the **Shift** key while clicking the $10^3/10^{-3}$ buttons to multiply/divide distortion coefficients specified in the table by 10, otherwise by 1000.
- In the **Block editor** window (**Window** › **Block editor**) you can use the following hotkeys:
 - **Ctrl+F** – search for an image by name (part of name);
 - **Ctrl+A** – choosing (highlighting) of all block images;
 - **Ctrl+arrows** – move chosen images right/left/up/down;
 - **Shift+Del** – delete chosen strip;
 - **Del** – delete chosen images;
 - **Shift+Ins** – add a new strip;
 - **Ins** – add images from files, located *out* of active profile resources.
- Press and hold the **Shift** key while clicking OK in the **Select stereopair** window (**Window** › **Stereopairs** › **Select stereopair**) after *highlighting* of one of two *selected* images on the **All images** tab, leads to opening of the *highlighted* image in 2D-window as a *right* stereopair image, otherwise (by default) images position in a strip is considered during stereopair opening.



Enabled checkbox in the list means choosing the object, blue highlight – object highlighting in the list.

- Press and hold the **Alt** key during opening of new 2D-window for single image (**Window** › **New 2D-window (single image)**) allows to open the image in 1:1 zoom, otherwise, it will be opened in 2D-window in full.
- Press and hold the **Alt** during choosing the **Rasters** › **Load georeferenced images (files/resources)** menu item to load selected image to 2D-window immediately using parameters of the last loading, otherwise prior to load selected image file a settings window is opened (used to select coordinate system and background color).
- Press and hold the **Shift** key while starting the *Mosaic* program (**Service** › **Mosaic** ) to invert a state of the **Start Mosaic as a separate application** checkbox on the **Modules** tab in the **Settings** window that contains general system settings.





Enabled checkbox **Start Mosaic as a separate application** allows to start the *Mosaic* program in a separate application, if the checkbox is disabled the module is opened instead of the main window of the system.

- **Shift+F10** allows to open context menu in 2D-window.

In graphic windows of the system, developed using common platform, you can use the following hotkeys:

- **Alt+1** – 1:1 zoom
- **Alt+2** – **Alt+4** – customized zoom
- **Alt+0** – previous zoom
- **Alt-5** – “preset zoom” (used to switch between two customized zooms)
- **Alt+Enter** – show window content in a whole (zoom to fit)
- = on main keyboard, * on numeric keyboard, - on main keyboard / on numeric keyboard – used for zoom management
- **Shift+arrows** – “panning” for 0,9 of the window size, i.e. shift of the window content for 0,9 of the window size
- **Shift+PgUp/ Shift+PgDn/ Shift+mouse wheel** – used to change parallax of image (not marker)
- **Shift+F2** – set marker parallax to zero value (at current images parallax)
- **Shift+F3, Home** – set marker parallax to default value for stereopair
- **Shift+F7** – turn on/off mode of fixed parallax marker
- **Shift+F8** – show/hide brightness-contrast-gamma correction pane located on the bottom of the window
- **Ctrl+F8** – show/hide scroll bars
- **F2** – adjust depth – allows to change images parallax to superpose marker
- **F3** – restore depth – allows to set images parallax to stereopair default value
- **F4** – turn on/off “marker=mouse” mode
- **F5** – refresh window content (layers cache is not refreshed, at that)
- **F6** – turn on/off fixed marker mode (*roam-mode*)










- **F7** or **/** on main keyboard – center window by marker
- **F9** – turn on/off stereomode in 2D-window with stereopair
- **F11** – toggle a phase in stereo window when stereomode is enabled, or toggle left/right frame when stereomode is disabled
- **Arrows** – move marker in plane by 4 directions
- **12346789** on numeric keyboard (with enabled **Num Lock**) – move marker in plane by 8 directions
- **PgUp/ PgDn** – move marker along Z axis
- **Esc** – cancel selection
- **Ctrl+arrows** – move selected objects in plane by 4 directions
- **Ctrl+12346789** (use numeric keyboard with enabled **Num Lock** to enter numbers) – move selected objects in plane by 8 directions
- **Ctrl+PgUp/ Ctrl+PgDn/ Ctrl+mouse wheel** – move selected objects along Z axis
- You can enable mouse additional features using the following hotkeys:
 - **Ctrl** + mouse move with pressed left button – allows to drag selected object in plane
 - **Alt** + mouse move with pressed left button – enables panning mode
 - **Shift** + mouse move with pressed left button – allows to select by rectangle in group selection mode by rectangle (the  button of the **Tools** toolbar)

Objects selection by polygon in group selection mode by polygon (the  button of the **Tools** toolbox): **Shift** + mouse click – used to define first vertex of polygon, mouse click – to specify every next vertex, double click – to define the last vertex of polygon (to finish a polygon drawing), **Esc** – to cancel polygon drawing for objects selecting



 - **Alt+Shift** + mouse move with pressed left button along horizontal line – fast marker move along Z axis
 - **Ctrl+Shift**+ mouse wheel – change images Y-parallax
 - **Ctrl+Alt** + mouse move with pressed left button – zoom in of image part located inside of rectangle defined by mouse

- **Ctrl+Alt+Shift** + mouse move with pressed left button – zoom out of image part located inside of rectangle defined by mouse
- **Ctrl+Alt** + mouse wheel – zoom change
- **Ctrl+Alt** + mouse click – 1 step zoom in
- **Ctrl+Alt+Shift** + mouse click – 1 step zoom out
- **Alt+Shift** + mouse move with pressed middle button along horizontal line – fast change of image parallax

In the **Points measurement** window you can use the following hotkeys:

- **Space**, **Ctrl+Space** are used to search for and add a tie point on two (**Space**) or on all (**Ctrl+Space**) opened images (duplicate the  or  buttons).
- **Q** shows correlation coefficient of current image and left image in the marker position (duplicates the  button).
- Press and hold the **Shift** key while clicking the  or  button (**Shift+Space** or **Shift+Ctrl+Space** shortcuts accordingly) that allows to center left image in the window by marker, but search for contrast point will be not performed on the left image.
- Press and hold the **Alt** key while clicking the  or  button (**F** or **Ctrl+F** accordingly) that allows to perform search for a point with marker position, but without proposition about new point adding.
- **Shift+C** allows to synchronize markers in all windows with images and center by marker the image in active window.
- **Shift+*** / **Shift+/** (where * and / – keys of numeric keyboard) allow to zoom images in all opened windows at once (synchronously).
- **Ctrl+numbers** allow to adjust a step of move in stereowindow.
- **Alt+Ins**/ **Alt+Del**/ **Ctrl+F** allow to add/delete/search for GCP on the **GCP list** tab () of the **Triangulation points** window (with automatic enabling of editing mode during points adding or deleting)
- **Alt** during adding of GC point () allows to add only one measurement on selected image, otherwise – on all opened images.

6. Geomosaic program

- Press and hold the **Shift** key while creating a preview (**Mosaic** > **Preview**  and **Mosaic** > **Preview (current sheet)** ) to perform re-calculating of brightness adjustment (= **Mosaic** > **Rebuild brightness adjustment**).