



**Manitowoc**

## SOLID STATE RELAY ASSY.

FOR CA200, CA260, FA290 AND HA300 DISPENSERS

### IMPORTANT

Before replacing this relay on a QPA310 ice dispenser:

- Check for moisture on the two-pin Molex connector for the dispense switch wiring harness.
- If moisture is present, dry and seal the ends of the connector with silicone sealant.

Moisture on this connector can simulate a defective relay.

