



Dear Horton Customer:

Recently, Horton discovered that some of our 2012 crossbows equipped with the Anti-Dry Fire (“ADF”) feature may remain in the “safety lock” position even after an arrow is fully inserted down the barrel. We want to emphasize that this “ADF Safety Lock” issue does not impact the safety or shooting performance of the bow, and only affects a small percentage of bows within certain 2012 production runs assembled in our facility.

In the event your Horton bow exhibits this ADF Safety Lock issue, there are three options to address this issue (see link to “Instructional videos” below):

1. Disengage ADF – Customers may shoot the bow by simply pressing the “manual ADF release lever” to disengage the ADF device and slide the safety lever to the fire position prior to shooting. An arrow must always be fully inserted down the barrel before discharging the bow.

2. Replace ADF – A simple procedure to replace the ADF accessory with a new one, supplied by Horton free of charge, can be performed by the end-user or retailer in less than five minutes (see below for ordering a replacement ADF)

3. Remove ADF – Alternatively, the ADF accessory device may be removed from the bow in a three minute procedure by removing a pin.

The ADF Safety Lock issue was caused by an assembly procedure we implemented in early 2012 that placed a wire coil in an incorrect location. We recently corrected and implemented a new procedure so that current production is not impacted. Bow models that may be affected are as follows:

| Model | Serial Number's | Cabela's SKU# |
|--|---------------------------|----------------------|
| Brotherhood & Bone Collector Models CB300, CB300Z, CB302, CB305 | Between 84262 and 88671 | 03427799 |
| Team Realtree Models CB514, CB517 | Between 107055 and 112008 | 02998102 |
| Fury Models CB870, CB871, CB875 | Between 22025 and 25042 | 03409051 |
| Zombie Bow | | 03485686 |

We apologize for any inconvenience caused by the ADF Safety Lock if you happen to have one of our 2012 crossbows affected by this issue. Again, this issue does not impact the safety or shooting performance of your Horton crossbow.

Instructional videos for performing the procedures listed above and instructions for ordering a replacement ADF are available at:

www.hortonarchery.com/ADF.aspx

or call Horton Customer Service @ 1-800-551-7468