





# CORDLESS DRIVER DRILL

**Model 6095D**  
**Model 6095DQ\***  
**Model 6095DW**  
**Model 6095DWE**  
**Model 6095DWBE**  
(MJ/MCA/MME/MCP)  
**Model 6095DWL-2**




**02-2001**  
**6095DQ\* Discontinued in 1992**



## SERVICE CHANGES


### 1. Change on Spur Gear, Steel Ball & Clutch Cam.




Item No.	Description	Type 1	Type 2
28	Spur Gear 89	221883-7	226233-1
29	Steel Ball	216002-8 (4.8)	216011-7 (5.6)
30	Clutch Cam	223059-2	223086-9
	Serial No. 6095D	~ 500353E	500354E ~
	Serial No. 6095DW	~ 34715E	34716E ~

### 2. Change on Housing.


Type 1



Type 2



Type 3



Item No.	Description	Type 1 (MJ)	Type 2 (MME)	Type 3 (MCP)
3	Housing (R)	414391-7 (No Longer Available)	415007-7	<b>183055-1</b> Set (415007-7A)
44	Housing (L)	414392-5 (No Longer Available)	415008-5	<b>183055-1</b> Set (415008-5A)

3 Model 6095D  
 3 Model 6095DQ\*  
 3 Model 6095DW  
 3 Model 6095DWE  
 3 Model 6095DWBE  
 3 Model 6095DWL-2