


Battery Installation



- 1. Locate battery door on bottom of product
- 2. Open battery door and position 4 AA batteries as shown in diagram
- 3. Close battery door


Operating Instructions

Automatic Mode

- Press on/off button to turn on
- Set on safe, flat surface such as table or floor
- BOLT[™] will automatically turn off after 15 minutes
- Press on/off button to turn off before 15 minutes

Manual Mode

- Press on/off button to turn on
- Press on/off button and hold for 3 seconds
- Hold in your hand and aim BOLT[™] wherever you like to create your own laser patterns
- BOLT[™] will automatically turn off after 15 minutes
- Press on/off button to turn off before 15 minutes



In Automatic or Manual Mode, you can adjust the mirror to aim the laser across a variety of surfaces.



SCOTTSDALE • 1-800-377-8033 • PEORIA 480-767-6800 • 1-800-377-8033 • 623-215-8470

To Ensure Proper Function

Do not mix old and new batteries

Do not mix standard, alkaline, or rechargeable batteries

Only use batteries of the same or equivalent type as recommended

Exhausted batteries should be removed immediately

Do not dispose of batteries with household waste

Warning

Do not aim the laser light directly into the eyes of pets or people.

Always supervise pets playing with pet toys.

This toy is intended for pets, not for children. Do not allow small children to use this toy, alone or with pets, without adult supervision.

Inspect this product periodically for damage and discard it immediately if it appears worn or broken.