

Procedure

- (1) Open the operation panel assembly.




Fig.10-1

- (2) Wipe the CIS glass surface with a soft dry cloth (lens cleaner cloth). If the surfaces require moisture to remove the dirt, use a cloth slightly dampened with water to remove the dirt, followed by a dry cloth to remove streaks.




Fig.10-2