

Always on the Top

Apotop SSD Firmware Update User Guide V1.0





WARNING :

- 1. Apotop SSD Firmware Field Updater is only supported on Windows 7/Vista/XP.
- 2. Updating your SSD firmware should not result in date loss. However, Apotop recommends that you back up your data as a precaution before updating firmware.
- 3. You must have Administrator rights in order to run the Field Updater



1. Double click "APOTOP_FieldUpdater" to start running this program.





2. The program will scan SSD

APOTOP_FieldUpdate	x.				
Field	Updater			Apoti	D p"
All	Model Serial No	. FW Rev.	Signature	Capacity (GB)	
	Scanning For I	Drives. Plea	se wait		
Petected Drives ist of supported drives peration. Update Firmware	s detected on your system. Please put a ch	leck mark to the driv	ves that you want update	. Click on drive icon to see the ou	tput from the last



3. The existing firmware config.file number will be shown under the "Signature" column.

	Field Updater			Aj	potop°
All	Model	Serial No.	FW Rev.	Signature	Capacity (GB)
	APOTOP SSD S3A 128GB	02816133500500004019	5.0.1	158-0-22671	119.24
Detected	Drives	a put a check mark to the drives	that you w	ant undate. Click on drive	icon to see the autout from the last
Detected List of supp operation.	Drives ported drives detected on your system. Please	e put a check mark to the drives	that you w	ant update. Click on drive	icon to see the output from the last



4. Select the drive to be update.

APOTOP	FieldUpdater				
	Field Updater			Apo	top®
All	Model	Serial No.	FW Rev.	Signature	Capacity (GB)
	APOTOP SSD S3A 128GB	02816133500500004019	5.0.1	158-0-22671	119.24
Detected	Drives				
List of sup operation. Update	ported drives detected on your system. Please put a	a check mark to the drives	that you wa	ant update. Click on drive icon to see t	About Exit



5. Click "Update Firmware" button and locate the config.file name(first five digits) that match the last five digits of the "Signature" number shown in previous screen.

APOTOP_FieldUpdater	_			– – X
Select Firmware File				-
😋 🕞 🗢 📙 « 507a Fi	eldUpd 🕨 507a FieldUpdater	▼ 🍫 搜尋 507a FieldUpda	ter p	nntnn
	29 11	8= -		
和中国准 ▼ 利用具作	2004 A	•	lignature	Capacity (GB)
🗙 我的最愛	名稱	修改日期	類型 59-0 22571	119.24
📜 下載	20002.vic	25/3/2013 22:01	VIC 檔案	115.24
直桌面	20004.vic	25/3/2013 22:01	VIC 檔案	
🗐 最近的位置	20006.vic	25/3/2013 22:01	と福案	
	20008.vic	25/3/2013 22:01	VIC 檔案	
🗧 媒體櫃	20010.vic	25/3/2013 22:01	VIC 檔案	
□ □ 文件	20047.vic	25/3/2013 22:01	VIC 檔案	
→音樂	20058.vic	25/3/2013 22:01	VIC 檔案	
「相相」	22665.vic	25/3/2013 22:01	VIC 檔案	
	22667.vic	25/3/2013 22:01	VIC 檔案	
	22671.vic	25/3/2013 22:01	VIC 檔案	
	22673.vic	25/3/2013 22:01	VIC 檔案	
	22679.vic	25/3/2013 22:01	VIC 檔案	
本後遊達(C.) 新授党環境(D.)	22733.vic	25/3/2013 22:01	VIC 檔案	
→ 利増盥焼 (D.) → 木蝉茂環 (C.)				
提表	P·欠報(NI): 22671	Currented files (twist EE		
1田弁	e合件(N). 22071.VIC	Supported mes (*.vic *.rr	ing this buttor	1.
		開啟舊檔(O) ▼	取消	
Update Firmware	Rescan For Drives			About Exit

6. Click on "Open" once the correct file is selected.



7. A warning windows will pop up, select "Proceed" and the firmware update will begin.

Do not disconnect or interrupt the driver until update is complete!

APOTOP_FieldUpdater				
Field Updater			Ара	otop®
All Model	Serial No.	FW Rev.	Signature	Capacity (GB)
APOTOP SSD S3A 128GB	02816133500500004019	5.0.1	158-0-22671	119.24
Warning Automatic n data before If you wish t otherwise d Update Firmware Update Firmware Update Firmware Rescan For Drives	estart may occur after this op • proceeding. o cancel the operation and s ick Proceed. be prompted to choose a fi	peration. You sh ave unsaved da Proc	ould save all unsaved ata now, click Cancel, ceed Cancel	About Exit



8. When firmware update is done, press "Rescan For Drives".

Field Updater			Ар	otop®
All Model	Serial No.	FW Rev.	Signature	Capacity (GB
APOTOP SSD S3A 128GB	02816133500500004019	5.0.1	158-0-22671	119.24
Scanning Fo	r Drives. Please	wait		
Detected Drives List of supported drives detected on your system. Please put operation.	a check mark to the drives	that you wan	nt update. Click on drive icon t	to see the output from the last
Update Firmware Stop Rescanning				About Exit
Update Firmware Stop Rescanning	e changed t	to the	latest versio	About Exit
Update Firmware Stop Rescanning The firmware version will be APOTOP_FieldUpdater	e changed t	o the	latest versio	About Exit
Update Firmware Stop Rescanning The firmware version will be APOTOP_FieldUpdater Field Updater	e changed 1	o the	latest version	About Exit
Update Firmware Stop Rescanning The firmware version will be APOTOP_FieldUpdater Field Updater All Model	e changed i	TW Rev.	latest version	About Exit
Update Firmware Stop Rescanning The firmware version will be APOTOP_FieldUpdater Field Updater All Model APOTOP_SSD_S3A_128GB	e changed 1	EW Rev. 1 5.0.7a	latest version	About Exit On. Capacity (GB) 119.24

Update Firmware... Rescan For Drives

About... Exit