# GPSLog User Guide V1.02

-- Read and Get GPS Data from Tracker

## 1. Hardware and Software

- 1.1 GPS tracker that supports logging of waypoints.
- 1.2 USB to serial converter and USB cable
- 1.3 Driver Installer for USB to serial converter (PL-2303 Driver Installer.exe)
- 1.4 GPSLog (GPSLogV1.02.exe or newer version)

### 2. Step by Step

2.1 Install driver PL2303 for USB to serial converter

Run PL2303 Driver Installer and press Next till Finish. Then restart your computer.



2.2 Connect the tracker with USB cable and converter to the USB port of computer.



After connection, you can find a new COM in Device Manager. It can be COM3, COM4, or COM5...etc. In this example it is COM3

- Please try to use same USB port of your computer to avoid resetting of COM
- 2.3 Run GPSLog (GPSLogV1.02.exe or newer version).



2.4 Select COM of your USB converter and then press Open

S GPS Log For Serial CON V1.02	
	СОМЗ -
	Open
	Save
	Clear Log
	GetSum
	Start
	Clear 🗸 🗖 Display
	SaveToFile

2.5 Press the power button to turn on the tracker.

If blue light flashes (on for 1 second and off for 2 seconds, or on for 0.1 second and off for 2.9 seconds), then you can read the stored GPS data.



- 2.6 Tick Display to display the stored GPS data on the window of GPSLog.
- 2.7 Tick SaveToFile to select path to save the stored data.



2.8 Press GetSum to get the amount of logged data:

GPS Log For Serial COM ¥1.02	>
Start 2008-12-26/21:13:00	▲ COM3 ▼
111458.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111500.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111502.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Close
111504.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111506.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111508.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Save
111510.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111512.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111514.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111516.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111518.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Clear Log
111520.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111522.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
11524.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	GetSum
111526.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111528.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111530.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	24271
111532.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	L ILI I
111534.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111536.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111538.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Start
111540.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Otdatt
111542.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111544.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111546.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	<u></u> Uisplay

2.9 Press Start to get the stored data.

Note: The data will be removed from the tracker until you press Stop.

2.10Open the TXT file to read the stored data

▲ ¥T310-20081224.TXT - 记事本	_ 🗆 ×
文件(E) 编辑(E) 格式(Q) 帮助(E)	
111626.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111628.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111630.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111632.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111634.000, A, 2232.6549, N, 11484.9607, E, 0, , 241208, E0	
111636.000, A, 2232.6549, N, 11484.9607, E, 0, , 241208, E0	
111638.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111640.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111642.000, A, 2232.6549, N, 11484.9607, E, 0, , 241208, E0	
111644.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111646.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111648.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111650.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111652.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111654.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111656.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	
111658.000, A, 2232.6549, N, 11404.9607, E, 0, , 241208, E0	

#### 3. More Details

GPS Log For Serial COM ¥1.02			<u>_ [] ×</u>
Start 2008-12-26/21:13:00		D 🔸	сомз -
111458.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
111500.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		1.00	and the second second
111502.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		E T	Close
111504.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
11506.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		5.4	-
111508.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			Save
11510.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
11512.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
11514.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
11516.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
11518.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		G	Clear Log
11520.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
11522.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			and the second s
11524.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		H	GetSum
11526.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
111528.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
111530.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		I 🐳 🛶	24271
111532.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			1
111534.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
111536.000,A,2232.6549,N,11404.9607,E,0,,241208,E0			
111538.000,A,2232.6549,N,11404.9607,E,0,,241208,E0		J 🗲	Start
111540.000,A,2232.6545,N,11404.9507,E,0,,241208,E0			
111542.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	1		
111544-000,4,2232.0043,N,11404.0007,E,0,,241208,E0	B	Clear _1	
the second se			i Dispidy

- A Window for displaying data
- B To clear the data displayed on A
- ${\bf C}$  To select a path and create a file for saving logged data
- D To select COM for USB to serial converter
- E To open or close the COM of D
- F To only save the data displayed on A
- G To format the flash memory inside the tracker (advised caution in pressing this button)
- ${\bf H}$  To read the amount of the waypoints logged and display it on I
- I The current amount of waypoints stored in the tracker. If failed to read data, it will show 'Error!' on I
- J To start or stop getting data from the tracker
- K To display data on A when ticked

#### 4. Troubleshooting

4.1 Prolific USB-to-Serial Comm Port(COM3) is not displayed after connect the tracker to the computer with USB cable and converter.

Resolution:

- Make sure the USB port of computer works
- Make sure the USB to serial converter is connected between USB cable and computer
- COM3 is used by other device. Please check if COM4/COM5...available
- 4.2 'Error!' is shown when GetSum or Start is pressed.

GPS Log For Serial COM ¥1.02	×
Start 2008-12-26/21:13:00	* COM3 -
111458.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111500.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111502.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Close
111504.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111506.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111508.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Save
111510.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111512.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111514.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	
111516.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Olever Level
111518.000,A,2232.6543,N,11404.3607,E,0,,241208,E0	Clear Log
111520.000,4,2232.5545,N,11404.9507,E,0,,241208,E0	
111022.000,4,2232.0343,N,11404.3007,E,0,,241200,E0 111624.000,4,22232.6549,N,11404.9607,E,0,241209,E0	0-10-11
111524.000,4,2232.0343,14,11404.3007,E,0,,241200,E0 111526.000 A 2222.6549 N 11404.9607 E 0. 241209 E 0	Getaum
111520.000/4,2232.0343,4,11404.0007,0,0,241200,00 111520.000 A 2222.0543,4,11404.0007,0,0,241200,00	
111530.000 A 2232.6549 N 11404 9607 E 0. 241200,E0	
111532 000 A 2232 6549 N 11404 9607 F 0 241208 F0	Erron
111534 000 & 2232 6549 N 11404 9607 E 0 241208 E0	· · · · · · · · · · · · · · · · · · ·
111536 000 & 2232 6549 N 11404 9607 E 0 241208 E0	
111538 000 A 2232 6549 N 11404 9607 E 0. 241208 E0	Start
111540 000 A 2232 6549 N 11404 9607 E 0, 241208 E0	Jan
111542.000 A 2232 6549 N 11404 9607 E 0. 241208 E0	
111544.000 A 2232 6549 N 11404 9607 E 0. 241208 E0	
111546.000,A,2232.6549,N,11404.9607,E,0,,241208,E0	Clear V Display
G:\GPSLog Step By Step\VT310-20081224.TXT	SaveToFile

Resolution:

- Check the tracker if in working mode
- USB cable and converter are connected properly
- Correct COM is selected and opened.
- 4.3 Amount of waypoints is displayed as '0'

Resolution:

- Check and make sure you have set interval of logging for the tracker.

Set by SMS

For example, send SMS command W000000,031,60 to tracker to interval as 60 seconds. For more information regarding SMS command please refer to Command List in *User Manual*. <u>Set by GPRS</u>

Please refer to < GPRS Communication Protocol>

Set by PC software

Please refer to < GPS Tracker Parameter Editor>

- Check and confirm the tracker previously worked and had GPS fix.