### Installation of CAN **Adapter Board**

IMPORTANT	READ AND UND
	INSTALLING. IF
	OUFOTIONO OAI

ERSTAND BEFORE THERE ARE ANY **QUESTIONS CALL 1-800-228-7667** 

#### STEP I

Disconnect Scan Tool and cables from vehicle.

#### STEP 2

Remove 1 phillips screw and 6 AAA batteries.



#### STEP 3

Remove 6 phillips screws from back cover using a #1 screwdriver.



## *9640UB UPGRADE*





**ACAUTION** 

Before installing CAN adapter board straighten any bent connector pins.

#### **STEP 6**

Remove CAN adapter board from anti-static bag making sure to handle adapter board by the edges.



Replace back cover, batteries and battery cover in reverse order they were removed. Install software as shown on other side of page.



	Make sure not to bend pins.
	Make sure no jumpers or components on circuit board are touching adapter board or are loose that could cause a short.
IMPORTANT	If required bend test point and transistor so that they do not touch adapter board due to the chances of a short. Make sure not to break leads on components.

#### STEP 7

Place CAN adapter board on Scan Tool circuit board pins. DO NOT push adapter board down. Check that all pins are aligned with connectors on adapter board. Then gently and evenly push CAN adapter board at the pressure points indicated onto Scan Tool circuit board until completely down.

#### STEP 8

**ACAUTION** Do not overtighten phillips screws.

#### Installation of 9640UB Software

Install the CAN Adapter Board before IMPORTANT installing software

> After 9640UB CAN Adapter Board installation, 9640UB software must be installed for tool to work correctly.

#### STEP I

Remove software serial number and place on CD in space provided.

#### STEP 2

Register Software by calling 1-800-228-7667 and receive an authorization number.

Scan Tool Serial Number: \_\_\_\_\_

Software Serial Number:

Authorization Number:

A computer is not required for an IMPORTANT authorization number but a computer, scan tool serial number and software serial number are required to update Scan Tool software.

#### STEP 3

Connect serial cable from serial port on computer to Scan Tool.

#### STEP 4

Press ON/OFF button on Scan Tool then press ENTER when told.



#### STEP 5

Place scan tool in Program Mode using the  $\uparrow$  and  $\downarrow$  arrows and pressing ENTER.





STEP 9

# IMPO

#### STEP 6

Close all programs on computer and place CD in drive.

© 2003 Actron Manufacturing Company All rights reserved.

#### STEP 7 Click Start then Run on computer.



#### STEP 8

Type "X:\setup.exe" in open box on computer and press OK.

X is the CD-ROM drive letter IMPORTANT on your computer.



Follow screen prompts on computer to complete software download.

ORTANT	If downloading process
	stops, repeat STEP 5
	through STEP 9.