

ET0100 THE ILLUMINATOR

Wind up:


1. Lift handle into the open position
2. Wind handle in clockwise direction for 30-60 seconds to charge
3. Return handle to closed position
4. Press button repeatedly to change light intensity

Notes:

- Avoid pointing light directly in eyes
- Do not submerge light in liquid
- Wind steadily in a clockwise direction

Suggestion:

For best results, wind up to 10 minutes before first use.



Mark Feldstein & Associates
www.markfeldstein.com