


TI

31437



Assembly instruction for 31437

- 1 Connect the supply & fixture wires at the junction box.
- 2 Attach the cross bar (A) to the junction box using the junction box screw.
- 3 Attach the fixture (B) by attaching the canopy to the cross bar (A) using the ball nut (C).
- 4 Attach the glass shades (D) to the fixture (B) and fix them using the check rings (E) and the socket rings (F).
- 5 Install the correct bulbs (not included).