


ASSEMBLY INSTRUCTIONS FOR 32513&32517



- Before beginning the assembly, carefully unpack and identify all parts referring to the illustration.
- Turn power to the installation point OFF.
- Unravel the supply power and ground wires and pass the holes of center column and fixture loop.
- Thread center column into the coupling at middle of fixture, then fixture loop into the protruding nipple at top of center column.
- 5. Thread the bottom column into the coupling at bottom of fixture body as shown in the diagram.
- Place candle sleeve over each socket.
- Install proper bulbs (not provided) to each socket referring to the markings and labels on fixture for maximum wattage.
- Place shade over each bulb.
- Attach crystal and longer crystal to the holes of center column and fixture body respectively as shown in the diagram.
- Restore power to the installation point ON. Retain this sheet for future reference.