


### Exploded View FOR TF-10Q



# VM301W Spare Parts List

| No. | Item Code       | Material Name              | Quantity |
|-----|-----------------|----------------------------|----------|
| 1   | 2.00.2TQ021-018 | Foamed Cabinet             | 1        |
| 2   | 1.06.TQ6212-027 | Hinge Hole Cover           | 1        |
| 3   | 1.11.01001TQ-01 | Upper hinge                | 1        |
| 4   | 1.06.TQ3210-001 | Upper Hinge Cover          | 1        |
| 5   | 1.13.G50130-104 | Flange Screw               | 10       |
| 6   | 2.23.22TQ00-018 | Evaporator                 | 1        |
| 7   | 1.03.11TQ39-018 | Drawer A                   | 3        |
| 8   | 1.03.31TQ39-018 | Drawer B                   | 1        |
| 9   | 1.39.2TQ102-010 | Door Gasket                | 1        |
| 10  | 1.06.TQ4310-001 | Door hinge plug            | 1        |
| 11  | 2.01.F1TQ02-018 | Foamed Door                | 1        |
| 12  | 1.13.Y40160-104 | Y type Screw               | 2        |
| 13  | 1.06.TQ2780-041 | Clip of Power Supply Cord  | 1        |
| 14  | 1.28.AA2006-001 | Power Supply Cord          | 1        |
| 15  | 1.46.0500TQ-002 | Process Tube               | 1        |
| 16  | 1.10.11130A-7XX | Compressor                 | 1        |
| 17  | 1.36.ATQ201-018 | Temp.control Cord          | 1        |
| 18  | 1.06.TQ0311-018 | Temp.control knob          | 1        |
| 19  | 1.12.B39160-AB7 | Self Tapping Screw         | 2        |
| 20  | 1.06.TQ4673-018 | Thermostat enclosure       | 1        |
| 21  | 1.06.TQ7370-018 | Thermostat enclosure Cover | 1        |
| 22  | 1.32.2624X0-1TQ | Thermostat                 | 1        |
| 23  | 1.11.04010TQ-01 | Compressor Base            | 1        |
| 24  | 1.13.G60280-104 | Flange Screw               | 4        |
| 25  | 1.46.0400TQ-001 | Drier Filter               | 1        |
| 26  | 1.11.03001TQ-01 | Lower hinge                | 1        |
| 27  | 1.06.TQ2113-027 | Adjustable leg             | 2        |
| 28  | 1.06.TQ1770-018 | Right Evaporator Fix       | 4        |
| 29  | 1.06.TQ1670-018 | Left Evaporator Fix        | 4        |