





# Quick Start Guide


## ConnectPort™ Display



VGA Cable




Ethernet Cable




DB9 Cable




PN:(1P) 90000754 A




4 Connect Power supply






1 Connect Ethernet




2 Connect serial device



3 Connect display device



Next >



Finish