BVO404A 420 TVL Color CCD IR Dome Camera with 24 IR LEDs

Features

- 1/3" Sony Color CCD
- Standard Resolution of 420 TV Lines
- · Minimum illumination of 0.05 Lux/F2.0, 0 Lux (IR On) 24 IR LEDs
- IR LED Effective Range Reaches Up to 15 25 Meters Power Supply: DC 12V
- · High Reliability Under Long Time Operation



Specifications

MODEL	BVO404A	
Video Standard	NTSC	PAL
Image Sensor	1/3" Sony CCD	
Internal	NTSC : 512 (H) × 492 (V)	PAL: 582(H)×512(V)
Horizontal Resolution	420 TVL	
Min.illumination (approx.)	0.05 Lux/F2.0, 0 Lux (IR On)	
R LED	24 Units	
R LED Effective Range	Up to 15 - 25 Meters	
Synchronizing System	Internal	
Video Out Level	1.0 V (p-p) / 75ohms,Composite	
Video S/N Ratio	More than 48dB (AGC Off)	
Auto Gain Control (AGC)	Auto	
Back Light Compensation (BLC)	Auto	
White Balance	Auto	
Lens	3.6 mm / 6 mm	
Power Requirement	DC 12V	
Operating Temperature	-20°C - +60°C	
Shall Material	Plastic	
Shell Color	White	Black
Dimension (mm)	94 (Ø) × 71 (H)	
Weight(g)	180	

* The specifications are subject to change without notice. ** Dimensional Tolerance: ± 5mm

Package Contents



Product Certificate × 1

Accessory Pack x 1

Installation

- Step 1. Open the packet and select the location where you would like to install the dome camera. Take the dome camera.
- Step 2. Slightly drill the supplied three screws into the three round holes on the mounting bracket and rotate the bracket clockwise until the screws are wedged into the narrower chase (as shown in Figure 1). Tighten the fixing screws to secure the mounting bracket to the ceiling.Step 3. Drill a hole in the middle circle and let the power and video line go through (as shown in Figure 2).
- Step 4. Mount the dome body onto the mounting bracket and rotate it until it clicks to secure (as shown in Figure 3). Adjust the camera to the correct position and test the dome camera to make sure it is working properly.



The tolerance of this unit is DC 12V ± 10 %



Figure 1

Over the maximum DC 12V power input will damage the video output connector (VIDEO OUT)

Please use the connector of the camera to a DC 12V regulated power supply.



Figure 2



CAUTION **RISK OF ELECTRIC SHOCK** Caution: To reduce the risk of electric shock, do not expose this apparatus to rain or moisture. Only operate this apparatus from the type of power source indicated on the label. The company shall not be liable for any damages arising out of any improper use, even if we have been advised of the possibility of such damages. The lightning flash with arrowhead symbol, within an equilateral triangle, is intended to alert the user to the presence of uninsulated 'dangerous voltage' within the product's enclosure that may be of sufficient magnitude to constitute a risk of electric shock to persons. The crossed-out wheeled bin mark symbolizes that within the European Union the product must be collected separately at the product end-of-life. This applies to your product and any peripherals marked with this symbol Do not dispose of these products as unsorted municipal waste. /4/ X

RoHS

Note

This exclamation point within an equilateral triangle is intended to alert the user to the presence of important operating and maintenance (servicing) instructions in the literature accompanying the appliance.

CE Mark CE

ROHS Announcement All lead-free products offered by the company comply with the requirements of the European law on the Restriction of Hazardous Substances (RoHS) directive, which means our manufacture processes and products are strictly "lead-free" and without the hazardous substances cited in the directive.

This apparatus is manufactured to comply with the radio interference. The company does not warrant that this manual will be uninterrupted or error-free. We reserve the right to revise or remove any content in this manual at any time.

