## **CMS-50D Plus Instructions by Cooper Medical Supplies**

(These instructions are to supplement the manufacturer's user manual not to replace it!)



Note: There are several softare versions that are compatible with the CMS-50D Plus. It depends on which version of Windows you are using and which version of firmware your oximeter has (the number that first shows on your oximeter screen when you first power it on). The software is always being changed and improved. If you purchase the oximeter from Cooper Medical Supplies, I will send you an email that may have instructions that are newer than this manual.

CMS-50D Plus

Windows Vista, XP, or earlier use Version 1.0 of SPO2 Review Windows 7 use Version 1.2 of SPO2 Review

Once you have installed the software onto your computer, you will have 2 icons on your desktop. One is a red heart that says SPO2, and the other is a green heart that says SPO2 Review. For continuous readings on your computer screen select SPO2. For downloading readings and sleep studies select SPO2 Review.





(Screenshot of SPO2 with 1 Oximeter)



(Screenshot of SPO2 with 4 oximeters on screen)

CMS-50D Plus RECORDING INSTRUCTIONS

STEP 1: PRESS THE POWER BUTTON TO TURN THE OXIMETER ON.

- STEP 2: PRESS THE POWER BUTTON AGAIN TO GO INTO THE SETTINGS MENU.
- STEP 3: PRESS AND HOLD THE POWER BUTTON UNTIL RECORD SHOWS ON.
- STEP 4: PRESS THE POWER BUTTON AGAIN AND THE ARROW WILL BE NEXT TO EXIT
- STEP 5: PRESS AND HOLD THE POWER BUTTON AND THE OXIMETER WILL SHOW THE OXYGEN LEVEL AND HEART RATE WITH A FLASHING DOT IN THE TOP RIGHT HAND CORNER
- STEP 6: AFTER A FEW SECONDS THE OXYGEN LEVEL AND HEART RATE WILL GO AWAY AND THE FLASHING DOT WILL BE THE ONLY THING ON THE DISPLAY. THIS IS SO THE BRIGHT LIGHTS DO NOT DISTURB YOU WHILE TRYING TO SLEEP. IF YOU HIT THE POWER BUTTON NOW, THE DISPLAY WILL SHOW RECORDING. IF YOU PRESS AND HOLD THE POWER BUTTON, THE DISPLAY WILL SHOW YOUR OXYGEN LEVEL AND HEART RATE FOR A FEW MORE SECONDS.

PLEASE NOTE: ONCE STARTING A NEW RECORDING ALL PREVIOUS DATA WILL BE LOST

ONCE YOU FINISH RECORDING:

STEP 1: TAKE THE OXIMETER OFF. OPEN THE SPO2 REVIEW SOFTWARE. STEP2: CONNECT THE OXIMETER TO THE COMPUTER VIA USB CABLE. STEP3: HIT THE MAGNIFYING GLASS ICON AND PRESS NEW SESSION AND ENTER YOUR INFORMATION. THE SCREEN SHOWS DEVICE CONNECTED: WAITING FOR DATA.

STEP 4: PRESS THE POWER BUTTON TO GO INTO THE SETTINGS MENU. THE ARROW WILL BE NEXT TO RECORD ON.

- STEP 5: PRESS THE POWER BUTTON AND HOLD UNTIL IT SHOWS RECORD OFF. YOUR DATA WILL BE UPLOADED INTO THE SPO2 REVIEW SOFTWARE. YOU CAN NOW GO INTO THE SOFTWARE AND HIT THE TOOLS BUTTON IF YOU WANT TO ADJUST THE PARAMETERS OF YOUR READING.
- STEP 7: PRESS THE PRINT ICON AND YOU CAN CHOOSE THE TYPE OF REPORT THAT YOU WANT.



(Screenshot of SPO2 Review Screen when first opened).

🤟 SP02 Review V0.982 rc1									
\$02(%) Puter (bpm)									
100 -									255
		Carrier							
	New	visession							- 240
									225
05 -			New Session	© R	eview				~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
		New Session							- 210
		Name		Height /n					
		- Control		riagite pit					- 195
		Age		Weight /b					
90 -									- 180
		Sex		<ul> <li>Connection</li> </ul>	COM4  CMS	S50E 👻			
85 -		Comments							
						*			- 150
						-			- 135
			File Name	_201007111102					- 120
80 -									- 105
									- 90
		Fi	nd File						-
75									- /5
/3									- 60
			ок		Cancel				00
									- 45
									1
70 -	70								
1	1 2	3	4	5	6	7	8	9	10
	Not Active.	1	10 60 M		2				
					SPO2 Review	V0.982 rc1			<u>     -    -</u>

(Screenshot of SPO2 Review Software New Session Entry. Press the Magnifying glass to get to this screen and upload your data.)





(Screenshot after hitting printer button. You will have the option of which report you want to print from Summary Report, Full Study Report, Oximetry Report, or Strip Chart Report).



(You may preview each report before printing)



You may also notice small squares on your graph. These appear at 22:26 and 22:29 on this graph. These show when you are having a SPO2 or Pulse Rate event. If you would like to set the Parameters for these events simply click on the Tools Icon in the lower left hand corner of the SPO2 Review Software and you will see a box like the one above.

Note: Normally a desaturation event is considered a drop of 4% for at least 10 seconds. Also, when a person's oxygen level drops to 88% or below, they are considered to be hypoxic and not getting enough oxygen into the bloodstream.