

# HDMI-2X2

2 INPUT BY 2 OUTPUT DISTRIBUTION AMPLIFIER







## **Table of Contents**

Overview	3
Installation	4
Technical Specifications	5
Warranty	6
Contact Information.	7

Copyright 2007 Intelix LLC.

DESIGN WITH INTELLIGENCE

### **Overview**

The Intelix HDMI-2X2 is not a standard 2 by 2 distribution amplifier. Instead, it features two independent inputs—an HDMI input, as well as a DVI input with optional digital SPDIF or optical audio. When the DVI/digital audio source is selected, the HDMI-2X2 automatically converts the signal to the HDMI format and routes it to two HDMI outputs. Front panel source selection provides switching between the HDMI and DVI/digital audio inputs. Multiple HDMI-2X2s may be linked for more than two outputs. The HDMI-2X2 supports resolutions up to 1080p and is HDCP compliant.

Design with Intelix and Design with Intelligence.

#### HDMI-2X2 Package Contents

- ➤ HDMI-2X2 distribution amplifier
- > 5 VDC power supply
- > Manual

### Installation

To install the Intelix HDMI-2X2 distribution amplifier, please perform the following steps.

- 1. Power-off the source and destination audio and video devices.
- 2. Connect the input sources to the HDMI-2X2 using high-quality HDMI or DVI and digital audio cables.
- Connect the output destination to the HDMI-2X2 using high-quality HDMI cables.
- 4. Connect the included 5 VDC power supply to the HDMI-2X2.
- 5. Power-on the HDMI-2X2.
- 6. Power-on the source and destination audio and video devices.
- 7. Select the desired input—either HDMI or DVI and digital audio—via the front panel *source select* switch.

#### Warning


- ➤ Do not expose the HDMI-2X2 to fluids or excessive moisture.
- ➤ Do not install the HDMI-2X2 near excessive sources of heat.
- Ensure the HDMI-2X2 is located in a well ventilated area.
- ➤ Do not place objects or equipment directly on or behind the HDMI-2X2.
- Clean the HDMI-2X2 only with a dry cloth. Never use flammable materials for cleaning the HDMI-2X2.
- ➤ Do not open or attempt to service the HDMI-2X2.

4 www.intelix.com

# **Technical Specifications**

60 Hz.
HDMI/HDCP 1.0/1.1
1280 x 1024, 1080p
5.0 volts p-p (TTL)
0.5 – 1.0 volts p-p
140 mHz
One (1) HDMI type A connector
One (1) DVI-D connector
One (1) SPDIF connector
One (1) optical connector
Two (2) HDMI type A connectors
1080i, 1080p, 780i, 780p, 480i, 480p
nt panel input switch; front panel channel LEDs
41 to 95 degrees F
-5 to 35 degrees C
5 to 90% non-condensing
Yes*
One (1) 5 VDC power supply
Front panel channel switch
Black metal
5.0 lbs
HDMI-2X2

<sup>\*</sup>Intelix recommends linking a maximum of five units with the units no more than 30 feet apart.







## Warranty

All Intelix products are guaranteed against malfunction due to defects in materials or workmanship for two years after date of purchase. If a malfunction does occur during the specified period, the defective product will be repaired or replaced at Intelix's option without charge. Furthermore, the "Fresh Start" program ensures that a product which has been repaired or replaced is itself guaranteed for an additional two years.

This warranty does not cover: 1) Malfunction resulting from use of the product other than as specified in the user manual; 2) Installation specific wiring; 3) Malfunction resulting from abuse or misuse of the product; 4) Exterior chassis appearance; 5) Malfunction occurring after repairs have been made by anyone other than Intelix or any of its authorized service representatives; 6) Acts of nature; 7) Optional embedded software upgrades or updates.

All repair and service of Intelix products should only be provided by qualified service personnel. Please contact Intelix for a list of authorized service agents. Other attempts at service or repair will void the warranty. Warranty service is only offered after a return authorization number has been generated by an authorized Intelix factory representative.

Intelix Applications and Engineering support must be contacted prior to any return of goods. To return a unit for service or repair, please call Intelix directly for a return authorization number. Intelix will match shipping charges for units still under warranty. If a unit which is out of warranty needs repair, the dealer must pay for shipping, replacement parts, and a fixed \$100/hr labor fee. Normal Intelix credit terms apply to billable repairs. If a unit is returned and found to work according to factory specifications, a standard \$100 service fee is billed regardless of warranty status. All repairs are made in a reasonably quoted amount of time; a rush shipment fee may apply to repairs needing a quicker than usual turn-around time.

Note: Warranty Terms and Conditions subject to change and do not apply outside the United States.

6 www.intelix.com

## Thank you for your purchase.

We appreciate your business. Please contact us with your questions and comments.

Intelix 2222 Pleasant View Road Suite 1 Middleton, WI 53562

Phone: 608-831-0880

Toll-Free: 866-4-MATMIX

Fax: 608-831-1833

www.intelix.com intelix@intelix.com



Copyright 2007 Intelix LLC.

DESIGN WITH INTELLIGENCE