Introduction

This is a software upgrade for AT&T Motorola BRAVO users who are currently using Android[™] 2.1 (Eclair) software versions. The 37.4.0 upgrade for Motorola BRAVO provides new features from Android 2.2 (Froyo) plus additional improvements.

Who Can Use This Release

All Motorola/AT&T BRAVO users.

Android 2.2 (Froyo) Highlights

Adobe Flash	Your device now supports Adobe® Flash® Player 10.1, allowing access to rich
Player 10.1	Web content and games. Adobe Flash Player 10.1 is installed along with this
	upgrade.
App storage and	Applications can now be stored on the device's microSD card. Additionally, apps
updating	can be set to automatically update by checking "allow automatic updating" under
	each app's page in Android Market [™] .
Wi-Fi Hotspot	Phone can provide an Internet connection for up to 5 Wi-Fi-enabled devices
USB Tethering	You can use your device as a 3G connection for a Windows® or Linux® laptop by
	connecting the phone to the computer with a USB cable.
Digital Keyboard	Added punctuation to the suggestion ribbon so contractions will display correctly.

BRAVO Specific Highlights of the Upgrade

Profiles	Added profiles feature that provides three customizable sets of home screens to
	give you access to the apps, shortcuts, and widgets you want, when you need them.
Applications	Added new applications Files, Latitude, Places, News and Weather, Google Search
Dialer search	Phone numbers and contacts can now be searched from the dialer screen by
	entering the first few letters of the contact's name or first few digits of the contact's
	number.
Task Manager	Added Task manager app to assist with managing apps
LinkedIn	LinkedIn® social network accounts can now be added to integrate with contacts,
	social networking updates, and messaging
Security	Added new security features, including Exchange-based encryption and password
	security
Gallery	Updated the design of the user interface

Instructions for Installing Software

For a successful installation, we recommend installing these updates while the battery in your phone is at least 50% charged. Make sure you have an active SIM card installed in your phone.

If you have received a notification message for this update:

- 1. Select "Download"
- 2. After the software is downloaded, select "Install now"
- 3. After the software is installed, your phone will re-start automatically
- 4. Your phone is now updated with 37.4.0 software

*Note: Menu->Settings->About phone-> System version

If you have not received a notification message for this update:

- 1. Select the Settings icon in the main menu
- 2. Select "About phone"
- 3. Select "System updates"
- 4. Select "Download"
- 5. After the software is downloaded, select "Install"
- 6. After the software is installed, your phone will re-start automatically
- 7. Your phone is now updated with 37.4.0 software

If you have difficulty with this update, visit http://www.att.com/econtactus/.

Certain features, services and applications are network dependent and may not be available in all areas; additional terms, conditions and/or charges may apply. All features, functionality and other product specifications are subject to change without notice or obligation. Contact your service provider for details.

MOTOROLA and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC. Android and Android Market are trademarks of Google, Inc. All other product and service names are the property of their respective owners. © 2011 Motorola Mobility Inc. All rights reserved.