



**MANUAL DE INSTRUCCIONES
BALANZA DIGITAL COLGANTE
ED-3109**



ESTIMADO CLIENTE

¡Felicitaciones por su compra!

Por favor lea cuidadosamente este manual y guárdelo para su futura referencia.

Si necesita soporte adicional no dude en escribir a: info@premiermundo.com

ÍNDICE

INTRODUCCIÓN	1
INSTRUCCIONES DE OPERACIÓN	2
INSTALACIÓN	2
USO Y MANTENIMIENTO	2
ALARMA	2
ESPECIFICACIONES	3
DESCRIPCIÓN	3

	PRECAUCIÓN	
RIESGO DE CHOQUE ELÉCTRICO, NO ABRA		
Precaución: Para reducir el riesgo de choque eléctrico, no retire la cubierta, no hay partes manipulables por el usuario al interior de la unidad. Refiera todo mantenimiento o intervención técnica a personal técnico calificado.		
	Este símbolo indica la existencia de voltaje peligroso al interior de esta unidad que constituye un riesgo de choque eléctrico.	
	Este símbolo indica que hay importantes instrucciones de operación y mantenimiento en la literatura que acompaña a esta unidad.	

LÍNEAS DE SERVICIO AL CLIENTE PREMIER

Venezuela:	0800 – ELECTRIC (353-2874)
Colombia:	01-900-331-PEJC (7352)
Panamá:	300-5185
Sitio Web:	www.premiermundo.com
E-mail:	servicioalcliente@premiermundo.com

NOTA

Nos reservemos el derecho de modificar las especificaciones, características y/u operación de este producto sin previo aviso con el fin de continuar las mejoras y desarrollo del mismo.

INTRODUCCIÓN

Con el fin de que obtenga el mayor desempeño de su balanza, por favor lea este manual de instrucciones cuidadosamente antes de comenzar a utilizarla.

INSTRUCCIONES DE OPERACIÓN

1. Por favor verifique que el voltaje de entrada que concuerde con la unidad antes de conectarla. Luego, conecte el cable al tomacorriente. Cuando la luz indicadora se encienda usted puede colocar los ítems para pesar. Si hay algún número restante en la pantalla para agregar, presione el botón TARA para colocar los contadores en ceros. Presione el botón de unidad/kg para ajustar el precio y los decimales. Luego se mostrará el precio total.
2. Para guardar el precio unitario, haga lo siguiente. Presione el botón de precio unitario y la pantalla mostrará un "0". Presione los botones numéricos para introducir la cifra de precio, al terminar presione cualquier botón del 1 al 3 para guardar la unidad en ese botón. Repita el proceso para otros dos precios. Usted podrá pesar los elementos cuando la pantalla esté en "0".
3. Para usar la función de precio unitario, coloque los elementos a pesar y presione el botón que corresponda. Si es el incorrecto, espere 3 segundos y presione el correcto.
4. Para la función de TARA, presione este botón cuando tenga un número en la pantalla y desee comenzar desde ceros ya con los elementos ubicados. Al presionar el botón, la pantalla mostrará el número "0.000".

INSTALACIÓN

Se debe colocar de forma horizontal y de forma estable. Los tornillos que utilice deben estar bien apretados y firmes para colgar la balanza de forma segura.

USO Y MANTENIMIENTO

- Esta balanza digital es un instrumento de precisión. Una vez que lo encienda, permita que se caliente por 10 minutos con el fin de que ofrezca un peso exacto al usarla.
- No utilice la balanza en un espacio abierto si está lloviendo, donde haya mucho viento (i.e. ventiladores o aire acondicionado), lugares con mucho sol, con altas temperaturas, polvo o mucha humedad.
- Desconecte la unidad cuando no la esté utilizando.
- No utilice agua para limpiar la unidad ni permita que entre a la unidad.
- Para presionar los botones, hágalo suavemente y sin hundir las uñas o con objetos punzantes.
- No coloque un peso más allá de la capacidad de la balanza.
- Guarde la unidad en una bolsa a prueba de aire, si no la va a utilizar por largo tiempo.
- Si la va a guardar por un periodo prolongado asegúrese de conectarla por al menos 3 horas cada 2 meses con el fin de mantener la vida útil.


ALARMA

Si se coloca un peso muy alto en la balanza, la pantalla mostrará la palabra "OF" y se escuchará un sonido de alarma. Por favor retire los elementos de inmediato. La cifra máxima en pantalla es "999.99".

ESPECIFICACIONES

Carga Máxima	30 Kg
Precisión	10 g
Batería	DC 6V 4.5AH, Tiempo de Carga: 25 horas
Voltaje	AC 110V/60Hz
Potencia	10 Vatios
Reinicio Automático a Ceros	
Apagado Automático	

DESCRIPCIÓN





**INSTRUCTION MANUAL
DIGITAL HANGING WEIGHING SCALE
ED-3109**



DEAR CUSTOMER

Congratulations for your purchase!
Please read this manual carefully and keep it for future reference.
If you need additional support please write to: info@premiermundo.com

INDEX

INTRODUCTION 1
 OPERATION INSTRUCTIONS 2
 INSTALLATION 2
 USE AND MAINTENANCE 2
 ALARM 2
 SPECIFICATIONS 3
 DESCRIPTION 3

	CAUTION	
RISK OF ELECTRIC SHOCK, DO NOT OPEN		
<p>Caution: To reduce the risk of electric shock do not open this device, there are not serviceable parts for customers. Please refer any maintenance or repair to qualified personnel.</p>		
	<p>This sign means the existence of dangerous voltage at the inside of the unit, which states a risk of electric shock.</p>	
	<p>This sign means that there are important instructions of operation and handling in the manual that comes with this device.</p>	

PREMIER CUSTOMER SERVICE

Venezuela:	0800 – ELECTRIC (353-2874)
Colombia:	01-900-331-PEJC (7352)
Panama:	300-5185
Website:	www.premiermundo.com
E-mail:	servicioalcliente@premiermundo.com

NOTE

This unit may be submitted to changes in specifications, characteristics and/or operation without prior notice to the user, in order to continue improving and developing its technology.

INTRODUCTION

In order to achieve the best performance of your digital scale please read this instruction manual carefully before using it.

OPERATION INSTRUCTIONS

1. Please verify that the entrance voltage matches with the unit before connecting it. Then, connect the power cable to the electrical outlet. When the indicator light is on you may put the items to weigh. If there are still numbers remaining on the screen, press the TARA key to put the counter in zero. Press the unit/kg key to adjust the price and decimals. Then it will be shown the total price.
2. In order to save the unit price, do the following. Press the unit key and the screen will show "0". Press the numeric keys to introduce the price, and when you finish, press any button from 1 to 3 to save the unit price in that button. Repeat the process for the other two prices. You may weigh the elements when the screen is in zero.
3. To use the function of unit price, put the items to weigh and press the button that corresponds. If your press the incorrect key, wait 3 seconds and try again.
4. To use the TARA function, press the button when you have one number in the screen and you want to put the counter in zero with the elements already placed in the scale. When you press the button, the screen will show "0.000".

INSTALLATION

It must be placed in horizontal way and stable. The bolts you use must be well adjusted and tighten in order to put the scale securely.

USE AND MAINTENANCE

- This digital scale is a precision instrument. Once you turn it on, allow it to warm-up for 10 minutes in order to have an accurate weight when you use it.
- Do not use the scale in an open space if it is raining, there is too much wind (i.e. fans or air conditioner), places with too much sun, high temperatures, dust or high humidity.
- Unplug the power cable when not in use.
- Do not use water to clean the unit and do not allow it to enter inside.
- When you press the keys, do it gently and without the fingernails or sharp objects.
- Prevent overload. Do not put a weight higher than the scale capacity.
- Keep the unit inside an airproof bag, if you are not going to use for a long time.
- If you are keeping it without use for a long period, remember to connect it at least 3 hours every 2 months with the purpose of keeping it in good shape.

ALARM

If you put a very high load in the scale, the screen will display the word "OF" and it will make the alarm sound. Please remove the elements immediately. The maximum number in the screen is "999.99".

SPECIFICATIONS

Maximum Load	30 Kg
Precision	10 g
Battery	DC 6V 4.5AH, Charging Time: 25 hours
Voltage	AC 110V/60Hz
Power	10 Watts
Automatic Zero Resetting	
Automatic Switch Off	

DESCRIPTION

