



11/30/2000



			1999	
	X	PART NO.		
4093-8 (OLD 5000-08)		X		
4094 (OLD 5000-25)			X	
BASIC PARTS	X			
		1	2	3
			4	5


120V., 400W., 60HZ.

[illegible]

***PLEASE SEE NOTES REGARDING MOTOR REPLACEMENT**

**** NOT SHOWN ON DRAWING**




*** (A,G) SEE OLD STYLE BLENDER JARS



EXAMPLE:

28 29 THE COMPONENT PARTS (SMALL INDEX NO.'S)
30 30 ARE INCLUDED WHEN ORDERING
THE ASSEMBLY PART (LARGE INDEX NO.)


CAUTION: NUMBERS SHOWN ON DRAWING
ARE INDEX NUMBERS ONLY. ORDER
PARTS BY CORRECT PART NUMBER.



WHEN ASSEMBLED, LOUVER ON BASE
COVER MUST BE LOCATED 90° FROM
SWITCH.

In order to replace the motor you need to verify your blender base. If you have a blender base type S (M98111 I), You need to used either the old motor bracket that is in your previous motor or use the # 56 (027878-000-000) to install the new motor.

Type "S" - (M98111-000-000)
(M98111-001-000)



Current Base 101793-001-000
101793-002-000

