

# KIA RIO & OPTIMA FITTED WITH MULTIMEDIA NAVIGATION SYSTEM

# **TROUBLESHOOTING GUIDE**

Problem	Solution
Contacts from SIM card are not displayed in car.	The Multimedia Navigation system cannot display contacts stored on SIM card. Please copy contacts from your SIM card to mobile phone
Phonebook is displayed partially or is not available at all.	The Multimedia Navigation system supports contact numbers stored as Mobile, Home, and Office. Numbers stored as General, Main, Other, etc are not displayed. Please check contact numbers in your phone and if required change category of the number to one of: Mobile, Home, Office.
avaliable at all.	The Multimedia Navigation system can display one number per category. If your contacts have multiple numbers in one category (for example Mobile), only one of them will be displayed.
Microphone is not working.	Please check microphone status on the Multimedia Navigation system display. Activate the microphone if required.
Cannot handle multiple calls.	Multiple calls are not supported by the Multimedia Navigation system.
Bluetooth search does not find iPhone.	Please set the Multimedia Navigation system to external authorisation mode and make pairing from the phone.

## APPLE

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
iPhone 3G	4.2.1	✓	1	1	1	1	1	c700	all
iPhone 3GS	4.3.2	1	1	1	1	1	1	•777	att
iPhone 4	4.3.3	1	1	1	1	1	1	9000	att

### BLACKBERRY

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
9800	V6.0 Bundle 2391 (V6.0.0.534, Platform 6.6.0.200)	1	1	1	1	<ul> <li>Image: A second s</li></ul>	1	۵ <i>۵۵</i>	all
Bold 9000	v5.0.0.900	1	1	1	1	✓	1	۵ <i>۵۵</i>	al
Bold 9700	v5.0.0.862	1	1	1	1	1	1	•777	all
Bold 9780	V6.0.0.534	1	1	1	1	✓	1	۵ <i>۵۵</i>	atl
Curve 3G 9300	v5.0.0.977	1	1	$\checkmark$	1	1	1	۵ <i>۵۵</i>	att
Curve 8520	v 4.6.1.314 (Platform 4.2.0.135)	1	1	1	1	1	1	•000	all
Curve 8900	v4.6.1.310 (Platform 4.2.0.0.127)	1	1	$\checkmark$	1	1	1	•000	att
Pearl 9100	v 5.0.0.882	1	1	1	1	1	×	۹ <i>۵۵</i>	att
Storm2 9520	v5.0.0.497 (Platform 4.2.0.220)	1	1	1	1	1	1	• <i>000</i>	att

# GOOGLE

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep stat	hone tus
Nexus S	V 2.3.3 Build:- GRI40	1	1	1	1	~	1	۵ <i>۵۵</i>	att

HTC

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
7 Mozart	Windows Phone 7 OS:7.0.7390.0	1	✓	1	1	×	×	• 772	all
7 MOZdI L	Windows Phone 7 OS:7.0.7392.0	1	1	1	1	1	1	•772	all
7 Trophy	Windows Phone 7 OS:7.0.7392.0	1	1	1	1	1	1	•000	all
Desire	Android ver: 2.2 SW No: 2.10.405.2	1	1	1	1	1	1	•772	all
Desire HD	Android version: 2.2	1	1	1	1	1	1	•000	all
Desire S	V 2.3.3 Build:- 1.28.401.1 CL24343	1	1	1	1	1	1	• 1722	all
Desire Z	Android Version 2.2	1	1	1	1	1	1	• 1724	att
HD 2	Windows Mobile 6.5 Pro OS ver 5.2.21869 (21869.5.0.82) ROM Ver: 1.72.206.3 (86372) WWE 04/15/10	1	✓	1	1	1	1	4 <u>000</u>	ail
HD 7	Windows Phone 7 OS Version: 7.0.7390.0	1	1	1	1	1	1	• 772	all
	Windows Phone 7 OS Version: 7.0.7392.0	1	1	1	1	1	1	• 1724	att
HD Mini	Windows Mobile 6.5 Pro OS ver 5.2.23103 (23103.5.3.3) ROM Ver: 1.36.401.1 (94538 WWE) 5/23/10	1	1	1	×	1	1	4 <u>100</u>	ail
Hero	Firmware: 2.1-update1 Sw no: 3.32.405.1	1	1	1	1	1	1	4772	att
Incredible S	V 2.2.1	1	1	1	1	1	1	• 772	att
Legend	Android Ver: 2.1 Build 1.32.720.3	1	1	1	1	1	1	• 772	all
Tattoo	1.67.405.6	1	✓	×	×	1	1	• 172	atl
Wildfire	Android Version: 2.1-update1 SW No: 1.25.405.1	1	1	1	1	1	1	٩ <i>٦٥</i> ८	all

# LG

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
BL40 New Chocolate	BL40_MSM76XX_V10e-JAN-21-2010-GB	1	1	1	1	✓	1	۵ <i>۵۵</i>	ail
Cookie Fresh GS290	GS290AT_V10d	1	1	1	1	×	×	۵ <i>۵۵</i>	all
GD510 Pop	GD510AT_V10g	1	1	1	×	×	×	• 772	all
GD880 Mini	GD880-MSM76XX-V10b-MAR-31-2010-DE	1	1	1	1	1	1	900	all
InTouch Max GW620	1.5 Kernel: 2.6.27 Version: GW620-V10k	1	1	×	×	✓	1	۵ <i>۵۵</i>	ail
Optimus 2x	V 2.2.2 LG-P990V10b	1	1	1	×	✓	1	•772	all
Optimus 7 E900	Windows Phone 7 OS Version: 7.0.7390.0	1	1	1	1	✓	1	۵ <i>۵۵</i>	att
Optimus Chic E720	Firmware:- 2.2 Build :- FRF91	1	1	1	1	✓	1	۵ <i>۵۵</i>	all
Optimus GT540	Firmware: 1.6 SW Ver: GT540-V10c-MAY-12-2010	1	1	1	1	<ul> <li>Image: A start of the start of</li></ul>	1	۵ <i>۵۵</i>	all
Optimus ME P350	V 2.2.2 LG-P350V10b	1	1	1	×	1	1	• <i>101</i>	all
Optimus One P500	Android Version 2.2 Sw version: V10a-OCT-08-2010	1	1	1	1	✓	1	• 772	all
Town C300	V10a-AUG-26-2010	1	1	×	×	1	1	• <i>101</i>	atl
Town GT350	GT350AT_V10a_May_24	1	1	1	1	1	1	• <i>700</i>	all
Viewty Snap GM360	GM360AT_V10a	1	1	1	1	1	1	9772	all

# MOTOROLA

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
Defy	2.1-update1	1	1	1	1	1	$\checkmark$	•777	atl
Flipout	2.1-update1	1	1	1	1	1	×	• 100	atl
Milestone	V 2.2.1	1	1	1	1	×	×	• 1772	atl
Milestone 2	Firmware: 2.2 Build:- MILS2_U6_2.2.16	1	1	1	1	1	×	•000	all

### NOKIA

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
2330 Classic	v 09.55 12-11-09	1	1	1	1	×	×	٩ <i>٦٥</i> ٢	all
2690	V 10.10	1	1	1	1	1	1	4700	all
2730 Classic	v 10.45 05-07-10	1	1	1	1	1	1	٩ <i>٦٥</i> ٢	att
3720 Classic	V 10.16	✓	1	$\checkmark$	1	✓	1	•100	att
5230	V40.0.003	1	1	1	1	1	1	• 100	all
6303ic	v07.10 25-03-10	1	1	1	1	1	1	• 1772	all
030310	V 10.80 21-01-11	1	1	1	1	1	1	• 772	all
6700	V 13.10 16-01-10	1	1	1	1	1	1	•772	all
6700 Slide	V062.001	1	1	1	1	1	1	9000	all
7230 Slide	V10.81	1	1	1	1	1	1	4772	all
C1-01	V04.40	1	1	1	1	×	×	٩ <i>٦٥</i> ٢	all
C3-00	V04.60	1	1	1	1	X	×	•100	aff
C3-01 Touch and Type	v 05.65	1	1	1	1	1	1	•777	all
65	Ver 061.005 27-0ct-2010	1	1	1	1	1	1	•772	all
C5	0.62.001 11-Dec-2010	1	1	1	1	1	1	• 100	all
C5-03	v 05.65	1	1	1	1	1	1	• 100	att
55.00	V20.0.042 11-11-10	1	1	1	1	1	1	•100	att
C6-00	V 40.0.021 17-05-11	1	1	$\checkmark$	1	1	1	• 100	all
<b>67</b>	012.003 2010-09-19	X	X	×	X	X	×	X	X
C7	014.002 2011-03-01	1	1	1	1	1	1	•100	all
E5	042.007 20-Jul-2010	1	1	$\checkmark$	1	1	1	• 100	all
E52	51,018	1	1	1	1	1	1	• 1771	at
E7	V 013.016	1	1	1	1	1	1	• 100	all
E71	v 500.21.009 02-06-2010	1	1	×	X	1	1	• 100	all
E72	V 052.005	1	1	$\checkmark$	1	1	1	• 100	all
N8	V14.002	1	1	1	1	1	1	• 100	all
N97 Mini	v 12.0.110 11-06-10	1	1	1	1	1	1	• 1772	all
ХЗ	V 08.54 25-10-10	1	1	1	1	1	1	• 1771	ail
X3-02 Touch and Type	V 0.5.60	1	1	1	1	1	1	• 1721	atl
X6	v 30.0.003 28-10-2010	1	1	1	1	1	1	٩ <i>٦٥</i> ८	ad

## SAMSUNG

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
Champ C3300	C3300.08	×	×	×	×	×	×	×	×
	V 2.2.1 Build:- FROYO.XWKA9	1	1	1	1	1	1	100	all
Galaxy ACE S5830	V 2.2.1 Build:- FROYO.XWKB7	1	1	1	×	1	1	100	all
	2.1-update1 Eclair.BVJF4	1	1	1	1	1	1	100	atl
Galaxy Apollo	2.2.FROYO.DDJP4	1	1	1	1	1	1	•000	atl
i9000 Galaxy S	2.1-Update1 Build No.: ECLAIR Phone Ver: I9000XXJF3	1	1	1	X	1	1	1777	atl
Monte S5620	S5620XXJF2	1	1	×	×	1	1	100	atl
Omnia 7 i8700	Windows Phone 7 OS version: 7.0.7004.0	1	1	1	1	1	1	•772	att
S3550	S3550XXJCF CSC:S35500XAJC1	1	1	1	1	×	×	1777	atl
S5260 Star	S5260MSKB1	1	1	1	1	×	×	100	atl
S3650 Genio touch	S3650ACIK1	1	1	1	×	1	1	100	att
S5230 Tocco Lite	S5230XPIK2	1	1	1	X	1	1	•1724	att
S5600 Blade	\$5600BUIF3	1	1	1	×	1	1	•000	atl
C722014	bada 1.1	1	1	1	1	1	1	1777	atl
S7230 Wave 723	bada 1.1 - S723EXXKA1	1	1	1	1	1	1	•1724	att
S8000 Jet	SW Ver.: S8000XXIF5 FTA SW Ver.: S8000.009	1	1	1	×	1	1	•772	all
S8500 Wave	bada 1.0 1005201728LISJEE	1	1	1	1	1	1	• 1724	att
Wave    \$8530	bada 1.2	1	1	1	1	1	$\checkmark$	• 1722	att

## SONY ERICSSON

Model	Telephone software	Incoming call	Outgoing call	Phone- book	Call Lists	Music streaming	Media control	Telep sta	hone tus
ELM	R7BA076prg1231-1917_GENERIC_SU	1	1	1	1	✓	1	۹ <i>۳۵</i> ۵	atl
CLM	1231-1917-R7CA061-100619	1	1	1	X	<i>✓</i>	1	۵ <i>۵۵</i>	al
W995	R1HA035prg1215-7995_GENERIC_HI	1	1	1	1	<i>✓</i>	1	٩ <i>٦٥</i> ٦	atl
Satio U1	1218-9500_R2AK006 18-02-10	1	1	1	1	1	1	۵ <i>۵۵</i>	al
Spiro	R1CA009	1	1	×	×	<ul> <li>Image: A start of the start of</li></ul>	×	٩ <i>٦٥</i> ٦	att
Vivaz U5	1224-4699_R2EA021	1	1	1	1	<i>✓</i>	1	٩ <i>٦٥</i> ٦	atl
Xperia ARC	2.3.2	1	1	$\checkmark$	1	✓	$\checkmark$	۹ <i>۵۵</i>	at
Veerie DLAV	V 2.3.2 Build:- 3.0.A.2.181	1	1	1	1	1	1	٩ <i>٦٥</i> ٦	att
Xperia PLAY	V 2.3.3 Build:- 3.0.1.A.0.145	1	1	$\checkmark$	1	✓	$\checkmark$	•777	atl
Vivaz Pro	1232-0380_R2EA021	1	1	$\checkmark$	1	<i>✓</i>	1	۹ <i>۵۵</i>	at
Xperia X8	Android Ver: 2.1-update1	1	1	1	1	<i>✓</i>	1	٩ <i>٦٥</i> ٦	atl
Xperia X10 mini E10i	Android Ver: 2.1 Update1 Build: 2.0.A.0.405	1	1	×	X	1	1	۵ <i>۵۵</i>	al
Xperia X10 mini Pro	Android Ver 1.6 Build No: 1.2.A.1.174	1	1	1	1	1	1	۵ <i>۵۵</i>	atl
Vaaria V10i	1.6 Build: R2BA020	1	1	×	×	$\checkmark$	1	۵ <i>۵۵</i>	atl
Xperia X10i	2.1-Update1Build No. 2.1.a.0.435	1	1	1	1	×	×	۵ <i>۵۵</i>	al
Zylo	1232-9903 R7DA062 1009262	1	1	1	1	1	1	٩ <i>٦٥</i> ٦	atl