
# INSTALLATION INSTRUCTIONS



**IN-WALL ENCLOSURE** 



**PAC501** 

PAC501 Installation Instructions

## **DISCLAIMER**

Milestone AV Technologies, and its affiliated corporations and subsidiaries (collectively, "Milestone"), intend to make this manual accurate and complete. However, Milestone makes no claim that the information contained herein covers all details, conditions or variations, nor does it provide for every possible contingency in connection with the installation or use of this product. The information contained in this document is subject to change without notice or obligation of any kind. Milestone makes no representation of warranty, expressed or implied, regarding the information contained herein. Milestone assumes no responsibility for accuracy, completeness or sufficiency of the information contained in this document.

Chief® is a trademark of Milestone AV Technologies. All rights reserved.



**WARNING:** A WARNING alerts you to the possibility of serious injury or death if you do not follow the instructions.

lack

**CAUTION:** A CAUTION alerts you to the possibility of damage or destruction of equipment if you do not follow the corresponding instructions.

**WARNING:** Failure to read, thoroughly understand, and follow all instructions can result in serious personal injury, damage to equipment, or voiding of factory warranty! It is the installer's responsibility to make sure all components are properly assembled and installed using the instructions provided.



**CAUTION:** This equipment must be installed and assembled by qualified service personnel in accordance with local building codes.


WARNING: Failure to provide adequate structural strength for this accessory can result in serious personal injury or damage to equipment! It is the installer's responsibility to make sure the structure to which this accessory is attached can support the combined weight of the box and all equipment not to exceed 200 lbs (90.72 kg).

#### NOTES:


- SUITABLE FOR USE IN OTHER ENVIRONMENTAL AIR SPACE IN ACCORDANCE WITH SECTION 300.22,
  (C) OF THE NATIONAL ELECTRICAL CODE.
- The maximum specified ambient temperature of the cabinet system is 40° 120°F (4° 49°).
- Minimum spacings between the accessories and components and the housing for Information Technology Communication Equipment shall be maintained for safe operation of the equipment when installed in accordance with the National Electric Code, ANSI/NFPA 70-1999. Refer to communication equipment manufacturer's specifications for minimum spacings.
- This Cabinet System is for use with ITE or Audio/Video equipment only.

Installation Instructions PAC501

## **DIMENSIONS**




## **LEGEND**




Installation Instructions PAC501

## **TOOLS REQUIRED FOR INSTALLATION**



## **PARTS**



PAC501 Installation Instructions

## INSTALLATION

WARNING: IMPROPER INSTALLATION CAN RESULT IN DEATH OR SERIOUS PERSONAL INJURY! This accessory should be installed by qualified personnel.

## **Site Preparation**

### **Locate and Prepare Mounting Site**

1. Identify a suitable wall location for the in-wall enclosure.

**IMPORTANT!**: The PAC-501 is designed for in-wall installation spanning a minimum of three wood studs, 16" on center. Installation of PAC-501 in 2x4 wall results in nearly direct contact with vertical studs and back wall. Inadequate space will remain for electrical wires/cables, plumbing, ductwork, or insulation. Locate installation accordingly.

WARNING: ELECTRICAL SHOCK HAZARD! CUTTING OR DRILLING INTO ELECTRICAL WIRES OR CABLES CAN CAUSE DEATH OR SERIOUS PERSONAL INJURY! ALWAYS make certain area behind mounting surfaces is free of electrical wires and cables before cutting, drilling, or installing fasteners.

WARNING: EXPLOSION AND FIRE HAZARD! CUTTING OR DRILLING INTO GAS PLUMBING CAN CAUSE DEATH OR SERIOUS PERSONAL INJURY! ALWAYS make certain area behind mounting surfaces is free of gas, water, waste, or any other plumbing before cutting, drilling, or installing fasteners.

- 2. Using a stud sensor, locate and mark studs.
- 3. Center and level housing between marked studs.
- 4. Using housing as a template, draw pencil line completely around housing. (See Figure 1)
- 5. Cut drywall on outside edge of line and remove.




Figure 1

## Frame Housing

The exposed portion of the center wood stud must be removed and the resulting cavity completely framed with wood. The following steps are suggested. The actual procedure is dependent upon the specific installation.

WARNING: STRUCTURAL FAILURE HAZARD! FAILURE TO TAKE ADEQUATE PRECAUTIONS CAN LEAD TO DEATH OR SERIOUS INJURY! Ensure removal of center stud will not cause unacceptable loss of structural strength. Consult a qualified building contractor and applicable building codes.

1. Remove exposed portion of center wood stud flush with upper and lower drywall edges.




Figure 2

Installation Instructions PAC501

- 2. Cut four 8" long support blocks out of 2x4 wood.
- Using three #10 x 2-1/2" countersunk wood screws (not provided), attach each support block to the studs (See Figure 2)

**NOTE:** Ensure screws are far enough from block end to prevent interference with framing screws installed in Step 5.

- If necessary, cut rectangular hole in horizontal framing to accommodate the PAC-501 electrical box.
- Attach horizontal framing to each support block with two #10 x 2-1/2" countersunk wood screws (not provided). (See Figure 2)

#### In-Wall Enclosure Installation

 Install junction box (B) into the PAC-501 (A) using four 08 x 1/2" Phillips pan head tap screws (F). (See Figure 3)




Figure 3

- 2. Connect electrical wiring.
- 3. Route audio/visual cables into housing.
- Center PAC-501 in opening and insert into opening. Align front of box with front face of wall. (See Figure 4)




Figure 4

WARNING: ELECTRICAL SHOCK HAZARD! CUTTING OR DRILLING INTO ELECTRICAL WIRES OR CABLES CAN CAUSE DEATH OR SERIOUS PERSONAL INJURY! ALWAYS make certain area behind mounting surfaces is free of electrical wires and cables before cutting, drilling, or installing fasteners.

5. Drill four 3/16" diameter pilot holes in studs at side mounting holes. (See Figure 5)




Figure 5

 Attach the PAC-501 to side studs using four M7 x 50mm Allen head connector screws (D) and mounting spacers (G) using an M4 Allen head drill bit (E). (See Figure 5)

**NOTE:** The PAC-501 has 1/2" total clearance between the two studs. The spacers allow side to side adjustment.

PAC501 Installation Instructions



Our Mounts. Your Vision.

Chief Manufacturing, a division of Milestone AV Technologies

8807-000073 Rev A ©2008 Milestone AV Technologies www.chiefmfg.com 10/08 **USA/International** A 8401 Eagle Creek Parkway, Savage, MN 55378

**P** 800.582.6480 / 952.894.6280

**F** 877.894.6918 / 952.894.6918

**Europe** A Fellenoord 130 5611 ZB EINDHOVEN, The Netherlands

P +31 (0)40 2668620

**F** +31 (0)40 2668615

Asia Pacific A Room 24F, Block D, Lily YinDu International Building

LuoGang, BuJi Town, Shenzhen, CHINA.

深圳市布吉罗岗村百合银都国际大厦D栋24F

**P** +86-755-8996 9226

F +86-755-8996 9217

