


6/1/06 - Tech Update for 2000R(N) US and Canadian Remotes

- The current 2000R remote shown below has been replaced with a new molding.
- All remote functions remain the same.
- Canadian remotes are distinguished by “Auto” in the top right corner and do not have FCC IDs on the back (IV-)

Current 2000R



New 2000R(N)

Front

Back

(The top remote is Canadian)

(The bottom remote is Canadian)

