Installation and Assembly - Adapter Bracket for VESA® 800 x 400 Screens

Model: PLP-V8X4

IMPORTANT! Read instruction sheet before you start installation and assembly.

Before you start make sure all parts listed are included with your product.


	Parts List			AA Î BB
	Description	Qty.	Part #	AA
AA	adapter bracket	1	201-1433	
ВВ	M6 x 12 mm serrated washer head socket pin screw	4	510-1050	
CC	M5 x 12 mm serrated washer head socket pin screw	4	510-1064	
DD	M8 x 15 mm socket pin screw	4	520-1068	
EE	#10 SAE flat washer	4	540-9400	l GG 🖺 📉
FF	1/4" SAE flat washer	4	540-9440	
GG	4 mm security allen wrench	1	560-9646	
	CC DD EE FF			
Sor	me parts may appear slightly different than illustrated.			

A WARNING

• Do not overtighten. Overtightening may cause permanent damage to the screen. Torque to 26-35 in • lb (30-40 kg • cm).

Begin with four M5 x 12 mm serrated washer head socket pin screws (CC), hand thread through #10 SAE flat washer (EE) and adapter plate (AA) into screen as shown below. Do not over tighten. If screw is too small, select four M6 x 12 mm serrated washer head socket pin screws (BB) and 1/4" SAE flat washers or four M8 x 15 mm socket pin screws (DD). Tighten screws.

NOTE: Screw must make at least three full turns into the mounting hole and fit snug into place. If you have any questions, please call Peerless customer care at **1-800-865-2112**.



NOTE: Spacers may not be used, depending upon the size of screw.

f 1 ISSUED: 11-09-07 SHEET #: 202-9250-2 11-04-08