

User Manual MODEL QS2350C



Q-**\66**

Protect Your Investments. www. Q-See. com

■ Caution:

- * Read this manual carefully before installation
- * To reduce the risk of electric shock, do not remove the cover
- * The color camera must be securely installed to avoid the risk of damaging the camera. Avoid installing camera at the places subject to shock or vibration.
- * Be sure of power supply of 100-240VAC
- * Use the correct power source and make sure that all the connections are secure before turning on the camera
- * Do not overload wall outlets and extension cords as this can result in the risk of fire or electrical shock
- * Do not touch the CCD sensor with your fingers. Use soft cloth moistened with alcohol to wipe off the dust. Do not use strong solvents and detergents.
- * Installation should conform to all local codes.Refer servicing to qualified technical person only.

■ General:

Thanks for purchasing Q-See professional Color CCD Camera The Professional series color camera utilizes superior sensitive CCD. This camera is perfect for extreme weather conditions.

■ Features:

- * Perfect combination of CCTV camera and IR sensor
- * Automatec Gain Control & High S/N ratio
- * Low illumination & Backlight Compensation
- * Built-in the blower & (100-240VAC)universal SMPS
- * Heavy Duty mounting bracket
- * automatic blower function when CDS ON
- * NTSC system
- *Optical Low Pass Fitter: IR/DN
- *3D omni-directional IR sensor energy-saving
- * Day and Night function
- * Electronic Shutter Control
- * Weatherproof with sun shield cover
- * O Lux with 12 IR LEDs range up to 60ft

■ Connection:

- 1, Connect a video terminal of the camera(BNC) and the video input terminal of a monitor or TV with a 75 ohm coaxial cable.
- 2. Connect the power terminal of the camera to a power Supply(100-240Vac).
- 3. Focus the camera as required